Symptom:
*PANEL DIMMNG INOPERATIVE

POSSIBLE CAUSES
INSTRUMENT CLUSTER PANEL DIMMING DTC
PARK LAMP FEED CIRCUIT OPEN
ILLUMINATION BULB
INSTRUMENT CLUSTER

TEST	ACTION	APPLICABILITY
1	**NOTE: Ensure that the Park/Headlamps operate properly before continuing with this test.** **NOTE: Ensure that other Instrument Cluster functions operate properly before continuing with this test.** Turn the ignition on. With the DRBIII®, select Body, Electro/Mech Cluster, read DTCs. Does the DRBIII® display PANEL DIMMER OPEN? Yes → Refer to PANEL DIMMER OPEN DTC in the Service Information. Perform BODY VERIFICATION TEST - VER 1. No → Go To 2	All
2	Turn the ignition off. Disconnect the Instrument Cluster C1 harness connector. Check connectors - Clean/repair as necessary. Turn the Park lamps on. Measure the voltage between the Park Lamp Feed circuit and ground. Is the voltage above 10.5 volts? Yes → Go To 3 No → Repair the Park Lamp Feed circuit for an open. Perform BODY VERIFICATION TEST - VER 1.	All
3	Turn the ignition off. Disconnect the Instrument Cluster C1 harness connector. Check connectors - Clean/repair as necessary. Remove and inspect the inoperative illumination bulb(s). Is the illumination bulb filament open? Yes → Replace the Instrument Cluster Illumination Bulb(s) in accordance with the Service Information. Perform BODY VERIFICATION TEST - VER 1. No → Replace the Instrument Cluster in accordance with the Service Information. Perform BODY VERIFICATION TEST - VER 1.	All