LEFT FRONT SENSOR SIGNAL FAILURE — Continued

POSSIBLE CAUSES
SPEED SENSOR OR CONNECTOR DAMAGED
TONE WHEEL DAMAGED
WHEEL SPEED SENSOR AIR GAP OUT OF SPECIFICATION
WHEEL BEARING EXCESS RUNOUT
WHEEL SPEED SENSOR INOPERATIVE
CAB - CAN'T READ WHEEL SPEED SENSOR SIGNAL
INTERMITTENT SIGNAL DTC

TEST	ACTION	APPLICABILITY
1	Turn the ignition on. Using the DRBIII®, monitor all Wheel Speed Sensors while an assistant drives the vehicle. Slowly accelerate as straight as possible from a stop to 24 km/h (15 mph). Note the DRBIII® Wheel Speed Sensor readings. Is one wheel speed signal zero or differing from others by more than 5 km/h (3 mph)? Yes → Go To 2 No → Go To 7	All
2	Turn the ignition off. Inspect the Wheel Speed Sensor and Connector at the affected wheel. Is the Sensor or Connector Damaged? Yes → Repair as necessary. The CAB must sense all four wheels at 25 km/h (15 mph) before it will extinguish the ABS Indicator. Perform ABS VERIFICATION TEST - VER 1. No → Go To 3	All
3	Turn the ignition off. At the affected wheel, inspect the Tone Wheel for damaged or missing teeth, cracks, or looseness. **Note: The Tone Wheel Teeth should be perfectly square, not bent or nicked.** Is the Tone Wheel OK? Yes → Go To 4 No → Replace the Tone Wheel. The CAB must sense all four wheels at 25 km/h (15 mph) before it will extinguish the ABS Indicator. Perform ABS VERIFICATION TEST - VER 1.	All
4	Turn the ignition off. Using a Feeler Gauge, measure the Wheel Speed Sensor Air Gap. **NOTE: The Air Gap should be checked in at least four places on the Tone Wheel.** Is the Air Gap between 0.42 mm - 1.71 mm (0.017″ - 0.068″) ? Yes → Go To 5 No → Repair as necessary. The CAB must sense all four wheels at 25 km/h (15 mph) before it will extinguish the ABS Indicator. Perform ABS VERIFICATION TEST - VER 1.	All