

Finding identification & remedial schedule

Project	Riverside Court - Cat B Fit-Out, Phase 2
Client	Halloway Cross Estates Ltd
Address	Riverside Court, 42 Kelham Street, Sheffield S3 8LP
Reference	SNG-2026-10-006
Report date	1 October 2026
Status	Draft - not yet published
Items included	18

Schedule of items - 18


No.	Item	What it is	Trade	Severity	Photograph
COSMETIC					
1	Item 6	Scuffed and poorly levelled paint finish to door casing	Decorator	Cosmetic	Ph 10 / pin 2
2	Item 8	Ceiling tiles sagging below grid line	Carpenter / joiner	Cosmetic	Ph 8
3	Item 15	Sealant residue on basin and tile glazed faces	Tiler	Cosmetic	Ph 2 / pin 3
4	Item 17	Absent sealant line to top of skirting	Decorator	Cosmetic	Ph 1 / pin 2
5	Item 18	Floor to skirting junction to be reviewed at handover	Principal contractor	Cosmetic	Ph 1 / pin 3
WORKMANSHIP					
6	Item 1	Door strike plate not rebated flush, jamb timber broken out	Carpenter / joiner	Workmanship	Ph 7
7	Item 2	Broken plaster and exposed angle bead to external wall corner	Plasterer	Workmanship	Ph 5
8	Item 3	Door lever handle and backplate painted over, seizing the lever	Decorator	Workmanship	Ph 3 / pin 1
9	Item 4	Backplate screw slots filled with paint, handle not removable	Decorator	Workmanship	Ph 3 / pin 2
10	Item 5	Door casing damaged and broken away at strike-plate height	Carpenter / joiner	Workmanship	Ph 10 / pin 1
11	Item 10	Extensive surface scratching to worktop	Principal contractor	Workmanship	Ph 4
12	Item 12	Perimeter movement joint grouted hard against skirting, not sealed	Tiler	Workmanship	Ph 6 / pin 2
13	Item 13	Silicone sealant smeared across basin upstand and tiles	Tiler	Workmanship	Ph 2 / pin 1
14	Item 16	Open butt joint and unfinished end grain to skirting	Carpenter / joiner	Workmanship	Ph 1 / pin 1
15	Item 20	Broken threshold junction between slab, blockwork and frame with loose debris	Bricklayer	Workmanship	Ph 9 / pin 2
PERFORMANCE					
16	Item 11	Floor tile fractured diagonally, approx. 400 mm, open crack	Tiler	Performance	Ph 6 / pin 1
17	Item 14	Unsealed gap at basin upstand and tile junction	Tiler	Performance	Ph 2 / pin 2
18	Item 19	Continuous crack to floor slab with local spalling at threshold junction	Structural	Performance	Ph 9 / pin 1

RESULTS

Cosmetic - 5 items

PHOTOGRAPHS CARRYING SEVERAL ITEMS

Each of these takes a page of its own: a numbered pin on the photograph for every item found on it, and those items listed underneath in pin order. An item's entry in the schedule points back at its pin.



Photograph 10 - 2 items on this photograph, 2 pins on this photograph

Findings on this photograph

Pin 1 - Item 5 - Door casing damaged and broken away at strike-plate height

Pin 2 - Item 6 - Scuffed and poorly levelled paint finish to door casing

Item 6

Scuffed and poorly levelled paint finish to door casing

Status: Finding - rectification required Severity: Cosmetic Trade: Decorator Photograph 10, pin 2

The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-006 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 2 of 2 - photograph 10

A crop of the area this item refers to.

Item 8

Ceiling tiles sagging below grid line

Status: Finding - rectification required **Severity:** Cosmetic **Trade:** Carpenter / joiner

The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-008 recorded on site during the inspection visit.


Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites





Photograph 2 - 3 items on this photograph, 3 pins on this photograph

Findings on this photograph

Pin 1 - Item 13 - Silicone sealant smeared across basin upstand and tiles

Pin 2 - Item 14 - Unsealed gap at basin upstand and tile junction

Pin 3 - Item 15 - Sealant residue on basin and tile glazed faces

Item 15

Sealant residue on basin and tile glazed faces

Status: Finding - rectification required Severity: Cosmetic Trade: Tiler Photograph 2, pin 3

The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-015 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.


Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 3 of 3 - photograph 2

A crop of the area this item refers to.



Photograph 1 - 3 items on this photograph, 3 pins on this photograph

Findings on this photograph

Pin 1 - Item 16 - Open butt joint and unfinished end grain to skirting

Pin 2 - Item 17 - Absent sealant line to top of skirting

Pin 3 - Item 18 - Floor to skirting junction to be reviewed at handover

Item 17

Absent sealant line to top of skirting

Status: Finding - rectification required **Severity:** Cosmetic **Trade:** Decorator **Photograph 1, pin 2**

The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-017 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 2 of 3 - photograph 1

A crop of the area this item refers to.

Item 18

Floor to skirting junction to be reviewed at handover

Status: Finding - rectification required **Severity:** Cosmetic **Trade:** Principal contractor **Photograph 1, pin 3**


The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-018 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 3 of 3 - photograph 1

A crop of the area this item refers to.

Item 1

Door strike plate not rebated flush, jamb timber broken out

Status: Finding - rectification required Severity: Workmanship Trade: Carpenter / joiner

The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-001 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Item 2

Broken plaster and exposed angle bead to external wall corner

Status: Finding - rectification required **Severity:** Workmanship **Trade:** Plasterer

The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-002 recorded on site during the inspection visit.


Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites





Photograph 3 - 2 items on this photograph, 2 pins on this photograph

Findings on this photograph

Pin 1 - Item 3 - Door lever handle and backplate painted over, seizing the lever

Pin 2 - Item 4 - Backplate screw slots filled with paint, handle not removable

Item 3

Door lever handle and backplate painted over, seizing the lever

Status: Finding - rectification required **Severity:** Workmanship **Trade:** Decorator **Photograph 3, pin 1**

The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-003 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 1 of 2 - photograph 3

A crop of the area this item refers to.

Item 4

Backplate screw slots filled with paint, handle not removable

Status: Finding - rectification required **Severity:** Workmanship **Trade:** Decorator **Photograph 3, pin 2**


The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-004 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 2 of 2 - photograph 3

A crop of the area this item refers to.

Item 5

Door casing damaged and broken away at strike-plate height

Status: Finding - rectification required Severity: Workmanship Trade: Carpenter / joiner Photograph 10, pin 1

The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-005 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 1 of 2 - photograph 10

A crop of the area this item refers to.

Item 10

Extensive surface scratching to worktop

Status: Finding - rectification required Severity: Workmanship Trade: Principal contractor


The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-010 recorded on site during the inspection visit.


Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites





Photograph 6 - 2 items on this photograph, 2 pins on this photograph

Findings on this photograph

Pin 1 - Item 11 - Floor tile fractured diagonally, approx. 400 mm, open crack

Pin 2 - Item 12 - Perimeter movement joint grouted hard against skirting, not sealed

Item 12

Perimeter movement joint grouted hard against skirting, not sealed

Status: Finding - rectification required **Severity:** Workmanship **Trade:** Tiler **Photograph 6, pin 2**

The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-012 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 2 of 2 - photograph 6

A crop of the area this item refers to.

Item 13

Silicone sealant smeared across basin upstand and tiles

Status: Finding - rectification required **Severity:** Workmanship **Trade:** Tiler **Photograph 2, pin 1**


The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-013 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 1 of 3 - photograph 2

A crop of the area this item refers to.

Item 16

Open butt joint and unfinished end grain to skirting

Status: Finding - rectification required Severity: Workmanship Trade: Carpenter / joiner Photograph 1, pin 1

The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-016 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.


Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 1 of 3 - photograph 1

A crop of the area this item refers to.



Photograph 9 - 2 items on this photograph, 2 pins on this photograph

Findings on this photograph

Pin 1 - Item 19 - Continuous crack to floor slab with local spalling at threshold junction

Pin 2 - Item 20 - Broken threshold junction between slab, blockwork and frame with loose debris

Item 20

Broken threshold junction between slab, blockwork and frame with loose debris

Status: Finding - rectification required **Severity:** Workmanship **Trade:** Bricklayer **Photograph 9, pin 2**

The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-020 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 2 of 2 - photograph 9

A crop of the area this item refers to.

Performance - 3 items

Item 11

Floor tile fractured diagonally, approx. 400 mm, open crack

Status: Finding - rectification required **Severity:** Performance **Trade:** Tiler **Photograph 6, pin 1**

The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-011 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 1 of 2 - photograph 6

A crop of the area this item refers to.

Item 14

Unsealed gap at basin upstand and tile junction

Status: Finding - rectification required **Severity:** Performance **Trade:** Tiler **Photograph 2, pin 2**


The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-014 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 2 of 3 - photograph 2

A crop of the area this item refers to.

Item 19

Continuous crack to floor slab with local spalling at threshold junction

Status: Finding - rectification required Severity: Performance Trade: Structural Photograph 9, pin 1

The concrete floor slab carries a continuous crack running diagonally across the visible floor area, with a width generally in the order of 2 to 4 mm, opening slightly wider at the junction with the wall and threshold, where the slab edge is visibly broken down and spalled. The crack extends beyond the frame of the photograph and its full length cannot be established from this image. Item F-019 recorded on site during the inspection visit.

Required action

Establish the full extent by opening up. Where the defect is confirmed static, rake out to a sound profile and fill with a semi-rigid repair mortar. Where it is wider than 5 mm or shows displacement, refer to the structural engineer.

Likely cause: Most likely impact damage during construction traffic, or movement where no joint has been provided. A single photograph cannot establish the cause with certainty.

Reference: BS 8000 - workmanship on construction sites



Pin 1 of 2 - photograph 9

A crop of the area this item refers to.