

	Work Instruction	Doc. Revision	00
	AXI V810 STD PIP Board Stop (Fiber Optic Type) Replacement Procedure	Effective Date	30-May 2016

This procedure is applicable to below models:

V810 STD	☒	S1	☒	S2
V810 XXL	☐	S1	☐	S2
V810 S2EX	☐			
V810 Mini	☐			

REVISION HISTORY

Rev	Effective Date	Description	Doc Originator
00	30 May 2016	First Release	Tan Liang Kai

	Work Instruction	Doc. Revision	00
	AXI V810 STD PIP Board Stop (Fiber Optic Type) Replacement Procedure	Effective Date	30-May 2016

Content

PC, Board Stop Removal.....	3
PC, Board Stop Replacement.....	5

ViTrox	Work Instruction	Doc. Revision	00
	AXI V810 STD PIP Board Stop (Fiber Optic Type) Replacement Procedure	Effective Date	30-May 2016

** This procedure is applicable for left & right PC, Board Stop.

PC, Board Stop Removal

1. Verify that there is no panel in the system.
2. Extend PIP Board Stop at Digital IO tab.
3. Turn off X-ray Source.Open Front Access Doors.
4. Use 2.5mm Hex Wrench to remove PIP Flag Screw & PIP Flag as shown in Figure 1.




Figure 1 PIP Flag removal

5. Remove 2 x Set Screws as shown in Figure 2.




Figure 2 Set Screws removal

	Work Instruction	Doc. Revision	00
	AXI V810 STD PIP Board Stop (Fiber Optic Type) Replacement Procedure	Effective Date	30-May 2016

6. Remove 1 x 8-32 thread (Inch Type) PIP Shoulder Screw from PC, Board Stop as shown in Figure 3.




Figure 3 Shoulder Screw removal

7. Gently position PIP Flag, PIP Flag Screw, Set Screws, Spacer, Curved Washer & PIP Shoulder Screw at visible area.




Figure 4

ViTrox	Work Instruction	Doc. Revision	00
	AXI V810 STD PIP Board Stop (Fiber Optic Type) Replacement Procedure	Effective Date	30-May 2016

8. Gently remove PC, Board Stop as shown in Figure 5.




Figure 5 PC, Board Stop removal

PC, Board Stop Replacement

1. Prepare PC, Board Stop, Curved Washer, Spacer by refer below Part ID
 - a) For Right STD PC, Board Stop (P/N: 4XAXY-155)
 - b) For Left STD PC, Board Stop (P/N: 4XAXY-156)
 - c) Curved Washer (P/N: 2720-0021)
 - d) Spacer (P/N: 4XAXY-003)
2. Gently slot new PC, Board Stop into Cylinder Nose. Next, slot PIP Sensor into PC, Board Stop as Figure 6.




Figure 6 PC, Board Stop Assembly

	Work Instruction	Doc. Revision	00
	AXI V810 STD PIP Board Stop (Fiber Optic Type) Replacement Procedure	Effective Date	30-May 2016

3. Arrange below fastening kit by refer below sequence. May refer to Figure 7.

a) PIP Shoulder Screw > Curved Washer > Spacer

Remark: Replace necessary Curved Washer & Spacer if worn out upon part replacement




Figure 7 PIP Shoulder Screw Assembly

4. Assemble all fastening (Shoulder Screw, Curved Washer & Spacer) into PC, Board Stop as shown in Figure 8. Tighten Shoulder Screws



Figure 8 PC, Board Stop Assembly

	Work Instruction	Doc. Revision	00
	AXI V810 STD PIP Board Stop (Fiber Optic Type) Replacement Procedure	Effective Date	30-May 2016

5. Align Sensor Head evenly with PIP Board Stop flat surface. Tighten 2 x Set Screws as shown in Figure 9.
Remark: Caution on Sensor Head protrusion upon routing




Figure 9 Set Screws Fastening

6. Assemble PIP Flag into PIP Board Stop. Tighten PIP Flag Screw as shown in Figure 10.




Figure 10 PIP Flag Assembly

	Work Instruction	Doc. Revision	00
	AXI V810 STD PIP Board Stop (Fiber Optic Type) Replacement Procedure	Effective Date	30-May 2016

7. Close Front Access Doors.
8. Obtain 1 x Dummy Board or Empty Carrier for Panel Handling test.
9. Go to Services > Subsystem Status & Control > Panel Handling > Click “Initialize” as shown in Figure 11.



Figure 11 Panel Handling

10. Enter board parameter & click “Load” as shown in Figure 12.

Remark: Do not load any board & click “Cancel” when outer barrier open.




Figure 12 Panel Handling

	Work Instruction	Doc. Revision	00
	AXI V810 STD PIP Board Stop (Fiber Optic Type) Replacement Procedure	Effective Date	30-May 2016

11. Go to services > Confirmation, Diagnostics & Adjustment > Run “Panel Handling Confirmation” for 5 loops as shown in Figure 13.




Figure 13 Panel Handling Confirmation

12. Load dummy board or carrier accordingly. Panel Handling confirmation task will prompt as “Passed”.
13. Unload board or carrier accordingly.