



09-Jul-26

JOB NO. S67771

CLAIM No. NRP267377484

IAG

LOCKED BAG 5050

PARRAMATTA NSW 2124

MRS P WRIGHT - 381 REDDALL PDE, MOUNT WARRIGAL NSW 2528

Claim Received

Incident Type: DAMAGE

Estimator: Chris Wood

Type of Make Safe: Roof

Contact: 0422 020 120

Specialist Report Type: ROOF



S67771-WRIGHT\FRONT\House

Property Details:

Detached Garage: NO

Sheds: YES

Swimming Pool: YES

Detached Granny Flat/Other building: NO

Client Discussion:

Estimator Chris met insured who advised that in May 2025 NBN installers accessed the roof space and have damaged the ceiling in the garage.

Resultant Damage:

There is sagging in the garage ceiling in multiple areas.

There is a crack in the middle of the ceiling which insured says is due to the NBN installers accessing the roof space.

There is also previous repairs to both the left hand side and right hand side of the ceiling in separate areas

Has the resultant damage to the property has been caused by a listed event? NO

Cause of Damage:

A roof report was arranged due to claim incident details of "NBN installer has damaged roof".

See roof report.

Roofer found no evidence of water ingress. The photos in the roof space show sagging plasterboard ceiling indicating glue failure, which is consistent with the sagging cornice viewed from below, and previous repairs to both sides of the garage.

Maintenance Related Issues:

N/A

Recommendation:

Do not accept - Not covered

Repair Estimate (inc GST): \$7,997.99

Variances to Scope:

Comments:

Do not accept.

The damage is not consistent with a storm event nor does it look to be caused by installers accessing the roof space.

The sagging ceiling and cornice are consistent with glue failure over time, not a one off event.

The ceiling needs to be replaced and an estimate for that is provided.

Roofer carried out make safe to 2 x broken watercourses by siliconing them from inside the roof space.

No makes to ceiling has been carried out at this stage but one can be arranged if required.

This report has been produced to facilitate claim resolution, is unbiased and objective, and is based on the information available at the time of writing.

Is Temporary Accomodation required immediately? NO

Estimate timeframe for immediate temporary accomodation: 0 Days

What temporary repairs are required to make the home liveable: N/A

Is Temporary Accomodation required DURING REPAIRS ONLY? NO

Estimate timeframe for temporary accomodation required during repairs: 0 Days

Works to be completed when insured is in temporary accomodation: N/A

Photos:



S67771-WRIGHT\cornice sag close up



S67771-WRIGHT\Cornice sag front of garage overview



S67771-WRIGHT\Cornice sag



S67771-WRIGHT\Lines in ceiling indicating glue failure



S67771-WRIGHT\Previous ceiling repairs right hand side



S67771-WRIGHT\Previous ceiling repairs right hand side2



S67771-WRIGHT\Previous ceiling repairs right hand side3



S67771-WRIGHT\Previous glue failure repairs



S67771-WRIGHT\Previous glue failure repairs2

For and on behalf of

ENSURE CONSTRUCTIONS AND RESTORATION PTY LTD