

Procedure for TopSky Dataset or TopSky Software Upgrade

Concern: TWR, FDO, AIRLOG, OCA, TMA, TECH

Procedure

- Prior to any TopSky modification which would require a restart of the ATM platform, an assessment should be carried by the duty ATC supervisor whereby a suitable time slot should be chosen for the ATM platform restart;
- Restart of the TopSky ATM System **should not be carried out** within one (1) hour of scheduled change of shifts;
- Prior to the restart of the TopSky ATC platform, a system verification of the functionality of all nodes by Air Traffic Control Officers/supervisors as per an operational checklist as per Step 1, a Flight Plan Save should be carried out and the flight strips printed from the flight strip printer and updated as per Steps 4-6 below.

The following stop action table dictates the procedures to be followed for a Dataset or Software upgrade.

Step	Action
1	Make two copies of section 5 of Supervisor manual (Functionality System Checks) and distribute pages for ATCO checks.
2	Advise ALL concerned staff when the upgrade will commence.
3	AFTM Filter: Use VTMA, VOC1, VOC2 and VXOC to check the traffic for the next two hours.
4	Ensure strip printer is ON at OCA, APP and AIRLOG. Advise ATCOs that paper strips for the next two hours are to be printed.
5	Inform TWR of upgrade and advise that paper strips for the next two hours are to be printed.
6	Ensure that OCA / TMA / AIRLOG / TWR printed strips have been updated from their electronic strips
7	Advise TECH/Thales that they can proceed with TopSky Dataset Distribution
8	Ensure FDO TopSky Queues are empty and advise that they will lose the AMHS link to FDP
9	After TECH advises that the dataset has been distributed repeat step 8 to cross check empty Queues
10	Ask TECH for PEA AMHS and SITA links to be closed.
11	Perform a Flight Plan Save at least 7 minutes prior to hour H, H+15, H+30, H+45 minutes.
12	Obtain flight plan print out from the Flight Data Operator (FDO) who must ensure that all aircraft on the list are in the system after the platform restart
13	Ask FDO to check Queues again
14	Advise TECH/Thales to proceed with the upgrade
15	After upgrade has been completed, perform Flight Plan Restore from OPSUP.
16	Ask TECH to restore the AMHS and SITA links
17	Ensure that correct values are on the OPSUP Information Dialogue Window for: SECT, QNH, AHO, AGDL, PSS
18	Advise all ATCOs that they can upgrade their TopSky Position from DEGD mode to NORM, and also to update their FDR and MMI
19	Complete System Checks.
20	Advise TWR ATCO upgrade is now completed.

From : Ag Senior Engineer(CNS)

To : Divisional Head (CNS)

Ref : CAV/COM/125/2/1

Date : 24 June 2026

Copy watch tech
for record & info.

8/08/2026


Noted.

Safety incident – TopSky ATC System

Please refer to f(24).

Coordination has been made with the ATM section and the updated procedure is attached.

Grateful for your approval.



O KOODORUTH
Ag Senior Engineer(CNS)

Eng(K)/MEMO TopSky Upgrade Procedure

DH ATM/- PLS find attached updated procedure.

Ag SE(K)/- PLS brief Watchtech & MSupt, SMO, MO,
Super-visors etc.

30.06/26

02/07/26

MSupt / Kindly circulate
and keep record.

MS(n) please do needful.

02/07/26

01/07

Reg/- PLS etc.

Procedure for TopSky Dataset or TopSky Software Upgrade

Concern: TWR, FDO, AIRLOG, OCA, TMA, TECH

Procedure

- Prior to any TopSky modification which would require a restart of the ATM platform, an assessment should be carried by the duty ATC supervisor whereby a suitable timeslot should be chosen for the ATM platform restart;
- Restart of the TopSky ATM System **should not be carried out** within one (1) hour of scheduled change of shifts;
- Prior to the restart of the TopSky ATC platform, a system verification of the functionality of all nodes by Air Traffic Control Officers/supervisors as per an operational checklist as per Step 1, a Flight Plan Save should be carried out and the flight strips printed from the flight strip printer and updated as per Steps 4-6 below.

The following stop action table dictates the procedures to be followed for a Dataset or Software upgrade.

Step	Action
1	Make two copies of section 5 of Supervisor manual (Functionality System Checks) and distribute pages for ATCO checks.
2	Advise ALL concerned staff when the upgrade will commence.
3	AFTM Filter: Use VTMA, VOC1, VOC2 and VXOC to check the traffic for the next two hours.
4	Ensure strip printer is ON at OCA, APP and AIRLOG. Advise ATCOs that paper strips for the next two hours are to be printed.
5	Inform TWR of upgrade and advise that paper strips for the next two hours are to be printed.
6	Ensure that OCA / TMA / AIRLOG / TWR printed strips have been updated from their electronic strips
7	Advise TECH/Thales that they can proceed with TopSky Dataset Distribution
8	Ensure FDO TopSky Queues are empty and advise that they will lose the AMHS link to FDP
9	After TECH advises that the dataset has been distributed repeat step 8 to cross check empty Queues
10	Ask TECH for PEA AMHS and SITA links to be closed.
11	Perform a Flight Plan Save at least 7 minutes prior to hour H, H+15, H+30, H+45 minutes.
12	Obtain flight plan print out from the Flight Data Operator (FDO) who must ensure that all aircraft on the list are in the system after the platform restart
13	Ask FDO to check Queues again
14	Advise TECH/Thales to proceed with the upgrade
15	After upgrade has been completed, perform Flight Plan Restore from OPSUP.
16	Ask TECH to restore the AMHS and SITA links
17	Ensure that correct values are on the OPSUP Information Dialogue Window for: SECT, QNH, AHO, AGDL, PSS
18	Advise all ATCOs that they can upgrade their TopSky Position from DEGD mode to NORM, and also to update their FDR and MMI
19	Complete System Checks.
20	Advise TWR ATCO upgrade is now completed.