

Jig Loading - SOP

Titan Track and Trace

1.Login

- Login to the application using your credentials.

2.Navigate to Jig Loading

- From the left navigation menu, click **Jig Loading**.
- The Jig Loading – Pick Table screen is displayed with all lots received from Brass Audit that are ready for Jig Loading.

Jig Loading Pick Table

Step 3 - Review the Pick Table

The Pick Table contains the following information:

Column	Description
S.No	Serial number of the lot.
Last Updated	Date and time when the lot was last processed.
Plating Stk No	Plating Stock Number of the model.
Action	Click Add Jig to begin Jig Loading or View to see tray details.
Lot Qty	Total quantity available for loading into the jig.
No. of Trays	Number of trays available for the selected lot.
Process Status	Current loading status of the lot.
Jig Type	Required jig capacity (for example 98 Jig or 144 Jig).
Lot Status	Yet to Start, Draft, etc.
Current Stage	Displays the current process stage.
Polishing Stk No	Polishing Stock Number.
Plating Color	Plating colour of the model.
Polish Finish	Surface finish of the model.
Type of Input	Type of production input.
Input Info	Additional input details.
Remarks	Remarks entered during processing.

Step 4 - Click Add Jig

- Locate the required lot.
- Click the **Add Jig** button to start the Jig Loading process.

Jig Loading Process

Step 5 - Enter Jig ID

- Enter the Jig ID based on the Jig Capacity.

Examples:

144 Capacity Jig → J144-0000

98 Capacity Jig → J098-0000

The application validates the Jig ID format before allowing further processing.

Step 6 - Scan Tray IDs

- Scan all tray IDs belonging to the selected lot.
- The application validates every scanned tray.

Delinked Tray Handling

- If any tray is already delinked, scan the delinked tray IDs.

Excess Lot Handling

If excess quantity is detected:

- Scan the excess lot trays.
- Complete the Delink process before continuing with Jig Loading.

Step 7 - Add Model (If Required)

- Use Add Model when the remaining jig capacity can accommodate another compatible model.

The application automatically:

- Excludes lots that are already selected.
- Prevents duplicate lot selection.
- Allows only eligible models.
- Validates compatible models before adding them to the same jig.
- Prevents held or already submitted lots from being selected again.

Step 8 - Broken Hooks

- Select the number of Broken Hooks present in the jig.

Broken hooks reduce the effective loading capacity of the jig and are considered during quantity calculations.

Step 9 - Empty Hooks Calculation

- The Empty Hooks value is automatically calculated.

CALCULATION LOGIC

Empty Hooks = Jig Capacity – Broken Hooks – Loaded Cases Quantity

Users cannot edit this value manually; it is calculated automatically by the system.

Step 10 - Loaded Cases Quantity Calculation

The Loaded Cases Qty is automatically calculated by the system based on:

- Total accepted lot quantity.
- Quantity loaded from all selected models (for multi-model jigs).
- Jig capacity.
- Broken hooks.

For multi-model loading, the application aggregates the allocated quantity of all selected models and calculates the total loaded quantity automatically.

Step 11 - Verify Jig Composition

Before submitting:

- Verify the models loaded into the jig.
- Verify tray allocation.
- Verify case allocation.
- Verify quantities for each model displayed in the Jig Composition screen.

Step 12 - Submit

- Review all entered details.
- Click Submit to complete Jig Loading.

Completion Flow

Successfully loaded lots are moved to the Jig Completed stage for the next manufacturing process.

Moved to → Jig Completed