



Aviation Investigation Final Report

Location: Bonham, Texas Accident Number: CEN23LA382

Date & Time: August 23, 2023, 15:40 Local Registration: N7122E

Aircraft: PIPER AIRCRAFT INC PA-44-180 Aircraft Damage: Substantial

Defining Event: Landing gear not configured **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The flight instructor stated that during a simulated one engine inoperative approach and landing, the pilot receiving instruction chose to leave the landing gear retracted until the landing was assured. The pilot receiving instruction turned the airplane onto a short base leg before final, increased the mixture and propeller control settings, and increased the airplane bank angle so as not to overshoot the final approach course. The flight instructor saw that the airplane airspeed was decreasing and told the pilot receiving instruction that they were low. The pilot receiving instruction increased airplane pitch, which resulted in a decrease in airspeed, a loss of altitude, and a rolling motion. The flight instructor leveled the wings and reduced pitch to regain airplane control and lift. When the airplane was over the runway threshold, the flight instructor did not remember that the landing gear was still retracted and he did not complete the final landing checklist, which resulted in a landing with the landing gear retracted. The airplane sustained substantial damage to the underside fuselage longerons. There was no mechanical malfunction/failure of the airplane or system that would have precluded normal operations.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The failure of the pilot receiving instruction and flight instructor to follow the landing checklist and extend the landing gear before landing

Findings

Personnel issues	orgotten action/omission - Instructor/o	heck nilot
i ersonner issues	orgotteri action, ornission instructor, c	JIICCK PIIOL

Aircraft (general) - Not used/operated

Personnel issues Forgotten action/omission - Student/instructed pilot

Page 2 of 6 CEN23LA382

Factual Information

History of Flight

Landing-flare/touchdown	Simulated/training event
Landing	Landing gear not configured (Defining event)

Flight instructor Information

Certificate:	Commercial; Flight instructor	Age:	39,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine	Toxicology Performed:	
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	June 16, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	July 30, 2022
Flight Time:	1546.7 hours (Total, all aircraft), 182 hours (Total, this make and model), 1475.5 hours (Pilot In Command, all aircraft), 150.3 hours (Last 90 days, all aircraft), 47.1 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Pilot Information

Certificate:	Commercial	Age:	37,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	July 30, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	August 18, 2023
Flight Time:	214.4 hours (Total, all aircraft), 14 hours (Total, this make and model), 139.5 hours (Pilot In Command, all aircraft)		

Page 3 of 6 CEN23LA382

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER AIRCRAFT INC	Registration:	N7122E
Model/Series:	PA-44-180	Aircraft Category:	Airplane
Year of Manufacture:	2018	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	4496447
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	July 20, 2023 100 hour	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:	1870.9 Hrs as of last inspection	Engine Manufacturer:	LYCOMING
ELT:	C126 installed, not activated	Engine Model/Series:	0-360-A1H6
Registered Owner:	CHRISTIANSEN AVIATION LLC	Rated Power:	180 Horsepower
Operator:	American Flyers	Operating Certificate(s) Held:	Pilot school (141)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	DUA	Distance from Accident Site:	23 Nautical Miles
Observation Time:	15:35 Local	Direction from Accident Site:	345°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.01 inches Hg	Temperature/Dew Point:	41°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Addison, TX (ADS)	Type of Flight Plan Filed:	None
Destination:	Bonham, TX	Type of Clearance:	VFR
Departure Time:	14:00 Local	Type of Airspace:	Class G

Page 4 of 6 CEN23LA382

Airport Information

Airport:	Jones Field Airport F00	Runway Surface Type:	Asphalt
Airport Elevation:	618 ft msl	Runway Surface Condition:	Dry
Runway Used:	17	IFR Approach:	None
Runway Length/Width:	4000 ft / 75 ft	VFR Approach/Landing:	Full stop;Touch and go

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	33.613092,-96.179325(est)

Page 5 of 6 CEN23LA382

Administrative Information

Investigator In Charge (IIC):	Gallo, Mitchell
Additional Participating Persons:	Lonnie McDaniel; Federal Aviation Administration, North Texas FSDO; Irving, TX
Original Publish Date:	December 13, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192944

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN23LA382