



# **Aviation Investigation Final Report**

Location: Ben Wheeler, Texas Accident Number: CEN24LA142

Date & Time: March 30, 2024, 13:10 Local Registration: N3322U

Aircraft: Cessna 182F Aircraft Damage: Substantial

**Defining Event:** Loss of control in flight **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

The pilot reported that he was performing a practice soft field landing on a grass runway. During the landing flare, the wind increased, the airplane drifted to the left, and the indicated airspeed decreased by 10 mph. The pilot attempted to correct for the deviation when the airplane developed an excessive sink rate and landed hard on the sand adjacent to the left edge of the runway. The nose landing gear and propeller dug into the sand, the airplane nosed over and came to rest inverted. The airplane sustained substantial damage to both wings, the left aileron, the rudder, the vertical stabilizer, and the right wing strut. Wind at the time of the accident was 210° at 11 knots gusting to 17 knots.

The pilot stated that there were no preimpact mechanical malfunctions or failures that would have precluded normal operations.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain control while landing in a gusting wind.

## **Findings**

Aircraft Crosswind correction - Not attained/maintained

Aircraft Airspeed - Not attained/maintained

Personnel issues Aircraft control - Pilot

**Environmental issues** Gusts - Effect on operation

Page 2 of 6 CEN24LA142

## **Factual Information**

## History of Flight

Landing-flare/touchdown	Other weather encounter	
Landing-flare/touchdown	Loss of control in flight (Defining event)	
Landing-flare/touchdown	Abnormal runway contact	
Landing-landing roll	Nose over/nose down	

### **Pilot Information**

Certificate:	Commercial	Age:	75,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	Lap only
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	June 29, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	November 24, 2023
Flight Time:	(Estimated) 12718 hours (Total, all aircraft), 3505 hours (Total, this make and model), 8631 hours (Pilot In Command, all aircraft), 9 hours (Last 90 days, all aircraft), 9 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CEN24LA142

## **Aircraft and Owner/Operator Information**

Aircraft Make:	Cessna	Registration:	N3322U
Model/Series:	182F	Aircraft Category:	Airplane
Year of Manufacture:	1963	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18254722
Landing Gear Type:	Tricycle	Seats:	1
Date/Type of Last Inspection:	July 9, 2023 Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	5317.1 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	C91 installed	Engine Model/Series:	O-470-R-81-B
Registered Owner:	On file	Rated Power:	230 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KTYR,544 ft msl	Distance from Accident Site:	16 Nautical Miles
Observation Time:	13:00 Local	Direction from Accident Site:	105°
<b>Lowest Cloud Condition:</b>	Scattered / 3300 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	11 knots / 17 knots	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	Unknown / Unknown
Altimeter Setting:	29.99 inches Hg	Temperature/Dew Point:	24°C / 16°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Ben Wheeler, TX (TA37)	Type of Flight Plan Filed:	None
Destination:	Ben Wheeler, TX (TA37)	Type of Clearance:	None
Departure Time:	12:40 Local	Type of Airspace:	Class G

Page 4 of 6 CEN24LA142

## **Airport Information**

Airport:	Vaca Moo Airport TA37	Runway Surface Type:	Grass/turf
Airport Elevation:	590 ft msl	Runway Surface Condition:	Dry
Runway Used:	18	IFR Approach:	None
Runway Length/Width:	2480 ft / 50 ft	VFR Approach/Landing:	Full stop

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	32.428211,-95.711126(est)

Page 5 of 6 CEN24LA142

#### **Administrative Information**

Investigator In Charge (IIC):	Maxon, Cory
Additional Participating Persons:	Thomas Good; Federal Aviation Administration; TX
Original Publish Date:	June 28, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=194010

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN24LA142