



Aviation Investigation Final Report

Location: Lapeer, Michigan Accident Number: CEN24LA134

Date & Time: March 12, 2024, 14:00 Local Registration: N1103H

Aircraft: Cessna T182T Aircraft Damage: Substantial

Defining Event: Loss of control in flight **Injuries:** 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot was conducting a crosswind landing when shortly before touchdown the airplane drifted left of the runway centerline. The airplane bounced and continued to drift left into the grass easement adjacent to the runway where the nose gear collapsed. The airplane then nosed over and came to rest inverted. The airplane sustained substantial damage to the vertical stabilizer, rudder, right wing strut, and left wing. Based on available wind data, there was a gusting right crosswind of 10-15 knots.

The pilot stated that there were no preimpact mechanical malfunctions or failures that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain aircraft control while landing in a gusting crosswind condition.

Findings

Aircraft Crosswind correction - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Crosswind - Effect on operation

Environmental issues Gusts - Effect on operation

Page 2 of 6 CEN24LA134

Factual Information

History of Flight

Landing-flare/touchdown	Other weather encounter	
Landing-flare/touchdown	Loss of control in flight (Defining event)	
Landing-flare/touchdown	Hard landing	
Landing-landing roll	Runway excursion	
Landing-landing roll	Landing gear collapse	
Landing-landing roll	Nose over/nose down	

Pilot Information

Certificate:	Private	Age:	61,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	October 10, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	December 19, 2023
Flight Time:	(Estimated) 912 hours (Total, all aird 90 days, all aircraft)	craft), 32 hours (Total, this make and r	model), 32 hours (Last

Page 3 of 6 CEN24LA134

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N1103H
Model/Series:	T182T	Aircraft Category:	Airplane
Year of Manufacture:	2006	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	T18208637
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	December 20, 2023 Annual	Certified Max Gross Wt.:	3100 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1900 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	TIO-12497-61A
Registered Owner:	On file	Rated Power:	235 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	D95,835 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	13:55 Local	Direction from Accident Site:	64°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots / 15 knots	Turbulence Type Forecast/Actual:	Unknown / Unknown
Wind Direction:	260°	Turbulence Severity Forecast/Actual:	Unknown / Unknown
Altimeter Setting:	29.81 inches Hg	Temperature/Dew Point:	19°C / 3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Adrian, MI (ADG)	Type of Flight Plan Filed:	None
Destination:	Lapeer, MI (D95)	Type of Clearance:	None
Departure Time:	13:15 Local	Type of Airspace:	Class G

Page 4 of 6 CEN24LA134

Airport Information

Airport:	Dupont/Lapeer Airport D95	Runway Surface Type:	Asphalt
Airport Elevation:	835 ft msl	Runway Surface Condition:	Dry
Runway Used:	18	IFR Approach:	None
Runway Length/Width:	3800 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	43.066472,-83.271556(est)

Page 5 of 6 CEN24LA134

Administrative Information

Investigator In Charge (IIC):	Fox, Andrew
Additional Participating Persons:	Jeffrey A. Anderson; Federal Aviation Administration - Eastern Michigan FSDO; Belleville, MI
Original Publish Date:	April 30, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=193930

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN24LA134