



# **Aviation Investigation Final Report**

Location: Chapman, Kansas Accident Number: CEN23LA279

Date & Time: July 5, 2023, 16:41 Local Registration: N67FA

Aircraft: Bell 206B Aircraft Damage: Substantial

**Defining Event:** Low altitude operation/event **Injuries:** 1 None

Flight Conducted Under: Part 137: Agricultural

### **Analysis**

The pilot intended to spray a corn field and had discussed the location of power lines with his ground crew. As he approached the field, he observed power lines on 3 sides of the field in addition to a large set of power lines feeding into an adjacent substation. The pilot completed a 360° survey to identify the hazards including power lines, guy wires, and trees. During the survey, the middle of the field appeared to be clear. The pilot initiated an initial application pass and the helicopter struck a green wire, about 1/4" in diameter. The pilot's efforts to maintain control of the helicopter were not successful, and it subsequently impacted the corn field. The helicopter came to rest on its left side with substantial damage to the fuselage, tail boom, main rotor blades, and flight controls. The pilot stated that there were no failures or malfunctions related to the helicopter before the impact with the power line. He also noted that the power line was green in color which was "practically invisible" with the background of the corn field.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain clearance from the power line during an agricultural application pass.

### **Findings**

Personnel issues	Identification/recognition - Pilot
Environmental issues	Wire - Contributed to outcome
Aircraft	Altitude - Not attained/maintained

Page 2 of 6 CEN23LA279

## **Factual Information**

### History of Flight

Maneuvering-low-alt flying	Low altitude operation/event (Defining event)	
Maneuvering-low-alt flying	Collision with terr/obj (non-CFIT)	

#### **Pilot Information**

Certificate:	Commercial	Age:	42.Male
		3	,
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	5-point
Instrument Rating(s):	Helicopter	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	June 28, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	September 3, 2022
Flight Time:	5250 hours (Total, all aircraft), 2008 hours (Total, this make and model), 4656 hours (Pilot In Command, all aircraft)		

Page 3 of 6 CEN23LA279

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Bell	Registration:	N67FA
Model/Series:	206B	Aircraft Category:	Helicopter
Year of Manufacture:	1994	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	5168
Landing Gear Type:	High skid	Seats:	3
Date/Type of Last Inspection:	June 22, 2023 Annual	Certified Max Gross Wt.:	3350 lbs
Time Since Last Inspection:	2 Hrs	Engines:	1 Turbo shaft
Airframe Total Time:	10095 Hrs as of last inspection	Engine Manufacturer:	Allison
ELT:	Not installed	Engine Model/Series:	250-C20 SER
Registered Owner:	SF LEASING LLC	Rated Power:	420 Horsepower
Operator:	SF LEASING LLC	Operating Certificate(s) Held:	Agricultural aircraft (137)
Operator Does Business As:	Fulks Helicopter Service	Operator Designator Code:	N/A

### **Meteorological Information and Flight Plan**

meteorological informati			
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KFRI,1065 ft msl	Distance from Accident Site:	12 Nautical Miles
Observation Time:	16:55 Local	Direction from Accident Site:	75°
<b>Lowest Cloud Condition:</b>	Few / 2500 ft AGL	Visibility	7 miles
Lowest Ceiling:	Broken / 7000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	4 knots / 0 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	10°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.05 inches Hg	Temperature/Dew Point:	27°C / 19°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Junction City, KS (PVT)	Type of Flight Plan Filed:	None
Destination:	Junction City, KS (PVT)	Type of Clearance:	None
Departure Time:	13:18 Local	Type of Airspace:	Class G

Page 4 of 6 CEN23LA279

### **Airport Information**

Airport:	Smokey Valley Ag PVT	Runway Surface Type:	
Airport Elevation:	1258 ft msl	Runway Surface Condition:	Vegetation
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	38.9978,-97.0175(est)

Page 5 of 6 CEN23LA279

#### **Administrative Information**

Investigator In Charge (IIC):	Sorensen, Timothy
Additional Participating Persons:	Michael LeBlanc; FAA Flight Standards; Wichita, KS
Original Publish Date:	September 8, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192545

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN23LA279