



Aviation Investigation Final Report

Location: Midlothian, Texas Accident Number: CEN23LA392

Date & Time: August 31, 2023, 16:13 Local Registration: N11648

Aircraft: Bellanca 7ECA Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot was familiarizing himself with the airplane in preparation for a multi-day cross-country flight. He also said that there was a potential that he would provide flight instruction to a student during the upcoming flights, so he wanted to perform three takeoffs and landings in the airplane to meet the recent flight experience requirements of Title 14 *Code of Federal Regulations* Part 61.57. He said that as he approached the airport, the reported weather indicated the wind was aligned with the runway. During the approach, he noted that the windsock showed a left crosswind, and he adjusted the approach using crosswind control correction for the left crosswind. During the rollout, the wind shifted, and the right wing rose. The pilot attempted to correct but when the wing came back down the airplane veered off the left side of the runway and the right main landing gear collapsed. He said that after the event the windsock showed a right crosswind and he believed that there was some windshear that resulted in the right wing raising during the event. The airplane received substantial damage to the right wing. The pilot reported that there were no mechanical issues with the airplane. The recorded weather at the airport where the accident occurred was from 020° at 3 knots, about the time of the accident.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during landing which resulted in the right main landing gear collapse.

Findings

A:	Divertional control Net attained/perintained
Aircraft	Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Page 2 of 5 CEN23LA392

Factual Information

History of Flight

Landing-landing roll	Loss of control on ground (Defining event)		
----------------------	--	--	--

Pilot Information

Certificate:	Commercial; Private	Age:	24,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	August 9, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	650 hours (Total, all aircraft), 4 hour	s (Total, this make and model)	

Aircraft and Owner/Operator Information

Aircraft Make:	Bellanca	Registration:	N11648
Model/Series:	7ECA	Aircraft Category:	Airplane
Year of Manufacture:	1972	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	838-72
Landing Gear Type:		Seats:	2
Date/Type of Last Inspection:		Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1
Airframe Total Time:		Engine Manufacturer:	
ELT:		Engine Model/Series:	
Registered Owner:	BRUNS LUKE J	Rated Power:	
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 CEN23LA392

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KJWY,749 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	16:15 Local	Direction from Accident Site:	190°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Broken / 10000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	20°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.89 inches Hg	Temperature/Dew Point:	37°C / 14°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Grand Prairie, TX (GPM)	Type of Flight Plan Filed:	None
Destination:	Grand Prairie, TX (GPM)	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Airport Information

Airport:	MID-WAY RGNL JWY	Runway Surface Type:	Asphalt
Airport Elevation:	727 ft msl	Runway Surface Condition:	Dry
Runway Used:	18	IFR Approach:	None
Runway Length/Width:	6500 ft / 100 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	32.458293,-96.912526

Page 4 of 5 CEN23LA392

Administrative Information

Investigator In Charge (IIC):	Brannen, John
Additional Participating Persons:	Leslie Williams; FAA; Irving, TX
Original Publish Date:	January 4, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192979

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CEN23LA392