



# **Aviation Investigation Final Report**

Location: Tyler, Minnesota Accident Number: CEN23LA335

Date & Time: July 28, 2023, 11:02 Local Registration: N7094Z

Aircraft: Piper PA-25-235 Aircraft Damage: Substantial

**Defining Event:** Loss of control in flight **Injuries:** 1 None

Flight Conducted Under: Part 137: Agricultural

#### **Analysis**

The pilot attempted the takeoff with the flaps in the half or first notch position. Unable to rotate during the takeoff roll, the pilot selected the full flap position, and the agricultural airplane lifted off the 2,500-ft long turf airstrip about 150 feet before the end of the runway. The airplane was unable to climb out of ground effect and contacted corn stalks that were located past the end of the runway. The airplane descended into the vegetation and came to rest nose down and upright. The airplane sustained substantial damage to both wings.

According to the airplane owner's handbook, a takeoff distance of about 1,370 feet was required to clear a 50-foot obstacle with the sprayer configuration. The handbook recommended that the wing flaps be retracted at all times during takeoff.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper flap position during takeoff, which resulted in degraded climb performance and a collision with terrain.

# **Findings**

Aircraft Trailing edge flaps - Incorrect use/operation

Personnel issues Incorrect action selection - Pilot

Aircraft Climb rate - Attain/maintain not possible

Page 2 of 6 CEN23LA335

# **Factual Information**

# History of Flight

Prior to flight	Preflight or dispatch event	
Initial climb	Loss of control in flight (Defining event)	
Initial climb	Collision with terr/obj (non-CFIT)	

### **Pilot Information**

Certificate:	Commercial	Age:	25,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Single
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	February 3, 2021
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	March 21, 2022
Flight Time:	1126 hours (Total, all aircraft), 837 hours (Total, this make and model), 1070 hours (Pilot In Command, all aircraft), 60 hours (Last 90 days, all aircraft), 25 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CEN23LA335

# **Aircraft and Owner/Operator Information**

Aircraft Make:	Piper	Registration:	N7094Z
Model/Series:	PA-25-235	Aircraft Category:	Airplane
Year of Manufacture:	1969	Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	25-5052
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	March 4, 2023 100 hour	Certified Max Gross Wt.:	2900 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	7029 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	O-540-B2-B5
Registered Owner:	On file	Rated Power:	235 Horsepower
Operator:	On file	Operating Certificate(s) Held:	Agricultural aircraft (137)
Operator Does Business As:	On file	Operator Designator Code:	1JKG

# Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KMML,1179 ft msl	Distance from Accident Site:	17 Nautical Miles
Observation Time:	10:56 Local	Direction from Accident Site:	57°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	30°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.96 inches Hg	Temperature/Dew Point:	26°C / 22°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Tyler, MN (63Y)	Type of Flight Plan Filed:	None
Destination:	Tyler, MN (63Y)	Type of Clearance:	None
Departure Time:	11:00 Local	Type of Airspace:	Class G

Page 4 of 6 CEN23LA335

# **Airport Information**

Airport:	Tyler Municipal Airport 63Y	Runway Surface Type:	Grass/turf
Airport Elevation:	1742 ft msl	<b>Runway Surface Condition:</b>	Dry;Vegetation
Runway Used:	32	IFR Approach:	None
Runway Length/Width:	2517 ft / 160 ft	VFR Approach/Landing:	None

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	44.291693,-96.153769

Page 5 of 6 CEN23LA335

#### **Administrative Information**

Investigator In Charge (IIC):	Finne, Andrew
Additional Participating Persons:	Thurston, Gregory ; FAA-FSDO; Minneapolis, MN
Original Publish Date:	October 5, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192748

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN23LA335