NR7101
Generic Version

Firmware Release Note

1.00(ABUV.11)C0

Date: Nov. 29, 2024
Author: Aaron Kuo
Reviewer:

THIS DOCUMENT CONTAINS PROPRIETARY TECHNICAL INFORMATION THAT IS THE PROPERTY OF THE ZyXEL AND SHOULD NOT BE DISCLOSED TO OTHERS IN WHOLE OR IN PART, REPRODUCED, COPIED, OR USED AS BASIS FOR DESIGN, MANUFACTURING OR SALE OF APPARATUS WITHOUT WRITTEN PERMISSION OF ZyXEL.

TABLE OF CONTENTS

SUPPORTED PLATFORMS: 8
VERSIONS: 8
FIRMWARE IMAGE INFORMATION: 8
NOTES: 9
DEFAULT SETTINGS IN FIRMWARE 9
MODIFICATIONS IN 1.00(ABUV.11)C0 10
MODIFICATIONS IN 1.00(ABUV.11)B1 10
MODIFICATIONS IN 1.00(ABUV.10)C0 10
MODIFICATIONS IN 1.00(ABUV.10)B2 11
MODIFICATIONS IN 1.00(ABUV.10)B1 11
MODIFICATIONS IN 1.00(ABUV.9)C0 12
MODIFICATIONS IN 1.00(ABUV.9)B5 12
MODIFICATIONS IN 1.00(ABUV.9)B4 12
MODIFICATIONS IN 1.00(ABUV.9)B3 13
MODIFICATIONS IN 1.00(ABUV.9)B2 13
MODIFICATIONS IN 1.00(ABUV.9)B1 14
MODIFICATIONS IN 1.00(ABUV.8)C0 14
MODIFICATIONS IN 1.00(ABUV.8)B3 15
MODIFICATIONS IN 1.00(ABUV.8)B2 16
MODIFICATIONS IN 1.00(ABUV.8)B1 16
MODIFICATIONS IN 1.00(ABUV.7)C0 17
MODIFICATIONS IN 1.00(ABUV.7)B3 18
MODIFICATIONS IN 1.00(ABUV.7)B2 18
MODIFICATIONS IN 1.00(ABUV.7)B1 19
MODIFICATIONS IN 1.00(ABUV.6)F3 20
MODIFICATIONS IN 1.00(ABUV.6)G2 20

MODIFICATIONS IN 1.00(ABUV.6)C1 20
MODIFICATIONS IN 1.00(ABUV.6)C0 21
MODIFICATIONS IN 1.00(ABUV.6)B5 21
MODIFICATIONS IN 1.00(ABUV.6)B4 22
MODIFICATIONS IN 1.00(ABUV.6)B3 23
MODIFICATIONS IN 1.00(ABUV.6)B2 24
MODIFICATIONS IN 1.00(ABUV.6)B1 25
MODIFICATIONS IN 1.00(ABUV.5)C0 26
MODIFICATIONS IN 1.00(ABUV.5)B2 26
MODIFICATIONS IN 1.00(ABUV.5)B1 27
MODIFICATIONS IN 1.00(ABUV.4)C0 28
MODIFICATIONS IN 1.00(ABUV.4)B3 28
MODIFICATIONS IN 1.00(ABUV.4)B2 28
MODIFICATIONS IN 1.00(ABUV.4)B1 29
MODIFICATIONS IN 1.00(ABUV.3)C0 30
MODIFICATIONS IN 1.00(ABUV.3)B6 30
MODIFICATIONS IN 1.00(ABUV.3)B5 31
MODIFICATIONS IN 1.00(ABUV.3)B4 32
MODIFICATIONS IN 1.00(ABUV.3)B3 32
MODIFICATIONS IN 1.00(ABUV.3)B2 32
MODIFICATIONS IN 1.00(ABUV.3)B1 33
MODIFICATIONS IN 1.00(ABUV.2)C0 34
MODIFICATIONS IN 1.00(ABUV.2)B5 34
MODIFICATIONS IN 1.00(ABUV.2)B4 35
MODIFICATIONS IN 1.00(ABUV.2)B3 35
MODIFICATIONS IN 1.00(ABUV.2)B2 36
MODIFICATIONS IN 1.00(ABUV.1)B2 37
MODIFICATIONS IN 1.00(ABUV.1)B1 37

MODIFICATIONS IN 1.00(ABUV.0)C0 38
MODIFICATIONS IN 1.00(ABUV.0)B12 38
MODIFICATIONS IN 1.00(ABUV.0)B11 38
MODIFICATIONS IN 1.00(ABUV.0)B10 39
MODIFICATIONS IN 1.00(ABUV.0)B9 39
MODIFICATIONS IN 1.00(ABUV.0)B8 39
MODIFICATIONS IN 1.00(ABUV.0)B7 40
MODIFICATIONS IN 1.00(ABUV.0)B6 41
MODIFICATIONS IN 1.00(ABUV.0)B5 41
MODIFICATIONS IN 1.00(ABUV.0)B4 42
MODIFICATIONS IN 1.00(ABUV.0)B3 42
MODIFICATIONS IN 1.00(ABUV.0)B2 43
MODIFICATIONS IN 1.00(ABUV.0)B1 43
CHECK LIST FOR THE ITEMS MAY BE RELATED TO HW FUNCTIONS 46

Revision History

Date	Release	Author	Description
2020/01/07	1.0	Aaron Kuo	1.00(ABUV.0)b1 FW release
2020/01/13	1.1	Aaron Kuo	1.00(ABUV.0)b2 FW release
2020/02/19	1.2	Aaron Kuo	1.00(ABUV.0)b3 FW release
2020/03/25	1.3	Aaron Kuo	1.00(ABUV.0)b4 FW release
2020/04/30	1.4	Aaron Kuo	1.00(ABUV.0)b5 FW release
2020/05/19	1.5	Aaron Kuo	1.00(ABUV.0)b6 FW release
2020/06/24	1.6	Marcus Tsai	1.00(ABUV.0)b7 FW release
2020/07/30	1.7	Aaron Kuo	1.00(ABUV.0)b8 FW release
2020/08/06	1.8	Aaron Kuo	1.00(ABUV.0)b9 FW release
2020/08/11	1.9	Marcus Tsai	1.00(ABUV.0)b10 FW release
2020/08/12	1.10	Marcus Tsai	1.00(ABUV.0)b11 FW release
2020/08/14	1.11	Marcus Tsai	1.00(ABUV.0)b12FW release
2020/08/18	1.12	Marcus Tsai	1.00(ABUV.0)C0FW release
2020/09/18	2.0	Aaron Kuo	1.00(ABUV.1)b1FW release
2020/09/28	2.1	Marcus Tsai	1.00(ABUV.1)b21FW release
2020/10/06	2.11	Marcus Tsai	Revise some release modifications
2020/11/17	3.1	YuChih Hu	1.00(ABUV.2)b2 FW release
2020/11/20	3.2	YuChih Hu	1.00(ABUV.2)b3 FW release
2021/01/19	3.3	Aaron Kuo	1.00(ABUV.2)b4 FW release
2021/02/02	3.4	Aaron Kuo	1.00(ABUV.2)b5 FW release
2021/02/08	3.5	Aaron Kuo	1.00(ABUV.2)C0 FW release
2021/03/29	4.1	Aaron Kuo	1.00(ABUV.3)b1 FW release
2021/05/04	4.2	Aaron Kuo	1.00(ABUV.3)b2 FW release
2021/05/07	4.3	ChungTa Hsieh	1.00(ABUV.3)b3 FW release
2021/05/11	4.4	Aaron Kuo	1.00(ABUV.3)b4 FW release
2021/05/28	4.5	Aaron Kuo	1.00(ABUV.3)b5 FW release
2021/06/24	4.6	Aaron Kuo	1.00(ABUV.3)b6 FW release
2021/07/08	4.7	Aaron Kuo	1.00(ABUV.3)C0 FW release
2021/08/16	5.0	Aaron Kuo	1.00(ABUV.4)b1 FW release
2021/09/24	5.1	Aaron Kuo	1.00(ABUV.4)b2 FW release
2021/10/15	5.2	Aaron Kuo	1.00(ABUV.4)b3 FW release
2021/11/03	5.3	Aaron Kuo	1.00(ABUV.4)C0 FW release

2021/11/26	5.3	Aaron Kuo	1.00(ABUV.5)b1 FW release
2021/12/30	5.4	Aaron Kuo	1.00(ABUV.5)b2 FW release
2022/01/12	5.5	Aaron Kuo	1.00(ABUV.5)C0 FW release
2022/01/27	5.6	Aaron Kuo	1.00(ABUV.6)b1 FW release
2022/03/15	5.7	Aaron Kuo	1.00(ABUV.6)b2 FW release
2022/04/25	5.8	Aaron Kuo	1.00(ABUV.6)b3 FW release
2022/05/26	5.9	Aaron Kuo	1.00(ABUV.6)b4 FW release
2022/07/04	6.0	Aaron Kuo	1.00(ABUV.6)b5 FW release
2022/07/27	6.1	Aaron Kuo	1.00(ABUV.6)C0 FW release
2022/08/15	6.2	Aaron Kuo	1.00(ABUV.7)b1 FW release
2022/08/31	6.3	Aaron Kuo	1.00(ABUV.6)C1 FW release
2022/09/16	6.4	Aaron Kuo	1.00(ABUV.7)b2 FW release
2022/09/29	6.5	Aaron Kuo	1.00(ABUV.6)G2 FW release
2022/10/24	6.6	Aaron Kuo	1.00(ABUV.7)b3 FW release
2022/11/14	6.7	Aaron Kuo	1.00(ABUV.6)F3 FW release
2022/11/30	6.8	Aaron Kuo	1.00(ABUV.7)C0 FW release
2022/12/20	6.9	Aaron Kuo	1.00(ABUV.8)b1 FW release
2023/02/16	7.0	Aaron Kuo	1.00(ABUV.8)b2 FW release
2023/03/24	7.1	Aaron Kuo	1.00(ABUV.8)b3 FW release
2023/05/15	7.2	Aaron Kuo	1.00(ABUV.8)C0 FW release
2023/06/20	7.3	Aaron Kuo	1.00(ABUV.9)b1 FW release
2023/08/25	7.4	Aaron Kuo	1.00(ABUV.9)b2 FW release
2023/09/21	7.5	Aaron Kuo	1.00(ABUV.9)b3 FW release
2023/10/26	7.6	Aaron Kuo	1.00(ABUV.9)b4 FW release
2023/11/27	7.7	Aaron Kuo	1.00(ABUV.9)b5 FW release
2023/12/05	7.8	Aaron Kuo	1.00(ABUV.9)C0 FW release
2024/02/19	7.9	Aaron Kuo	1.00(ABUV.10)b1 FW release
2024/08/01	8.0	Aaron Kuo	1.00(ABUV.10)b2 FW release
2024/08/26	8.1	Aaron Kuo	1.00(ABUV.10)C0 FW release
2024/11/22	8.2	Aaron Kuo	1.00(ABUV.11)b1 FW release
2024/11/29	8.3	Aaron Kuo	1.00(ABUV.11)C0 FW release

ZyXEL NR7101 Generic
1.00(ABUV.11)C0

Release Note

Date: Nov. 29, 2024

Supported Platforms:

ZyXEL NR7101 Generic (EU)

Versions:

Bootbase version : U-Boot 1.1.3 (Jul 18 2019 - 14:58:57)
Firmware version : V1.00(ABUV.11)C0
Kernel version: 3.10.14
WLAN code version: V4.0.1.0rev1
LTE Module FW version: RG502QEAACR13A04M4G_ZYXEL

Firmware image information:

Image	Version	File name	MD5 sum
Uboot Image -1: Pre-programming	U-Boot 1.1.3 (Jun 3 2020 - 08:39:27)	uboot-7101-20200603.bin	19a87cd4b44d240bcf0a26de20e1ef17
Uboot Image-2: Zyxel uboot update		100ABUV0b9.bm	122b6a11db56015a03dea868c022e62c
FW Image	**1.00 (ABUV.11)C0**	**100ABUV11C0.bin**	**9190e41ef1a4cf584cbd24c0c0bd66de**
	1.00 (ABUV.11)D0	**100ABUV11D0.bin**	**8867a7fdb2ed4117a56489d1543102d2**
	1.00 (ABUV.11)D1	**100ABUV11D1.bin**	**9ab230af31040037d5ca28265d9cbf56**
	1.00 (ABUV.11)E0	**100ABUV11E0.bin**	**13bce3eca6620a9c034674d8923457eb**
	1.00 (ABUV.11)F0	**100ABUV11F0.bin**	**7b298a9f74f63a50aa183d0882331a05**
	1.00 (ABUV.11)G0	**100ABUV11G0.bin**	**19323effba2b4eb1138cc5a234da29cc**
	1.00 (ABUV.11)G1	**100ABUV11G1.bin**	**dd418b99a31b1513f6a773e5b30d1804**
	1.00 (ABUV.11)H0	**100ABUV11H0.bin**	**d48867a01dc20bfd3b081054615c4201**
	1.00 (ABUV.11)I0	**100ABUV11I0.bin**	**e1828d7281777cb456bc0503858f4509**

	1.00 (ABUV.11)J0	**100ABUV11J0.bin**	**dd83332e613ffd5c4b77ea2c952a57b8**

Notes:

There are two Bootbase files :
uboot-7101-20200603.bin
is used for manufacturing PROGRAMMER to program on the NAND flash
100 ABUV0b9.bm
is for zyxel bootloader update usage, **This file with zyxel header and must not directly program to flash. Wrong action will cause the failure of boot.**

Default Settings in Firmware

- Refer to the *.rom in the fw release package.
- Refer to the *.config and *.predef for human readable default configuration.
- *.config define the default value of writable parameters, *.predef define the default value of read only parameters.
- Please use the website http://jsoneditoronline.org/ to open the *.config and *predef files.

Modifications in 1.00(ABUV.11)C0

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Change version from 1.00(ABUV11)b1 to 1.00(ABUV.11)C0
2. Configuration change and new certificate for G1

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.11)b1

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

N/A

[Fixed Defects]

1. Zyxel-SI-1576 [Vulnerability] Unauthenticated buffer overflow in the libclinkc library
2. [eITS Ticket #240800516] not forwarding un-initaited IPv6 traffic
3. [eITS Ticket #240800935] goes offline after setting band lock
4. [eITS Ticket #240901830] DHCPv6, nobinding on renew

Modifications in 1.00(ABUV.10)C0

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Change version from 1.00(ABUV10)b2 to 1.00(ABUV.10)C0

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.10)b2

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

N/A

[Fixed Defects]

1. [eITS Ticket #240101156] PCI scan does not work: extend PCI scan's timeout value from 120 seconds to 180 seconds.
2. [eITS Ticket #240101167] adjust module reset's design to address attach rush: changes timestamp's format in cm_log to Unix epoch.
3. [eITS Ticket #240200302] Unauthorized error when trying to log into WebGUI
4. [eITS Ticket #240201153] ZySH admin privileges for cfg tr69 command
5. [eITS Ticket #240201223] DNS entry for G0
6. [eITS Ticket #240501062] ztr69cli support for querying multiple parameters

Modifications in 1.00(ABUV.10)b1

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Add B32/B34 information in Band selection
2. Add new setting of TR069 to G0 branch

[Fixed Defects]

1. [eITS Ticket #231000045] does not reboot after module upgrade - obuspa seems crashed
2. [eITS Ticket #231002222] IPv6-features
3. [eITS Ticket #231101167] IPv6 implementation
4. [eITS Ticket #231002087] Danish APNs added into 5G FWA/NR devices
5. [eITS Ticket #231101228] SCC values inconsistency between cli/web/tr069
6. [eITS Ticket #231201466] DNS static change
7. [eITS Ticket #240100202] Neighbours cells
8. [eITS Ticket #240100794] USP Not able to disable IP Passthrough
9. [eITS Ticket #240101110] policy route to wrong br
10. [MANTIS-7157] Updated: DHCP NAK - Lease not found

11. [Vulnerability] Zyxel-SI-1536 Buffer overflow vulnerability in the "traceroute" command

Modifications in 1.00(ABUV.9)C0

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Change version from 1.00(ABUV9)b5 to 1.00(ABUV.9)C0

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.9)b5

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. New IP address (195.3.82.230) for network monitor detection
2. New Bridge IP Address setting

[Fixed Defects]

1. [eITS Ticket #231100496] [NR7101] USP GET parameter response shows unexpected values
2. [Internal Issue #39519]: SPV SentDHCPOption.N.Value as "String' format is invalid
3. [Customer’s Issue]: Unable to upgrade from 9b4_X to official version

Modifications in 1.00(ABUV.9)b4

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Change ip alias from 192.168.1.1 to 195.3.85.241
2. Support dhcp option 121

[Fixed Defects]

1. [eITS Ticket #231000027] NR7101 V1.00(ABUV.9)b3_I0 broken ntp

Modifications in 1.00(ABUV.9)b3

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

N/A

[Fixed Defects]

1. [Internal Issue #32469] Scheduled reboot setting at Specific time function invalid
2. [Internal Issue #36290] DMZ fail while deliver UDP traffic
3. [Internal Issue #36700] Login web GUI via supervisor/admin account, restore configuration (with user group account), DUT will enter to production FW, it is incorrect.
4. [Internal Issue #38461] SCC#1 Band cannot display correct info.(showed N/A)

Modifications in 1.00(ABUV.9)b2

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. add object of PhyCellIdLockedList for TR98
2. Zyxel LCM options in OPAL devices.
3. add 5G parameters of TR98
4. Add rom convert to support Dual SIM function

[Fixed Defects]

1. [Internal Issue #31607] Fix Duplicated VLAN ID will cause VLAN setting incorrect.
2. [Internal Issue #35850] Multi-DEFAULT_CERTIFICATE options in TR-069 Client page
3. [Internal Issue #37413] Fix Not support "sys ltefw_upgrade <URL>" command
4. [Internal Issue #37295] There is no any NR information on GUI (Cellular Info & Cellular WAN Status).
5. [Internal Issue #37690] ACS cannot SPV / GPV correctly after DUT set inform interval time from default (43200) to 30
6. [eITS Ticket #230300541] NR7101: show IPv6 prefix and prefix length on GUI
7. [eITS Ticket #230701467] NR7101: remove dropbear pubkey
8. [Vulnerability][Zyxel-SI-1498] Fix WPS vulnerability in WLAN

Modifications in 1.00(ABUV.9)b1

[Know defects]

2. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

N/A

[Fixed Defects]

1. [eITS Ticket # 230300593] attach behavior
2. [eITS Ticket # 230500979] Add BandwidthDownIndex and BandwidthUpIndex to scc
3. [Internal Issue# 24914] UE reboot automatically due to memory ran out
4. [Internal Issue# 30464] DUT only can establish registration to IPv6 ACS via Cellular WAN1
5. [Internal Issue# 31872] DUT happened "Sending discover"
6. [Internal Issue# 35757] After default WiFi on 30mins, should deactivate WiFi.
7. [Internal Issue# 36056] Under 5G capable environment, GUI often displayed LTE/LTE-A mode.
8. [Internal Issue# 36201] After doing reboot stress test via SMS, test fail & rilcmd will restart regularly, reboot cannot recover.
9. [Internal Issue# 36238] NR SCC Band frequency info doesn't meet customer's requirement in Cellular WAN Status page.
10. [Internal Issue# 36239] NR5G-SA SCC info doesn't display via CLI.
11. [Internal Issue# 36246] NR5G-SA SCC info doesn't display via CLI.
12. [Internal Issue# 36260] DUT can't attach APN which supports IPv6 PDP type only.
13. [Internal Issue# 36445] Only can remote management with IPv6 address via APN2 (Cellular WAN 2).
14. [Internal Issue# 36525] The Web GUI of TR-471 Test is not user friendly.

Modifications in 1.00(ABUV.8)C0

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Change version from 1.00(ABUV.8)b3 to 1.00(ABUV.8)C0

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.8)b3

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

N/A

[Fixed Defects]

1. [eITS Ticket # 230300772] No dual SIM failover happened
2. [Vulnerability] Potential buffer overflow in CGI
3. [Internal Issue# 20725] Two APNs are random used simultaneously even the dual APN feature is not enabled under auto APN mode.
4. [Internal Issue# 30536] Special character WiFi SSID cause Scan QR code malfunction.
5. [Internal Issue# 30647] could be upgraded to other project FW directly
6. [Internal Issue# 31722] Cellular info in Web GUI is not correct for SA NR CA mode
7. [Internal Issue# 31761] DUT can't get correct DNS server information from ISP (Customer Version)
8. [Internal Issue# 31762] DUT can't get correct DNS server information from ISP(Generic Version)
9. [Internal Issue# 31794] NR PCC has no Phy Cell ID info. under EN-DC RAT
10. [Internal Issue# 31795] Signal Information Table has wrong information.
11. [Internal Issue# 31872] DUT happened "Sending discover"
12. [Internal Issue# 34860] RM fail via Cellular WAN2/3 under 5G-SA with IPPT/Router mode
13. [Internal Issue# 35676] GUI will hang after changing RAT then select part of Cellular related options.
14. [Internal Issue# 35909] 3G shouldn't be included in Preferred Access Technology by default
15. [Internal Issue# 35857] Switch mode between IPPT and Router, will cause DUT to disconnect, reboot can recover.
16. [Customer’s Issue] Change to syslog size from 100kib to 1000
17. [Customer’s Issue] Changing operation mode from IPPT to Router mode brings NR7101 offline
18. [Customer’s Issue] DHCP Server does not assign IP addresses on untagged Bridge1 out of 195.3.85.243-195.3.85.246 pool it is configured in router mode
19. [Customer’s Issue] extension of the "Trust Domain" ACL with this ULA network: fda1:3fb1:0:102:0:0:0:0/64
20. [Customer’s Issue] TR-069 SPVs InternetGatewayDevice.Cellular.NetworkMonitorEnabled return 9002.
21. [Customer’s Issue] reboot router via SMS txt message feature request

Modifications in 1.00(ABUV.8)b2

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. The page “Agent→ Contorller→MQTT” change to “MQTT→ Agent→ Controller”

[Fixed Defects]

1. [eITS Ticket # 220900596] Fix infinite loop in the ping of diagnostic when input IPv6 addresses.
2. [eITS Ticket # 221200524] USP Boot when changing broker
3. [eITS Ticket # 221201311] WebGUI Missing cellular info
4. [eITS Ticket # 230100554] Baseband not shown without SIM card
5. [eITS Ticket # 230101369] APN change causing LAN disconnection
6. [eITS Ticket # 230101370] certificate dates
7. [eITS Ticket # 230200494] Disabling NAT by TR-069 does not work immediately; a reboot is needed
8. [Internal Issue #34490] Web GUI is always loading
9. [Internal Issue #34526] There is no APN column of APN#4 in SIM 1 / SIM 2.
10. [Internal Issue #30639] CM detected Device status as CREG_REGISTERED_ROAMING while registered with EHPLMN in SIM
11. [Customer Issue] Public Subnet Not Work
12. [Customer Issue] Set TR-471 default server
13. [Customer Issue] Remote-Access on further APNs2-4
14. [Customer Issue] add the ACL "Trust Domain" and Activation of Maintenance WiFi per default
15. [Customer Issue] Manual band locking will result in device losing connectivity. Reboot will restore connectivity
16. [Customer Issue] Device fail to display in GUI and CLI

Modifications in 1.00(ABUV.8)b1

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Add TR-471 test item in Diagnostic page
2. Add new feature that can set different APN in in different SIM slots for Dual SIM.

[Fixed Defects]

1. [eITS Ticket # 220900182] Device.SoftwareModules.InstallDU() doesn't handle https and command-injection issue
2. [eITS Ticket # 221000453] NTP Client
3. [eITS Ticket # 221001636] USP: Map Bandwidth ID from driver to actual BW in MHz
4. [eITS Ticket # 221001646] USP: Unnecessary parameter RSSI
5. [eITS Ticket # 221001652] UDP: Add eNBID/siteid to datamodell
6. [eITS Ticket # 221100294] obuspa client restarts during
7. [eITS Ticket # 221101479] Set "Device.Cellular.X_ZYXEL_Refresh_Interval" to an empty value disconnects cellular WAN
8. [eITS Ticket # 221100532] USP: Issues with ExecutionUnit.{i}.SetRequestedState() and/or ExecutionUnit.{i}.Status
9. [eITS Ticket # 221200525] Add LAN-client OUI to data-model
10. [eITS Ticket # 221200526] Band numerical value
11. [Internal Issue #26006] UE CALL Trace and then go into "LTE_MODULE_HW_RESET" status loop cause UE connect fail
12. [Internal Issue #26483] UE continue reboot by itself for CALL TRACE
13. [Internal Issue #28638] The setting(MGMT Services and Trust Domain) of Remote Management can't be saved after we upload the backup configuration.
14. [Internal Issue #28750] Backup/Restore function doesn't include TR-369 configuration setting
15. [Customer’s Requirements] Change to New Certificate

Modifications in 1.00(ABUV.7)C0

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Change version from 1.00(ABUV.7)b3 to 1.00(ABUV.7)C0
2. [eITS Ticket #221100438] Change default config

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.7)b3

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. TR-471 feature
2. GUI MQTT version/Username/Password for MQTT client setting

[Fixed Defects]

1. [eITS Ticket # 220700325] Daily reboot schedule
2. [eITS Ticket # 220900180] Modify Device.Cellular.AccessPoint.{i}.Password to return the value of the password
3. [eITS Ticket # 220900182] Device.SoftwareModules.InstallDU() doesn't handle https
4. [eITS Ticket # 220900340] ztr69 fail to create socket
5. [eITS Ticket # 220900596] Device.SoftwareModules.InstallDU() is too slow installing
6. [eITS Ticket # 220900750] Continuous reconnect after upgrade
7. [eITS Ticket # 220901180] Add ztr69cli
8. [eITS Ticket # 220901239] APN password is visible in TR-369
9. [eITS Ticket # 220901343] Missing boot event
10. [eITS Ticket # 220901483] preferred access technology configuration change
11. [eITS Ticket # 220901484] cfg cellwan_band not available for admin
12. [eITS Ticket # 220901646] still shows incorrect 5G information
13. [eITS Ticket # 220901729] FW upgrade using FTP not working anymore
14. [eITS Ticket # 221000165] can't register to network in auto mode
15. [Vulnerability] Buffer overflow vulnerabilities and command injection vulnerability
16. [Internal Issue #29284] Delete MQTT client cause controller/agent reference fail
17. [Internal Issue #30989] IP will be blocked while upgrade FW
18. [Internal Issue #32434] Can't use CLI command to publish to a MQTT broker
19. [Internal Issue #32437] DeploymentUnit Uninstall() command can't uninstall all DUs at once and cause obuspa process crash/re-restart

Modifications in 1.00(ABUV.7)b2

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Disable TR369/Controller/MQTT in default setting

[Fixed Defects]

1. [eITS Ticket #220800861] TR-069 module upgrade uses a wrong APN to download module firmware
2. [eITS Ticket #220800984] add an APN to auto APN list
3. [eITS Ticket #220801033] No host under Device.Hosts.Host
4. [eITS Ticket #220801472] add DHCP-option in default config
5. [eITS Ticket #220900220] Change the selectable band list
6. [Customer Issue] support should not be able to log in via LAN
7. [Customer Issue] Service manipulation via request forging / user permissions.
8. [Customer Issue] ParentalControl - information in gray box is not removed.

Modifications in 1.00(ABUV.7)b1

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. New Web Guide for Cellular Infor page

[Fixed Defects]

1. [eITS Ticket #220600953] USP: Introduce more topics for Telemetry/BulkData data
2. [eITS Ticket #220700403] CLI command to publish to a MQTT broker
3. [eITS Ticket #220700404] Install and execute shell scripts on the CPE
4. [Internal Issue #24707] Duplicated VLAN ID will cause VLAN setting incorrect
5. [Internal Issue #25464] UE Host Name setting invalid
6. [Internal Issue #29125] WAN host/BSE can't ping DUT WAN IPv6 address successfully under IPPT mode.
7. [Internal Issue #29126] Change from IPPT to Router mode, ping from WAN host to DUT WAN IPv6 address can't work, reboot can recover.
8. [Internal Issue #29278] [TR-369] MQTT version 5.0 cause agent no bound interface found and connect fail
9. [Internal Iusse #30757] [TR-369] Modify manual APN setting by SET message cause connection abnormal and connection unstable
10. [Customer Issue] Part 3 / Service manipulation via request forging / user permissions are not verified
11. [Customer Issue] Part 8 / Extracting encrypted passwords (and potentially any othersensitive encrypted data)

12. [Customer Issue] HomeNetworking -> DNS Values -> From ISP = fields are empty
13. [Customer Issue] Change hashing function used in /etc/passwd from MD5 to SHA-512

Modifications in 1.00(ABUV.6)F3

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. [eITS Ticket #221100438] Change default config

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.6)G2

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. [eITS Ticket #220901483] preferred access technology configuration change

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.6)C1

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Disable TR369/MQTT in default setting
2. Remove the information of test broker

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.6)C0

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Change version from 1.00(ABUV.6)b5 to 1.00(ABUV.6)C0

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.6)b5

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

N/A

[Fixed Defects]

1. [eITS Ticket #220600177] Setting Device.ManagementServer.DelayReboot multiple times fails
2. [eITS Ticket #220600178] Device.BulkData.Profile.{i}.Parameter.{i} does not allow more than 8 entries
3. [eITS Ticket #220600517] use a parameter defined in TR-181 USP to enable/disable TR-369
4. [eITS Ticket #220600604] USP: SSL issues
5. [Internal Issue #28616]Agent inactive when execute Device.LocalAgent.Request.{i}.Cancel() command while there is not any request object be created.
6. [Internal Issue #28859] UE call trace and out_of_memory cause Agent USP service inactive while testing USP conformance test cases
7. [Internal Issue #29228] Under Single APN setting, NW Monitor malfunctions.
8. [Internal Issue #29733] MQTT (Device.MQTT.Client.1) publish payload content incomplete for cellular information
9. [Internal Issue #29832] Device.DeviceInfo.BootFirmwareImage value is empty
10. [Internal Issue #29861] LTE and 5G PCI Lock setting rules confusing users and cause device disconnects and Web UI page display errors
11. [Customer Issue] there are empty band values when using Manual band selection
12. [Customer Issue] remove description in gray box on top of the CellWanStatus page
13. [Customer Issue] filed are empty in System page
14. [Customer Issue] there are error message “The request was forbidden” in RM, NAT and ParentalControl page

15. [Customer Issue] remove the EmailNotFication page
16. [Customer Issue] When NAT is disabled and public subnet is configured to LAN, then WEB GUI becomes accessible via WAN even-though remote access is disabled
17. [Customer Issue] increase DHCP pool
18. [220300515] OPAL DEVICE SECURITY: Part 7 / Rooting device via shell command injection

Modifications in 1.00(ABUV.6)b4

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Update openssl to 1.1.1n
2. Refine WiFi popup setting of cardpage

[Fixed Defects]

1. [eITS Ticket #220500142] NR7101 MQTT-client can't connect to Coustomer's MQTT broker
2. [eITS Ticket #220500349] NR7101 How to configure USP+mqtt with client-certificates
3. [eITS Ticket #220500850] NR7101 USP: Device.DeviceInfo.FirmwareImage.{i}.Download() doesn't handle booleans correctly
4. [# N/A] NR7101: wrong firmware version in TR-069, web GUI and "sys atsh" after downgrading from 6b3_D0 to 4b3_D0 or 5D0
5. [eITS Ticket #220500961] Release ABUV.6bx_D1
6. [Internal Issue #28615] Bound Interface function doesn't work with Cellular WAN2/3/4
7. [Internal Issue #28618] There is not value of output_args IPAddressUsed for TraceRoute() OperationComplete NOTIFY
8. [Internal Issue #28620] Even FW Download() have done successfully, but OperationComplete Notify still report error code: 7022.
9. [Internal Issue #28622] [TR-369] OperationComplete NOTIFY of output_args for DownloadDiagnostics() is different with SUPPORTED_DM and usp-data-models (tr-181-2.15)
10. [Internal Issue #28623] OperationComplete NOTIFY of output_args for UploadDiagnostics() is different with SUPPORTED_DM
11. [Internal Issue #28626] There is not value of output_args IPAddressUsed for IPPing() OperationComplete NOTIFY
12. [Internal Issue #28627] Certificates Trusted CA webGUI display overlap between Subject and Type content

13. [Internal Issue #29254] FW downgrade cause FW version displayed and activate FW image incorrect
14. [Internal Issue #29273] MQTT (Device.MQTT.Client.1) can't be activated with _D0 FW
15. [Internal Issue #29275] Local Agent function invalid with Generic FW
16. [Internal Issue #29279] SecondaryComponentCarrier table only support 3 instances
17. [Internal Issue #29281] Notify Event(Device.BulkData) overnight test cause out of memory
18. [Internal Issue #29282] Device.DeviceInfo.ActiveFirmwareImage data schema does not exist
19. [220300504] OPAL DEVICE SECURITY: Part 2 / Privilege escalation using request forging and enabling "hidden" pages
20. [220300509] OPAL DEVICE SECURITY: Part 3 / Service manipulation via request forging / user permissions are not verified
21. [220300511] OPAL DEVICE SECURITY: Part 5 / Firmware downgrade prevention is trivial to bypass
22. [220300512] OPAL DEVICE SECURITY: Part 6 / Uploaded firmware image is not cryptographically signed nor verified
23. [220300515] OPAL DEVICE SECURITY: Part 7 / Rooting device via shell command injection
24. [220300516] OPAL DEVICE SECURITY: Part 8 / Extracting encrypted passwords (and potentially any other sensitive encrypted data)

Modifications in 1.00(ABUV.6)b3

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Writing Zyxel's IMEI to a back partition after FW upgrade

[Fixed Defects]

1. [eITS Ticket #220300336] NR7101 Timeout in Device.IP.Diagnostics.IPPing() command uses wrong magnitude
2. [eITS Ticket #220301265] NR7101 Change dual-bank setup
3. [eITS Ticket #220301861] NR7101 USP Telemetry missing: temperature
4. [eITS Ticket #220301862] NR7101 USP Missing Telemetry: mcs, ri, cqi and pmi
5. [eITS Ticket #220301863] NR7101 USP Telemetry missing: NR mcs, mod_type, RB_start, numRBs and TB_size
6. [eITS Ticket #220301864] NR7101 USP Telemetry missing: CA state
7. [eITS Ticket #220301865] NR7101 USP Telemetry sysinfo: eth1 linkrate
8. [eITS Ticket #220301866] NR7101 USP Telemetry sysinfo: Packet counters

9. [eITS Ticket #220301868] NR7101 USP Telemetry sysinfo: Load and proccess count
10. [eITS Ticket #220301869] NR7101 USP Telemetry sysinfo: Memory info
11. [eITS Ticket #220301870] NR7101 USP Telemetry sysinfo: IP contrack
12. [eITS Ticket #220400430] NR7101 Wrong parameter-values in data-model when Cisco-client connected
13. [eITS Ticket #220400804] No LTE/5G connection with APN from Orange in Romania
14. [Internal Issue #28611] Specify HTTPS URL cause cleartext storage of sensitive information (TR-069 password) vulnerability security issue
15. [Internal Issue #28614] Notify msg sending fail after UE re-attach successfully
16. [Internal Issue #28615] Bound Interface function doesn't work with Cellular WAN2/3/4
17. [Internal Issue #28619] Disable and Enable TR-369 Local Agent will cause Agent sent Boot! Event
18. [Internal Issue #28624] There is an extra Spusu imsi into suggest to remove from Auto APN list
19. [Internal Issue #28644] Module FW upgrade for object Device.DeviceInfo.FirmwareImage.{i}.Download() not yet implemented

Modifications in 1.00(ABUV.6)b2

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. [TR369] GUI option: Bound Interface.
2. [TR369] Performance enhancement with Get Device
3. [TR369] Device.LocalAgent.AddCertificate()
4. [TR369] Device.LocalAgent.Certificate.{i}.Delete()
5. [TR369] Device.LocalAgent.Request.{i}.Cancel()
6. [TR369] Device.LocalAgent.Controller.{i}.AddMyCertificate()
7. [TR369] Device.DeviceInfo.VendorLogFile.{i}.Upload()
8. [TR369] Device.DeviceInfo.VendorConfigFile.{i}.Backup()
9. [TR369] Device.IP.Diagnostics.TraceRoute()
10. [TR369] Event - Device.LocalAgent.TransferComplete
11. [TR369] Notification - OperationComplete
12. [TR369] Notification – ValueChange
13. [TR369] Device.IP.Diagnostics.UploadDiagnostics()
14. [TR369] Device.IP.Diagnostics.DownloadDiagnostics()
15. Add the related information of Spusu into Auto APN list

[Fixed Defects]

1. [eITS Ticket #211200708] Throughput Performance Test Results
2. [eITS Ticket #220100453] NR7101 / Plan to support Dual SIM card
3. [eITS Ticket #220101639] zyxel.localhost domain usage lead to unpredictable results in name resolution
4. [eITS Ticket #220101641] Partions are not formatted after factory reset
5. [eITS Ticket #220101644] Semi-bridge routing is present when device is used in router mode
6. [eITS Ticket #220200643] admin privileges for cfg command
7. [eITS Ticket #220200951] B2B default configuration changes
8. [eITS Ticket #220201308] Problem with option 67 in dnsmasq
9. [eITS Ticket #220201362] adding "" in custom DHCP option's config file will make IP address becomes string
10. [eITS Ticket #220300222] Parental control page
11. [eITS Ticket #220300334] Adding an instance for Device.BulkData.Profile fails
12. [eITS Ticket #220300337] IPPing() command does not work
13. [eITS Ticket #220300338] NR7101 Configuration for MQTT and USP client
14. [eITS Ticket #220300339] Firmware upgrade over TR-369 not implemented
15. [External Issue] NR7101's APN2 traffic cannot go out (APN1 is okay)
16. [Internal Issue #28012] TR-369 asynchronous operations cancel cause CALL TRACE.
17. [Internal Issue #28013] MQTT Client Force ReConnect function button can't be enabled.
18. [Internal Issue #28014] UE(Agent) can't add multiple controllers by webGUI.
19. [Internal Issue #28016] Cellular WAN Status refresh interval not really refer to Device.Cellular.X_ZYXEL_Refresh_Interval.

Modifications in 1.00(ABUV.6)b1

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Add TR369 feature
2. Add TR98 parameters for APN
   ⇨ Username / Password/ X_ZYXEL_AuthenticationType/ X_ZYXEL_PDP_Type
3. Use the at command " AT+COPS" to replace " AT+CGATT" do detach/attach

[Fixed Defects]

1. [eITS Ticket #200800824] FIXIP & Public Subnet Support
2. [eITS Ticket # 210200352] TR-069 is enabled by default and it cannot be disabled without filling in the ACS URL
3. [eITS Ticket #211201244] NR7101 Update-interval from module to OPAL

- ⇨ "Device.Cellular.X_ZYXEL_Refresh_Interval"

4. [Internal Issue#24723] User traffic will be blocked after Change Bridge 1 interface LAN IP with router mode
5. [Internal Issue#27320] Connection recover mechanism fail will cause UE lost control from Ether LAN client.
6. [Internal Issue#27321] There is chance cause CM(rilcmd) enter exception loop situation while connection recover mechanism

Modifications in 1.00(ABUV.5)C0

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Change version from 1.00(ABUV.5)b2 to 1.00(ABUV.5)C0

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.5)b2

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Add the solution of Slow webpage loading on NR5101
2. Add the parameter that can disable or enable the feature “save in the log all AT commands that CM executed and their responses”
   - ⇨ Device.X_ZYXEL_Log_Setting.AT_LOG_Enable for TR181
   - ⇨ InternetGatewayDevice.X_ZYXEL_EXT.Log_Setting.AT_LOG_Enable for TR98

[Fixed Defects]

1. [Internal Issue #22432] Neighbour Cells still displayed previous information on webGUI (Cellular WAN Status) after user disabled Neighbour Cells by TR69
2. [Internal Issue #24257] There is not any neighbor cell information when UE connect to ENDC mode and 5G cell activate
3. [Internal Issue #24771] Network Monitor enhancement fail on APN2 and APN4
4. [Internal Issue #25479] CM will not activate re-cover mechanism while call_end_reason_verbose is 2509

5. [Internal Issue #26010] UE APN2 connection fail after continuous FW upgrade by TR-069
6. [Internal Issue] BandSelection in Web Guide issue
7. [eITS Ticket # 211100043] Logging to syslog on module events of “Device in roaming state but not enable the function” case still failed.
8. [eITS Ticket #211100730] support for standard TR-181 v2.10 parameter - Device.ManagementServer.DelayReboot
9. [eITS Ticket #211001335] Add custom DHCP-options for IPPassthrough APN's

Modifications in 1.00(ABUV.5)b1

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Add TDC information into Auto APN list

[Fixed Defects]

1. [eITS Ticket #211001072] IP conflicts in the network
2. [eITS Ticket #211001329] increase syslog’s size to 1024K
3. [eITS Ticket # 211100043] Logging to syslog on module events

Module reboot

Case 1: When module can’t be detected, try to reboot module.

“module try on/off radio action”

“Reset LTE module because of opening tty device failed”

Case 2: When transmission timeout, try to reboot module.

“Reset LTE module because of timeout flag is 1”

Case 3: After set NR cell lock, need to reboot module to apply changed.

“Reboot LTE module because of setting NR cell lock”

Module Reattach

Case 1: User change cell band setting, profile setting, select network manually

“send_sig_command head bandchange”

“send_sig_command head apnConfig”

“send_sig_command head selectopauto”

Case 2: When detect some call end reason

“cid: x call end reason: xxxx”

Case 3: When detect network un-registration

“CEVENT_WAN_PHYSICAL_LINK_DOWN”

Case 4: When detect IP changed

"ip address change from XXX to XXY"

Case 5: Connect to roaming cell but user disable roaming function

"Device in roaming state but not enable the function"

4. [eITS Ticket #211101246] NR7101 Change MTU to 1500
5. [eITS Ticket #211101254] TR-181 parameters to change MTU on br0 and br1
   - ⇨ Device.Ethernet.Interface.1.X_ZYXEL_Jumbo_Frame

Modifications in 1.00(ABUV.4)C0

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Change version from 1.00(ABUV.4)b3 to 1.00(ABUV.4)C0

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.4)b3

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

N/A

[Fixed Defects]

1. [Internal Issue #24726] 4G PCI lock function invalid and setting can't apply
2. [Internal Issue #24729] Please optimization the description and setting flow of 4G/5G PCI lock function of Cellular Lock page
3. [Internal Issue #25478] 4G PCI lock setting will disappear on webGUI once user leave the setting page
4. [Internal Issue #25480] TR-069 FW upgrade fail due to Wrong image checksum
5. [Internal Issue #25490] nslookup function is invalid in Diagnostic
6. [Customer Issue] NR7101 ethernet links flaps

Modifications in 1.00(ABUV.4)b2

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Add Boot on Scan feature for QSCAN feature
2. DHCP option 60/43 for Customer's requirement

[Fixed Defects]

1. [Internal Issue #20762] WebGUI will stucked oftenly after doing some setting in web, and popup warning message
2. [Internal Issue #22432] Neighbour Cells still displayed previous information on webGUI (Cellular WAN Status) after user disabled Neighbour Cells by TR69
3. [Internal Issue #22512] There is not LTE CQI/MCS/RI information displayed of service information with ENDC mode when UE out of 5G service
4. [Internal Issue #24710] Customer issue: UL CA performance poor with QoS enabled default setting
5. [Internal Issue #24712] SCAN button invalid on Cellular Lock page
6. [Internal Issue #24724] Customer issue: zcfg message delivered not successful cause UE reboot frequently
7. [Internal Issue #24725] Word spelling incorrect for "Waiting SIM avaiable"
8. [Internal Issue #24726] 4G PCI lock function invalid and setting can't apply
9. [Internal Issue #24728] Enabled 5G PCI lock function will re-start again once user enter Cellular Lock page on webGUI
10. [Internal Issue #24729] Please optimization the description and setting flow of 4G/5G PCI lock function of Cellular Lock page
11. [Customer Issue] MPLS - failed transport of fragmented packets

Modifications in 1.00(ABUV.4)b1

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Disable 3G by Web Guide/TR069
2. Implement new mechanism of FQ_Codel
3. Add QSCAN new feature
4. Update openssl version to 1.1.1b

[Fixed Defects]

1. [Internal Issue #21405] PCI lock function should include NR-5G cell
2. [Internal Issue #24252] User can't enable neighbor cell display function with Customer's config ROM-D
3. [Internal Issue #24350] Network Monitor enhancement fail on APN1
4. [eITS Ticket #210401094] NR7101: when IP passthrough client's OUI is a specific string, the client receives a WAN IP address but cannot access the Internet

5. [eITS Ticket #210601566] NR7101 nuttcp download fails

Modifications in 1.00(ABUV.3)C0

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Change version from 1.00(ABUV.3)b6 to 1.00(ABUV.3)C0

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.3)b6

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Add PCI Lock for NR-5G
2. Network Monitor for each APN

[Fixed Defects]

1. MTK WiFi Frag Defrag attack
2. [Internal Issue #20716] GUI wording overlapped
3. [Internal Issue #20745] Web-GUI typo issue, NR7101 did not support 2G/3G but Prompt display related words
4. [Internal Issue #20749] Web-GUI will make user logout immediately while user perform the configuration changing between IPPT and router mode of each PDN(APN)
5. [Internal Issue #20762] WebGUI will stucked oftenly after doing some setting in web, and popup warning message "It is impossible to retrieve the information now. Please try again".
6. [Internal Issue #22452] Change default GW and APN disable/enable may cause APN system info(DNS/IPv6 addr.) incorrect on webGUI
7. [Internal Issue #22479] There isn't any LTE SCC band information when the RAT is ENDC mode with CA condition
8. [Internal Issue #22509] System info content didn't adjusts to suitable Web frame of IE/Firefox browser
9. [Internal Issue #22514] DHCP lease not found when multiple VLAN clients with same MAC address from LAN side

10. [Internal Issue #23523] There isn't limitation to set how many character of user password.
11. [Internal Issue #23631] Customer issue: UE CALL TRACE and reboot approx. every 2 hours
12. [eITS Ticket #210601408] NR7101 APN with PDP-type IPv4/IPv6 doesn't work
13. [eITS Ticket #210601409] NR7101 Problem with iptables blocking GUI-access
    - ⇨ We temporarily remove these two rules
    - ⇨ "iptables -I INPUT 1 -p tcp --syn --dport 80 -m connlimit --connlimit-above 5 -j REJECT --reject-with tcp-reset”
    - ⇨ "iptables -I INPUT 1 -p tcp --syn --dport 443 -m connlimit --connlimit-above 5 -j REJECT --reject-with tcp-reset”

Modifications in 1.00(ABUV.3)b5

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. Add the feature that handle the module does not reply any ATC request
2. add module reset when tx time out

[Fixed Defects]

1. [Internal Issue #20716] GUI wording overlapped
2. [Internal Issue #20729] LED status fail after APN2 / APN3 / APN4 disabled
3. [Internal Issue #20733] PLMN SCAN result of OP name display not complete (be limited 8 charecters)
4. [Internal Issue #20735] Modify Router mode RM port will cause IPPT RM service access connection refused
5. [Internal Issue #21403] UPnP log repeated a lots of records once enable UPnP function
6. [Internal Issue #22432] Neighbour Cells still displayed previous information on webGUI (Cellular WAN Status) after user disabled Neighbour Cells by TR69
7. [Internal Issue #22434] Operator name display incorrect with chunghwa commercial 5G SIM card
8. [Internal Issue #22525] Supervisor can't restore UE configuration saved by admin user
9. [Internal Issue #22753] 4th PDN (APN)'s IPv6 DNS information display NA in system info page
10. [Internal Issue #22788] Trust domain behavior is not match to function description on webGUI
11. [Internal Issue #22843] PLMN manual selection for LTE should not force RAT type to 4G(LTE)
12. [Internal Issue #23175] LED behavior incorrect while FW upgrade

13. [Internal Issue #23193] There isn't limitation to set how many character of user password

Modifications in 1.00(ABUV.3)b4

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails

[Feature Enhancement/Configuration Changing]

1. [eITs Ticket #210500314] Feature request: Include GenXML

[Fixed Defects]

1. [eITs Ticket #210500402] 3b2_D0 all LAN traffic goes to wwan1
2. [Internal Issue# #22513] LED behavior incorrect after user unlock PIN/PUK code and connect to internet

Modifications in 1.00(ABUV.3)b3

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails
2. The TR-069 bound interfaces can’t work until reboot

[Feature Enhancement/Configuration Changing]

1. Remove NR_N79 support in Band Selection page
2. Add module reset while tx timeout happened
3. Add support band selection for RG502Q

[Fixed Defects]

1. [Internal Issue] Fix remote management cannot work in IPPT mode in 3b2

Modifications in 1.00(ABUV.3)b2

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails
2. The TR-069 bound interfaces can’t work until reboot

[Feature Enhancement/Configuration Changing]

1. [eITs Ticket #210401346] disable supervisor account in Coustomer configuration
2. [eITS Ticket #210401124] Change system start-time to compile-date
3. add feature to support 5G Band Selection

4. if the value in NR-RSRP/NR-RSRQ is invalid, the they will show N/A in CLI command

[Fixed Defects]

1. [Internal Issue#20763/Internal Issue#22761] IPPT mode br interface IPv4v6 incorrect while APN3 and APN4 change mode from router mode to IPPT mode
2. [Internal Issue #20737] CM process (rilcmd) be killed automatically with UDP traffic of overnight stress test
3. [eITS Ticket #210400535/Internal Issue#22589] Upstream traffic from the NR7101 stops
4. [eITS Ticket #210400870] Management is lost (SSH/TR69/WEB)

Modifications in 1.00(ABUV.3)b1

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fails
2. The TR-069 bound interfaces can't work until reboot

[Feature Enhancement/Configuration Changing]

1. DNSMASQ update to 2.78 to fix Volnerabilities issues
2. Add Service Domain selection
   ⇨ Device.Cellular.Interface.1.PreferredServiceDomain
3. Add Jumbo Frame(MTU Size 2000)

[Fixed Defects]

1. [Internal Issue# 20720] RAT display (cellular info) incorrect on webGUI
2. [Internal Issue# 20726] APN name manual setting issue.
3. [Internal Issue# 20727] Multiple APNs connection establish process not stable on APN3/4
4. [Internal Issue# 20728] TR69 connection fail with IPPT mode if Multi_WAN APN1 / APN2 / APN3 / APN4 Used by TR-069 Client Function works well after reboot UE
5. [Internal Issue# 20731] IPv6 TCP DL performance is more half less than IPv4 performance
6. [Internal Issue# 20737] CM process (rilcmd) be killed automatically with UDP traffic of overnight stress test
7. [Internal Issue# 20741] LED indicator behavior abnormal while SIM card detecting fail
8. [Internal Issue# 20742] There is risk for module upgrade procedure, it will let UE lost connection and control, need to reboot to recover it
9. [Internal Issue# 20743] IPv6 service offering be blocked while device set as router mode
10. [Internal Issue# 20751] Firmware FW should be V1.00(ABUV.x)xx in system info display

11. [Internal Issue# 20757] IPv6 Remote management service access port number works both route mode port and IPPT mode port
12. [Internal Issue# 20758] It cause system CALL TRACE and reboot oftenly when user is remote management UE by IPv6 access
13. [Internal Issue# 20759] IPv6 Remote management service can't be bounded to any cellular interface
14. [Internal Issue# 20943] It cause system CALL TRACE and reboot often when user is remote management UE by IPv6 access
15. [Internal Issue# 21401] UE should provide exception handling mechanism for DFOTA upgrade module version by TR-69 and webGUI
16. [Internal Issue# 21962] The end user can't get the IPv6 address of each PDN.
17. [eITs Ticket# 210300082] Wrong source-IP when using static route
18. [eITs Ticket# 210100935] Add new parameters of TR69 to enabled/disabled CDRX
    ⇨ Device.Cellular.Interface.1.X_ZYXEL_CDRX_Enable
19. [eITs Ticket# 200801594] Add new parameters of TR69 to enable/disable Neighbourcell feature
    ⇨ Device.Cellular.X_ZYXEL_NBR.Enable

Modifications in 1.00(ABUV.2)C0

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. The TR-069 bound interface can’t work until reboot

[Feature Enhancement/Configuration Changing]

1. Change version from 1.00(ABUV.2)b5 to 1.00(ABUV.2)C0

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.2)b5

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. The TR-069 bound interface can’t work until reboot

[Feature Enhancement/Configuration Changing]

1. Disable neighbourcell feature

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.2)b4

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. The TR-069 bound interface can't work until reboot

[Feature Enhancement/Configuration Changing]

1. integrate encrypted function in the command "sys atprivkey"
2. add new parameters of TR-69 to get SubEdition version of module
   ➔ Device.Cellular.Interface.1.X_ZYXEL_ModuleSoftwareSubVersion

[Fixed Defects]

1. [Internal Issue#20732] PCI lock function invalid while change SIM card and first reboot
2. [Internal Issue#20739] reboot may cause WAN dhcp issue and WAN connection fail
3. [Internal Issue#20752] NR5G-SA cellular information incorrect of RFCN and cellID display on webGUI
4. [Internal Issue#20753] NR5G-SA signal strength and Cellular WAN signal quality display abnormal in home page
5. [Internal Issue#20761] UE traffic will be blocked when default GW is Celluar WAN1 and APN1 is IPPT mode, APN2 is router mode
6. [Internal Issue#20764] PCI lock fail after UE reboot
7. [Internal Issue# 20848] There is not NR band information displayed on 5G NR-NSA information
8. [eITS Ticket #201001067]- NR7101 Add TR-69 Client events to syslog
   ➔ Add "Syslog Debug Logging" in Log Setting web page for tr-069 syslog
9. [eITs Ticket # 201001360] NR7101 LAN-side client doesn't regain Internet-connection after resetting module
10. [eITs Ticket #201001419] Request an AT-command to read 5G band
11. [eITs Ticket #201001420] NR7101 AT-command to read 5G earfcn
12. [eITs Ticket #201101271] NR7101 ABUV.2b3 + R01A04 doesn't work
13. [eITs Ticket #201200123] NR7101 How to configure Wi-Fi Auto-off
    ➔ Device.WiFi.Radio.1.X_ZYXEL_Radio_Pwrsave_Enable //enable or disable this function
    ➔ Device.WiFi.Radio.1.X_ZYXEL_Radio_Pwrsave_Quiet_Time //set the time to closed wifi WIFI

Modifications in 1.00(ABUV.2)b3

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. The TR-069 bound interface can't work until reboot

[Feature Enhancement/Configuration Changing]

1. Add the information of SA mode
2. Only NR5G setting in Web Guide

[Fixed Defects]

1. [**blackcatinfo**] HSTS Missing From HTTPS Server
2. **[Internal Issue#95]** UE call trace when user disabled 2nd APN first time after reboot.
3. **[Internal Issue#105]** VLAN ID colum always display NA in APN page
4. **[Internal Issue#106]** VLAN group settinginvalid while user add duplicate VLAN condition and delete the old one
5. **[Internal Issue#109]** IP Passthrough mode invalid with fix MAC address.
6. Traffic cannot go out while change mode from router mode to IPPT mode
7. Add logs when ethernet lan cable is down/up, duplex mode and speed.
8. Adding default route may fail if Cellular WAN is ip passthrough mode.
9. LAN pc would not get ip address even if Cellular WAN 1 is connected to LTE network
10. Norway [#201001353] NR7101 Connection Request available on APN1 even if TR-69 is bound to APN2 (Connection Request available on APN1 even if TR69 is bound to APN2 (no wwan0 iptables 7547 rule)
11. wwan0 will not appear as default gateway when APN 1 is connected to LTE network.
12. There should be no -j MASQUERADE for wwan0 in ip passthrough mode.

Modifications in 1.00(ABUV.2)b2

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. The TR-069 bound interface can't work until reboot

[Feature Enhancement/Configuration Changing]

1. Support IPv6 Remote MGMT on multi APN.
2. Support IPv6 NTPClient.
3. Show each APN connection time.
4. Show GNSS information on cellular info page.
5. Show neighbor cell information on cellular wan status page.
6. Disable 3G.
7. Add MQTT-Client/ TR-69 Client/cellular/ LAN-port/ events to syslog
8. Force search and attach to base station
9. Add conntrack-tools

[Fixed Defects]

1. [internal] Connection Request available on APN1 even if TR-69 is bound to APN2

Modifications in 1.00(ABUV.1)b2

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. The TR-069 bound interface can't work until reboot

[Feature Enhancement/Configuration Changing]

1. Support Multiple APN and VLAN
2. Support all Customer existing features
3. Support SA mode(SA mode test should be with specific module fw: RG502QEAAAR11A01M4G_BETA_20200917A)
4. Data model spec change to TR-098 : "X_ZYXEL_DataModelSpec":"TR-098".
5. Enlarge cellular lock number from 2 to 5
6. Modify apnlist buffer from 128 to 512
7. Merge OPAL VlanGroup in WebGUI feature
8. Add TR-098 mapping parameter for APN
9. Enable LOGIN ACCOUNT flag to let account can be edit with tr098
10. Add pbit upstream QoS
11. If there is no corresponding interface grouping, Cellular WAN could not switch to ip passthrough mode
12. Add interface grouping setting page to shown with admin account
13. Remove "Retype Login Password to Confirm The Change" feature in WebGUI.

[Fixed Defects]

1. Merge all Customer "fixed" bugs.
2. If DHCPv4 Server is disabled, lan pc would not get ip address even after LTE is connected when WAN in ip passthrough mode.

Modifications in 1.00(ABUV.1)b1

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. **[Internal Issue#51]** NR5G isn't work

[Feature Enhancement/Configuration Changing]

1. **[eITS Ticket #200800832]** NR7101 Compile iperf3

[Fixed Defects]

1. **[eITS Ticket #200900052]** NR7101 Device.DeviceInfo.ProvisioningCode in inform events is not

updated

2. **[eITS Ticket #200801567]** NR7101 BOOTSTRAP received when Device.X_ZYXEL_EXT.BootFromFactoryDefault = 0
3. **[eITS Ticket #200801573]** NR7101 BOOT received when Device.X_ZYXEL_EXT.BootFromFactoryDefault = 1
4. GPS of tr069 can't work

Modifications in 1.00(ABUV.0)C0

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. **[Internal Issue#51]** NR5G isn't work

[Feature Enhancement/Configuration Changing]

1. Change version from 1.00(ABUV.0)b12 to 1.00(ABUV.0)C0

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.0)b12

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. **[Internal Issue#51]** NR5G isn't work

[Feature Enhancement/Configuration Changing]

[Fixed Defects]

1. **[issue #94]** Modify 1st APN config. (ex: APN name) will cause 2nd APN attach failed

Modifications in 1.00(ABUV.0)b11

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. **[Internal Issue#51]** NR5G isn't work

[Feature Enhancement/Configuration Changing]

[Fixed Defects]

1. **[issue #94]** Modify 1st APN config. (ex: APN name) will cause 2nd APN attach failed

2. **[issue #90]** Static Route add function fail to WAN1 interface when APN1 is IPPT mode

Modifications in 1.00(ABUV.0)b10

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. **[Internal Issue#51]** NR5G isn't work

[Feature Enhancement/Configuration Changing]

[Fixed Defects]

1. **[issue #89] IPPT client can't access internet while using APN2 as default GW**
2. **[issue #91] TR069 connection request will fail if TR-069 WAN Interface set to Cellular WAN 2**

Modifications in 1.00(ABUV.0)b9

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. **[Internal Issue#51]** NR5G isn't work

[Feature Enhancement/Configuration Changing]

1. Change DDR speed to 1200 MHz in u-boot
2. [eITS Ticket #200603490] Boot from factory default config

[Fixed Defects]

1. **[eITS Ticket #200800130]** NR7101 Wrong default gateway used

Modifications in 1.00(ABUV.0)b8

Note this version is based on 1.00(ABUV.0)b6

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. **[Internal Issue#51]** NR5G isn't work

[Feature Enhancement/Configuration Changing]

1. Remove Vlan function
2. Remove "RETYPE_LOGIN_PASSWORD_BEFORE_APPLY" function

3. Disable auto wifi off function.
4. Disable MBN configuration of module when upgrading module fw by TR069
5. Add new linux command “diff”
6. Add new CLI command “sys atb64encode” and “sys atb64decode”
   For example:

```
root@NR7101:~# sys atb64encode 1234
The output is:
MTIzNA==
root@NR7101:~# sys atb64decode MTIzNA==
The output is:
1234
```

[Fixed Defects]

1. **[Internal Issue#63]** After module upgrade by Qfirehose (from A01 to A02), UE can't connect to WAN.
2. **[Internal Issue#64]** DDNS could not active after CPE reboot
3. **[Internal Issue#65]** WebGUI display PIN Protection - PUK status incorrect after reboot device
4. **[Internal Issue#66]** LTE attach fail with Auto RAT setting and LTE only environment
5. **[Internal Issue#69]** WebGUI add account will cause UE crash
6. SIM cards cannot be detected on LTE routers
7. Display the right mode for each APN in system info page

Modifications in 1.00(ABUV.0)b7

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. **[Internal Issue#51]** NR5G isn’t work

[Feature Enhancement/Configuration Changing]

1. Module FW upgrade by Qfirehose via TR-69
2. Vlan function enable.
3. Multiple apn from 2 to 4.
4. Every vlan support ippt/router mode switch.
5. Disable auto wifi off function.

[Fixed Defects]

Modifications in 1.00(ABUV.0)b6

[Know defects]

1. **[Internal Issue#43]** DHCPv6 relay function fail
2. **[Internal Issue#51]** NR5G isn't work
3. **[Internal Issue#53]** 2nd APN attach fail with ENDC mode

[Feature Enhancement/Configuration Changing]

1. Add the mechanism that uses QFirehose to upgrade the FW of Module through TR069.

[Fixed Defects]

1. **[Internal Issue#18]** GUI allow user to apply blank value of APN1/2 name. And simulator only connects one PDN.
2. **[Internal Issue#25]** SIM PIN save mechanism can't be reset after reset UE by webGUI
3. **[Internal Issue#31]** RAT display (cellular info) incorrect on webGUI
4. **[Internal Issue#33]** There are no CQI / MCS / RI value and NR information display on 5G NR-NSA information
5. **[Internal Issue#34]** Cellular information display incorrect when UE disconnect internet.
6. **[Internal Issue#45]** PIN code setting issue in SIM slot 2.Entering the wrong PIN code, the attempts remaining won't be reduced in SIM slot 2.
7. **[Internal Issue#46]** Reduce the UE RSRP and let it connection down After 10 mins, let UE back to good RSRP environment, but UE can't re-connect to WAN
8. **[Internal Issue#47]** Roaming function fail No matter enable or disable the roaming, the UE data traffic always could transmit to internet
9. **[Internal Issue#48]** Cellular status displays incorrect while connection down Let simulator BTS out of service, but UE cellular status display UP and still keep previous connection information, LED also display solid green.
10. **[Internal Issue#54]** 2nd APN attach successfully with LTE mode, but can't be disabled or modify

Modifications in 1.00(ABUV.0)b5

[Know defects]

1. [Internal Issue#43] DHCPv6 relay function fail

[Feature Enhancement/Configuration Changing]

1. Add CLI command of GPS
2. Add PCI Lock feature

[Fixed Defects]

1. [**Internal Issue#4**] Device log support Band is [275] Device_Support_Bands: LTE_BC1,LTE_BC3,LTE_BC5,LTE_BC7,LTE_BC8,LTE_BC20,LTE_BC28,LTE_BC38,LTE_BC40,LTE_BC41, it's different from the UE capacity information of simulator information. (1,3,5,7,8,18,19,20,26,28,32,34,38,39,40,41,42,66,71)
2. **[Internal Issue#33]** There are no CQI / MCS / RI value and NR information display on 5G NR-NSA information
3. **[Internal Issue#36]** UE can't attach LTE network with good signal condition in chance.
4. **[Internal Issue#37]** Preferred Access Technology function invalid on Cellular Band page User cannot specify RAT options in 3G/4G/Auto/NR-NSA
5. **[Internal Issue#38]** Band Selection function invalid on Cellular Band page User cannot specify connected LTE Band within UE capability
6. **[Internal Issue#41]** MAC filter function fail on wireless connections

Modifications in 1.00(ABUV.0)b4

[Know defects]

N/A

[Feature Enhancement/Configuration Changing]

N/A

[Fixed Defects]

1. [**Internal Issue#7**] CHAP to PAP/CHAP Authentication Type issue.
2. [**Internal Issue#16**] PING function selection issue.
3. [**Internal Issue#19**] WAN cannot PING APN2 IP address
4. It happened the crash when using iperf3 tool to test UDP-packets

Modifications in 1.00(ABUV.0)b3

[Know defects]

1. It happened the crash when using iperf3 tool to test UDP-packets

[Feature Enhancement/Configuration Changing]

1. Add the parameters X_ZYXEL_Delay_Baseline , X_ZYXEL_Latency_Diff and X_ZYXEL_Latency_Limit for FQ_CODEL setting
2. When TLS is set we include the –cafile option when starting mosquitto_pub
3. Use the mechanism “31K buffer + reduce 50% memory copy” to enhance downlink throughput

[Fixed Defects]

N/A

Modifications in 1.00(ABUV.0)b2

[Know defects]

1. RM service enable / disable cannot take effect immediately after setting

[Feature Enhancement/Configuration Changing]

1. MQTT support openssl-1.1.1
2. Add Security protect for Broken access control
3. MQTT will not cause TCP Connect and Disconnect for every Publish

[Fixed Defects]

2nd APN connection is unstable

Modifications in 1.00(ABUV.0)b1

First release

Public Domain Software Announcements

Open Source Used in product (3rd party software)	Version	From (Source)	Licensing Term	Modified / Used
atftp	0.7.1	http://sourceforge.net/projects/atftp/	GPLv2	Used
BusyBox	1.20.1	http://www.busybox.net/	GPL	Modified
c-ares	1.14.0	https://c-ares.haxx.se/	MIT	Used
clinkc	2.4	http://sourceforge.net/projects/clinkc/	BSD	Modified
conntrack-tools	1.4.3	http://conntrack-tools.netfilter.org/	GPLv2	Used
curl	7.29.0	http://www.mirrorspace.org/curl/	GPL/LGPL	Used
dnsmasq	2.67	http://www.thekelleys.org.uk/dnsmasq/doc.html	GPLv2/GPLv3	Modified
dropbear	2018.76	http://matt.ucc.asn.au/dropbear/releases/	MIT	Modified
ebtables	2.0.10	http://ebtables.sourceforge.net	GPL	Modified
eventlog	0.2.10	https://my.balabit.com/downloads/eventlog/0.2/	BSD	Used
expat	1.95.8	https://libexpat.github.io/	MIT	Used
ez-ipupdate	3.0.11b8	https://sourceforge.net/p/ez-ipupdate/	GPLv2	Used
gettext	0.16	http://www.gnu.org/software/gettext/	GPLv2	Used
glib	2.37.7	https://wiki.gnome.org/Projects/Glib	LGPLv2	Used
iproute2	3.15.0	http://repository.timesys.com/buildsources/i/iproute2/	GPL	Modified
iperf	3.7	https://software.es.net/iperf/	GPL	Used
jpeg	9a	http://www.faqs.org/faqs/jpeg-faq/	GPL	Used
json-c	0.9	https://github.com/json-c/json-c/downloads	MIT	Modified
libedit	20080712-2.11	https://thrysoee.dk/editline/	BSD	Modified
libffi	3.0.11	https://sourceware.org/libffi/	MIT	Used
libiconv	1.11.1	http://www.gnu.org/software/libiconv/	LGPLv2	Modified
libmnl	1.0.3	http://netfilter.org/projects/libmnl/	GPLv2	Used
libnetfilter_conntrack	1.0.4	http://netfilter.org/projects/libnetfilter_conntrack/	GPLv2	Used
libnetfilter_queue	1.0.2	http://www.netfilter.org/projects/libnetfilter_queue/	GPLv2	Used
libnfnetlink	1.0.1	http://www.netfilter.org/projects/libnetfilter_queue/	GPLv2	Used
libpcap	1.1.1	www.tcpdump.org	BSD	Used
libqmi	1.8.0	http://www.freedesktop.org/wiki/Software/libqmi	LGPLv2.1	Used

libtool	2.4	http://www.gnu.org/software/libtool/	GPLv2	Used
libusb	1.0.9	https://libusb.info/	LGPLv2.1	Used
logrotate	3.7.1	https://launchpad.net/ubuntu/hardy/i386/logrotate/	GPLv2	Modified
mosquitto-ssl	1.6.7	http://mosquitto.org/files/source/	Eclipse Public License v1.0	Modified
ncurses	5.7	https://invisible-island.net/ncurses/	MIT	Modified
net-snmp	5.7.2	http://www.net-snmp.org/	BSD like	Modified
ntfs-3g	2013.1.13	http://ntfs-3g.org	GPLv2+LGPLv2	Used
ntpclient	2007_365	http://doolittle.icarus.com/ntpclient/	GPLv2	Modified
openssl	1.0.2n	http://www.openssl.org	OpenSSL License & the original SSLeay license	Modified
popt	1.16	https://github.com/daishe/popt	MIT	Modified
ppp	2.4.3	https://ppp.samba.org	GPL & BSD-style & public domain	Modified
pure-ftpd	1.0.30	http://pureftpd.org	BSD	Modified
radvd	1.8	http://www.litech.org/radvd/	BSD	Used
readline	6.2	https://tiswww.case.edu/php/chet/readline/rltop.html	GPLv3	Used
samba	3.0.37	http://www.samba.org/samba/	GPL	Modified
sqlite	3.6.23.1	http://www.sqlite.org/	Piblic Domain License	Used
syslog-ng	2.0.10	http://www.balabit.com/network-security/syslog-ng/	GPL/LGPL	Used
tcpdump	4.2.1	http://www.tcpdump.org/	BSD	Used
udhcp	0.9.8	http://udhcp.busybox.net/	GPLv2	Modified
WIDE-DHCPv6	20080615	http://wide-dhcpv6.sourceforge.net/	BSD	Modified
zebra	0.93a	http://www.zebra.org/	GPLv2	Used

Check list for the items may be related to HW functions

Items	Any change?	Comments
DSL/Modem code	N	
DSL/GE/PON Application/Driver code and setting parameters	N	
Wireless driver (WiFi/3G/WiMAX/LTE..)	N	
VoIP driver & setting	N	N/A
Video decoder driver	N	N/A
Memory access related (like tuning DDR parameters, etc)	N	
Dying gasp	N	
LED behavior	Y	
FAN speed control	N	
Temperature sensor control	N	
Others	N	