

Dell OptiPlex 7000 Series

BIOS & Firmware Compatibility Matrix — Document No. DCM-2026-Q1-117 — Revision C — Published 2026-02-10

1. Purpose

This document defines the supported BIOS, TPM firmware, and NIC firmware combinations for the Dell OptiPlex 7000 series fleet. IT administrators must reference this matrix before approving any BIOS update via Dell Command | Update or fleet management tooling. Deviating from supported combinations may result in boot failures, degraded network performance, or security baseline non-compliance.

2. Supported BIOS Versions

BIOS Version	Release Date	Status	Minimum TPM FW	Notes
2.14.0	2025-04-02	Legacy	7.2.1	End of support 2026-06-30
2.15.2	2025-08-14	Supported	7.2.1	—
2.16.0	2025-11-20	Supported	7.2.3	Required for Windows 11 24H2 security baseline (see Sec. 4)
2.17.1	2026-01-30	Current / Recommended	7.3.0	Latest stable release

3. Known NIC Firmware Conflicts

BIOS 2.16.0 and later enable a revised Secure Boot certificate chain that is incompatible with Intel I219-LM NIC firmware versions below 23.0. Devices that receive the BIOS 2.16.0 update while running NIC firmware 22.x will experience intermittent PXE boot failures and may drop from corporate Wi-Fi/Ethernet management VLANs during the POST handshake.

Required action: NIC firmware must be upgraded to 23.0 or later **before** or in the same maintenance window as any BIOS upgrade to 2.16.0 or higher. This is a hard blocking dependency, not a recommendation.

Component	Affected Versions	Constraint	Severity
Intel I219-LM NIC Firmware	< 23.0	CONFLICTS_WITH BIOS >= 2.16.0	Critical
Intel I219-LM NIC Firmware	>= 23.0	Compatible with all listed BIOS versions	—

4. TPM Firmware Requirements

BIOS 2.16.0 introduces an updated TPM measured-boot policy. Systems must be running TPM firmware 7.2.3 or later prior to applying this BIOS version. Systems on TPM 7.2.1 attempting to apply BIOS 2.16.0 directly will fail the firmware signature check and the update will be rejected by Dell Command | Update with error code DCU-0x442.

5. Chipset Driver Notes

Customers running BIOS 2.17.1 are advised to consider upgrading the Intel chipset INF driver to 10.1.45 or later for optimal power-management telemetry reporting to endpoint management agents. No functional issues have been reported on earlier chipset driver versions at this time.

Footnote reference [1] — see Appendix A.

Appendix A — Footnotes

[Continued from prior internal revision; full footnote text intentionally withheld pending legal review for this public revision. Contact Dell Enterprise Support for the complete footnote text if required for compliance audits.]

Document classification: Dell Enterprise Partner Distribution. Subject to change without notice.