

Intel Ethernet Controller I219-LM

Firmware Advisory 23.0 — Security & Compatibility Update — Published 2025-12-18

Summary

Intel is releasing firmware version 23.0 for the I219-LM Ethernet controller family to address a Secure Boot certificate chain validation issue (CVE-2025-41822) affecting systems with BIOS implementations released after late 2025. This advisory also covers driver-level compatibility for the chipset INF driver package.

Affected Versions and Remediation

Firmware Version	Status	Minimum Driver	Action Required
22.1	Vulnerable	10.1.40	Upgrade to 23.0 immediately
22.5	Vulnerable	10.1.40	Upgrade to 23.0 immediately
23.0	Patched	10.1.40	No action — current

Systems applying OEM BIOS updates that introduce the revised Secure Boot certificate chain (for example, Dell BIOS 2.16.0 and later per Dell document DCM-2026-Q1-117) **MUST** have NIC firmware 23.0 or later installed beforehand. Failure to sequence this correctly may result in the network controller failing POST validation, requiring manual BIOS recovery to restore network connectivity.

Driver Compatibility

Firmware 23.0 requires chipset INF driver 10.1.40 or later. Earlier driver versions (10.1.3x and below) have not been validated against this firmware revision and may report incorrect link-speed negotiation values in Windows Device Manager, though no functional connectivity loss has been observed in internal testing.

Deployment Notes

This firmware can be deployed via standard OEM firmware update utilities (e.g., Dell Command | Update 5.x, Lenovo Vantage, HP Image Assistant). No reboot sequencing constraints apply beyond standard firmware update practices.