



**Exhaust Treatment** 

**Technical Services** 

WV92S335 Issue 1, 28 January 2021

# Filter replacement for SICK MARSIC300

Distribution to operators and owners of installations concerned

# Next opportunity \*

## **Equipment concerned**

SICK MARSIC300 Continuous Emission Monitoring System (CEMS) used in WÄRTSILÄ® SOx scrubbers.

#### Reference

- System OMM, section valid for CEMS
- Operational Manual SICK MARSIC300

## Introduction

Wärtsilä has recently experienced an increased number of cases where the SICK MARSIC300 CEMS has reported the error code S035 with the error text "Ref. energy too low". This error code relates to a contaminated measuring cell.

### **Problems**

A contaminated measuring cell (part of the analyser) either needs service or replacement.

# **Preventive action**

Replace the accompanying filter in accordance with the makers maintenance interval.

# **Validity**

Until further notice.

Before taking any action, always check the available online systems for the latest revision of this document. Any locally stored or printed version is considered to be an uncontrolled document.

Tel: +358 010 709 0000

<sup>\*</sup> Next opportunity: Action is highly recommended and should be taken at next opportunity.



WV92S335, Issue 1, Page 2 / 4

# **Document history**

Issue	Date	Description	SBWT ID
1	28-01-2021	Initial release	003842

## Introduction

The Continuous Emissions Measuring System (CEMS) is part of the scrubber deliveries from Wärtsilä and monitors the SO<sub>2</sub>/CO<sub>2</sub> ratio. The SICK MARSIC300 CEMS consist of several parts including one or more Gas Sampling Unit(s) (hereby called SFU). The SFU is directly mounted into the upper part of the scrubber and provides the analyser and its measuring cell scrubbed exhaust gas for analysis.

Wärtsilä has recently experienced an increased number of cases where the MARSIC300 CEMS has reported the error code S035 with the error text "Ref. energy too low" - this relates to a contaminated measuring cell.



Figure 1, SICK MARSIC300 CEMS (SFU is shown to the left and analyser to the right)

# Instructions

To ensure that the measuring cell is in a clean state it is important to ensure that the SFU filter and the air preparation filters are replaced within the makers maintenance interval which are listed below:

- SFU filter to be replaced on a maximum three-month basis.
  If the flow seen on the MARSIC300 HMI starts decreasing noticeably or the error code S004 with the error text "Flow too low" is present, this is a sign of a contaminated filter ready for replacement (regardless of time in use).
- Air preparation filters to be replaced on a maximum six-month basis.
  Due to the quality differences for compressed air, the filter elements should be replaced when an oily substance is clearly noticeable on the filters (regardless of time in use). The required air quality is listed in the CEMS manual (part of the OMM), section "Supply gases".



## **CAUTION:**

Regardless of wording found in manuals, the filters mentioned in this Service Letter (including the measuring cell filter) shall be replaced and **not** attempted to be cleaned.

## NOTE:

Rectifying measuring cell contamination is often a costly repair that seldomly is covered by warranty.



WV92S335, Issue 1, Page 3 / 4

When SFU filter replacement is carried out, both the filter and the provided gaskets (as seen in Figure 2) must be replaced.



Figure 2, Parts included in the SFU filter kit

Filter replacement instructions are found in the CEMS manual (part of the OMM), however, additional instructions are shown below due to the importance of correct replacement.

When performing the filter replacement, releasing and applying force to the SFU lid is done via the rotary handle and not by tightening the accompanying fasteners (see Figure 3).




Figure 3, SFU filter fasteners

If applying force to the SFU lid is done by tightening the fasteners, the rotary handle will be able to move freely, hence lack of required sealing pressure is applied to the filter and gasket (see Figure 4 on the next page). This will create an escape path between the filter element and its gasket which likely will result in a contaminated measuring cell.

WV92S335, Issue 1, Page 4 / 4




Figure 4, SFU filter installation guidelines (red part illustrates the gasket)



## ATTENTION:

Use only the rotary handle for releasing and applying sealing pressure forces to the filter – fasteners are not to be adjusted.

## Contact

For services, spare parts and/or tools, please contact your nearest Wärtsilä representative or log in to Wärtsilä Online: www.wartsila.com/wartsila-online

If you do not have the contact details at hand, please follow the link: www.wartsila.com/contact

## © 2021 Wärtsilä Finland Oy - All rights reserved

No part of this publication may be reproduced or copied in any form or by any means (electronic, mechanical, graphic, photocopying, recording, taping or other information retrieval systems) without the prior written permission of the copyright holder. Wärtsilä Finland Oy makes no representation, warranty (express or implied) in this publication and assumes no responsibility for the correctness, errors or omissions for information contained herein. Information in this publication is subject to change without notice. Wärtsilä does not assume any liability for the consequences of the owner's/operator's actions, inactions, and/or decisions made or based upon the information provided herein.

Unless otherwise expressly set forth, no recommendation contained in this document or any of its appendices is to be construed as provided due to a defect of the product, but merely as an improvement of the product and/or the maintenance procedures relating thereto. Any actions by the owner/operator as a result of the recommendations are not covered under any warranty provided by Wärtsilä and such actions will thus be at the owners/operators own cost and expense.

NO LIABILITY WHETHER DIRECT, INDIRECT, SPECIAL, INCIDENTAL OR CONSEQUENTIAL, IS ASSUMED WITH RESPECT TO THE INFORMATION CONTAINED HEREIN. THIS PUBLICATION IS CONFIDENTIAL AND INTENDED FOR INFORMATION PURPOSES ONLY.