



Exhaust Treatment

Technical Services

WV92S303 Issue 2, 04 June 2020

Temporary inspections of WES damper valve control cabinets

Distribution to:

- Operators and owners of installations concerned
- Commissioning teams of projects concerned



For immediate attention

Equipment concerned

WÄRTSILÄ® V-SOx and Q-SOx scrubbers equipped with damper valve(s) manufactured by WES.

Reference

WV92S298 - Ensuring working air for damper soot cleaning is present at all time

Background

Wärtsilä has recently received claims regarding WES damper control cabinets being affected by hot flue gases. The purpose of this Service Letter is to give temporary instructions to prevent this issue.

A solution for preventing the issue is under development. In the meantime, customers should perform the inspections described in this bulletin.

Risk

In case hot flue gases enters the damper cabinet, it might result in risk for hot surfaces and malfunction of the specific damper. This can result in operational difficulties.

Preventive actions

- Ensure that pressurized air is available for the components concerned at all time
 including working air for soot cleaning and instrument air for valve actuation.
- Ensure that other related components in the soot cleaning line are in good working condition without leakages.

Validity

Until further notice. Replacing issue 1 dated 24 February 2020.

Before taking any action, always check the available online systems for the latest revision of this document. Any locally stored or printed version is considered to be an uncontrolled document.

Tel: +358 010 709 0000

^{*} For immediate attention: This bulletin should be read immediately with possibly immediate action as well.

Neglecting this bulletin can be dangerous for personnel or cause damage to the installation or environment.



WV92S303, Issue, Page 2/3

Document history

Issu	Date	Description	SBWT ID
1	24-02-2020	Initial release (3-way dampers).	003378
2	04-06-2020	Second release, all dampers manufactured from WES included.	003492

Introduction

The scrubber system has dampers installed (either 2-way or 3-way). The purpose of the dampers is to route the exhaust gas into the scrubber or directly to the exhaust stack. The damper discs can over time be fouled by soot; hence the soot cleaning function. Soot cleaning is automatically activated by the scrubber control system, but if desired soot cleaning can be triggered manually.




Figure 1, Example of a 3-way damper valve with control cabinet (project dependent)



CAUTION:

If a backflow of hot flue gases from the damper to the damper control cabinets occurs, the internal components in the cabinet will be negatively affected by the acidic environment and increased temperature (both caused by the hot flue gases).

Actions

- Immediately perform a thorough inspection of the WES damper control cabinets. Look especially for any leaks and inspect the components that are part of the soot cleaning system. Be aware of the risk for hot surfaces.
- Until further notice from Wärtsilä: Perform daily inspections of the WES damper control cabinets. Be aware of the risk for hot surfaces.
- If a flue gas leakage is noticed, temporarily close the working air (if possible) and plug the soot cleaning hoses from the damper to the cabinet. This will ensure that the components in the cabinet are not exposed to hot flue gases



WV92S303, Issue, Page 3/3

Contact

For services, spare parts and/or tools, please contact your nearest Wärtsilä representative or log in to Wärtsilä Online: www.wartsila.com/wartsila-online

If you do not have the contact details at hand, please follow the link: www.wartsila.com/contact

© 2020 Wärtsilä Finland Oy - All rights reserved

No part of this publication may be reproduced or copied in any form or by any means (electronic, mechanical, graphic, photocopying, recording, taping or other information retrieval systems) without the prior written permission of the copyright holder. Wärtsilä Finland Oy makes no representation, warranty (express or implied) in this publication and assumes no responsibility for the correctness, errors or omissions for information contained herein. Information in this publication is subject to change without notice. Wärtsilä does not assume any liability for the consequences of the owner's/operator's actions, inactions, and/or decisions made or based upon the information provided herein.

Unless otherwise expressly set forth, no recommendation contained in this document or any of its appendices is to be construed as provided due to a defect of the product, but merely as an improvement of the product and/or the maintenance procedures relating thereto. Any actions by the owner/operator as a result of the recommendations are not covered under any warranty provided by Wärtsilä and such actions will thus be at the owners/operators own cost and expense.

NO LIABILITY WHETHER DIRECT, INDIRECT, SPECIAL, INCIDENTAL OR CONSEQUENTIAL, IS ASSUMED WITH RESPECT TO THE INFORMATION CONTAINED HEREIN. THIS PUBLICATION IS CONFIDENTIAL AND INTENDED FOR INFORMATION PURPOSES ONLY.