

Drum will not spin

SAFETY: Before any inspection, isolate the machine at the main disconnect and lock out the supply. Confirm the drum has fully stopped before opening the panel. Moving parts and residual voltage can cause serious injury.

If the drum does not spin, first check the door interlock switch. A failed interlock reports as error code E14 and prevents the motor from energising.

Next, inspect the drive belt for wear or slippage. A glazed or cracked belt should be replaced. Correct belt tension is 12 mm deflection at mid-span under light thumb pressure.

If the belt and interlock are good, check the motor capacitor and the inverter output. Do not probe the inverter terminals while energised.

Error codes

E14: Door interlock open or faulty. The controller inhibits spin. Verify the interlock continuity and the door strike alignment.

E22: Water not draining. Check the drain pump and hose for blockage before restarting a cycle.

E31: Over-temperature on the heating circuit. Allow the machine to cool and inspect the NTC sensor.

Steam valve maintenance

SAFETY: Steam lines operate at high temperature and pressure. Close the steam supply and allow the line to cool before servicing. Wear heat-resistant gloves.

A leaking steam valve is usually caused by a worn seat or diaphragm. Replace the diaphragm kit (part reference varies by model; confirm against the parts list).

After reassembly, pressure-test the valve at working pressure and check for leaks with the supply restored slowly.