

LCR Meter Startup

1. Power on

Press the **Power** button in the top-left corner.

2. Enter the configuration menu

Hold **UTIL** for 3 seconds. The screen shows **bBEEP**.

3. Turn off the beep

Press **Down**. The **on** at the top of the screen changes to **oFF**. The meter will no longer beep while reading.

4. Turn off auto sleep

Press **UTIL** once. The screen shows **AoFF**.

Press **Down**. The **5** at the top (5 minutes) changes to **oFF**. The meter will now stay on indefinitely and will not shut off mid-cycle.

5. Return to the main screen

Press **L/C/R/Z**.

6. Confirm capacitance mode

Check for **C** in the top-left corner of the screen. If it is not there, press **L/C/R/Z** to cycle through modes until **C** appears.

7. Enable USB

Press **USB**. **RMT** flashes in the bottom-right corner when USB is active. The meter can now be read over USB.

Quick reference

Step	Button	Screen shows
Power on	Power (top left)	Display on
Config menu	Hold UTIL 3 s	bBEEP
Beep off	Down	on -> oFF
Auto sleep menu	UTIL	AoFF
Auto sleep off	Down	5 -> oFF
Main screen	L/C/R/Z	Measurement screen
Capacitance	L/C/R/Z (if needed)	C top left
USB on	USB	RMT flashing bottom right