



July 21, 2026

To whom it may concern,

I inspected the roof at 1174 Liberty Dr., Indianapolis, IN 46234 on July 20, 2026 at 9:15 am.

After my inspection of the roof, I have determined that it is between twelve and fifteen years old. It appears to be a certain weatherwood dimensional shingle. These usually carry what is called a limited lifetime warranty but most manufacturers and installers call it a thirty year shingle. This shingle does display some signs of degranulation, but this is normal for a shingle this age. There was one nail pop that was present in the inspection photos. I was able to identify it and it can be easily resolved. The shingle itself can be resealed to prevent any wind damage. I did not observe any broken shingles. The soft metals, such as the vents and the skylight flashing did not display signs of hail damage. The shingles did not display any signs of wind damage.

Despite the typical degranulation, I believe this roof has at least ten good years left. The granules themselves serve as impact protection; also, it's what gives them their color. In certain colors, it can also serve as UV protection. Under the granules is a fiberglass matting with a petroleum base. This matting is tough and with its petroleum base, it helps to completely shed water. In the absence of granules, the fiberglass matting still enables the shingle to perform most of its duties. The type of granular loss and the absence of cracked fiberglass matting tells me this shingle is more than capable of fulfilling its duties. This is why I say the roof has a good ten years left to it.

My only real recommendation is to fix one nail pop and reseal that particular shingle. I also suggest that the boots get a fresh bead of sealant and any of the nails that need to be face nailed into the ridge cap ends and transitions get a fresh dab of sealant. This is typical roof maintenance protocol. I suggest people get these checked every few years.

As for the kickout flashings that were suggested, I do not feel they are necessary because of the way the step flashing, J-channel, and siding were ran. It won't hurt to have but the areas seem water tight already and there are no signs of water intrusion at this time.

Sincerely,
Chris Balmer
Owner of Quality First Handyman and Remodeling Solutions, LLC

 q1st@yahoo.com

 317-413-8669