DUNCAN AVIATION

Non-Final Warranty Work Order Print

Job Detail

3033768

Project Manager: Edduyn Pita
Work Order: CT8VA-A
Generated Date: 12/31/2025

WORK PERFORMED BY: DENVER
7375 SOUTH PEORIA ST. #9
ENGLEWOOD CO 80112

Work Order Totals: $4,445.00

DASSAULT FALCON JET-FALCONCARE
WARRANTY ACCTS-BILL KEYNTON
BOX 2000
TETERBORO AIRPORT
SOUTH HACKENSACK NJ 07606

Liberty Global, Inc. (N250LG)
1550 Wewatta Street; Ste 1000
Triangle Building
Denver CO 80202

Customer #: 117171
Date: 12/22/2025
Warranty Claim #: AME
Aircraft: N250LG

Customer Squawks

1 HUBEM/ LANJU 12-22-25

Powered on Aircraft and found the Cockpit Handset(ID 81) to be resetting every ten seconds and the Cabin RH #1 Table Handset(ID 82) to "waiting for system availability" with no IP address assigned.
Troubleshot using Maintenance Computer and the ST4200/DIU Maintenance Port located in the Cockpit Crew Closet. Found the Ethernet to the ST4200 to be intermittent, but was able to log in to the ST4200 and verify that the Phone trunking to be setup for two Handsets using Channel One only with 81 & 82 being selected. Also found that the CTR SSID to be set for disabled and DHCP set to enabled. Lost connection to the CTR and ST4200 after verifying these settings. Suspected ST4200 to be failing. Contacted GOGO Tech Support and spoke to Chase. Discussed findings with Chase and he also mentioned he has been trying to troubleshoot with the Customer Chris as well. He also suspects the ST4200 to be failing from the troubleshooting with the Customer and the Customer provided prints. Recommended to Customer to order a Falconcare exchange ST4200.

HUBEM/ LANJU 12-23-25

Customer received Falconcare exchange ST4200. Accessed ST4200 (see Equipment Removal for access). Removed suspected failed ST4200 PN: P12023-001 SN: 1202300100251 and installed Falconcare tested exchange ST4200 PN: P12023-001 SN: 1202300100476. Using a Maintenance Laptop

found the connection to the ST4200 to be unresponsive as well as the Cabin Handset to "waiting for system availability". Customer provided WD from the installation at this point. Verified power and grounds at the ST4200, CTR, ACA and DIU. Found all power and grounds present. Reconnected ST4200, CTR, ACA and DIU.

Pulled CB and powered on remaining system. Found the Maintenance Point has no activity on connection with CTR CB pulled. Found the Customer provided WD does not match the aircraft exactly. Suspect that the Maintenance Port goes to the CTR instead of the ST4200 from when the system had the ATG 5000 still installed. Recommended to Customer to order a Falconcare exchange CTR. All work performed IAW current XWGOGO AXXESS II IM Doc: D12004 and Customer provided WD: F7XW23-15-23 KA

Parts	Labor	Other Services	Flat Rate	Total
$0.00	**$2,695.00**	**$0.00**	**$0.00**	**$2,695.00**

2 LANJU 12/29/25

Customer received Falconcare exchange. Removed suspected failed CTR PN: P12083 SN: 1208313204 and installed Falconcare repaired exchange CTR PN: P12083 SN: 1208313166. Using a Maintenance Laptop connected to the CTR. Verified on the Cabin Handset the original "waiting for system availability" was no longer present and the normal operating menu was present, work performed IAW current XWGOGO AXXESS II IM Doc: D12004. Falcon SATCOM operational testing for Ext. 82 Cabin Handset IAW AMM F7X23-15-00-710-801 and Data Transmission and Auto Calling IAW Falcon F7X 23-20-00 general description. No current U.S Airworthiness Directives apply. Notified Customer Ext 81 Cockpit Handset Inop prior to Maintenance Customer elected no further work at this time.

Parts	Labor	Other Services	Flat Rate	Total
$0.00	**$1,750.00**	**$0.00**	**$0.00**	**$1,750.00**

Work Order Totals

Parts	Labor	Other Services	Flat Rate	TOTAL
$0.00	**$4,445.00**	**$0.00**	**$0.00**	**$4,445.00**

Work Order Totals: $4,445.00

WIRE INFORMATION:
US BANK: LINCOLN, NE 68508
ABA 104000029
ACCOUNT#: 1 494 0152 5626
SWIFT ADDRESS: USBKUS44IMT

CORPORATE ADDRESS:
3701 Aviation Road
Lincoln, NE 68524

REMIT TO:
P.O. BOX 956153
St Louis, MO 63195-6153
REFERENCE: Liberty Global, Inc. (N250LG)
CUSTOMER #: 117171 | N250LG

Credit@DuncanAviation.com | +1 402.479.8175

Vendor warranty claims have been submitted on the items indicated by a 'W' or 'S' and are not included in the totals. Any claims denied or reduced by the vendor will become your responsibility.

(W) Vendor warranty claims will be submitted on these items.
Any claims denied or reduced by the vendor will become your responsibility.

Outlook

F7X, SN: 012, REG# N250LG, CT8VA, DRAFT

From Adam Everley <adam.everley@duncanaviation.com>
Date Wed 12/31/2025 3:51 PM
To Warranty-Invoice-WH <Warranty-Invoice-WH@DassaultFalconJet.com>

2 attachments (122 KB)
JobDtl - 2025-12-31T143640.242.pdf; xprCustAct_CT8VA_139364_A_1.xml;

This email is external to Dassault. Caution with links and attachments.

****** FALCON CARE ******

F7X
SN: 012
REG# N250LG
FAILURE DATE: 12/22/2025
DEPARTURE DATE: 12/23/2025
TT: 5823.9
LG: 2292
LABOR HOURS: 25.4
LABOR RATE: $175.00
PARTS: $0.00
TOTAL: $4445.00

Hello,

Please review for Dassault FalconCare & provide Breakdown of coverage when you can.
Please let me know of any questions.

Have a great day,

ADAM EVERLEY
RETURN GOODS ADMINISTRATOR
DIRECT: +1 402.479.4261
www.DuncanAviation.aero