



PRE-PURCHASE INSPECTION REPORT

Ref: TRW-PPI-SMN1057C · 25 September 2026

Vehicle No.	SMN1057C	Make / Model	Honda Freed Hybrid
Inspection Date	25 September 2026	Odometer Reading	_____ km (as displayed)
Prepared For	_____	Inspected By	The Right Workshop

OVERALL ASSESSMENT: PROCEED WITH CAUTION — NOT RECOMMENDED AT CURRENT CONDITION / ASKING PRICE

This vehicle shows signs of a **previous rear-end accident** that was not properly rectified, with **rust already forming on the boot**. We also **suspect the mileage has been adjusted**, as the overall wear and findings on the vehicle are not consistent with the displayed odometer reading. Together with a **cracked front stabiliser link** and a **leak at the clutch area**, we advise the buyer to request further verification and factor the repair costs into any price negotiation before committing.

SUMMARY OF FINDINGS

#	Item	Area	Severity
1	Mileage suspected to have been adjusted	Odometer / History	HIGH
2	Rear accident history — not restored to proper fitment, rust on boot	Body / Rear	HIGH
3	Front stabiliser linkage cracked	Suspension	HIGH
4	Clutch plate area leaking	Transmission	MEDIUM
5	Rear boot stopper missing	Body / Tailgate	LOW

DETAILED FINDINGS

1. Suspected Odometer Adjustment

HIGH

Based on our findings during the inspection, the overall wear and condition of the vehicle do not match the mileage shown on the odometer. We therefore **suspect the mileage has been adjusted before**. If so, the true mileage is likely higher than displayed, which affects the car's value and the expected remaining life of wear items (suspension, transmission, hybrid battery).

Recommendation: Ask the seller for full servicing records and cross-check the mileage history against past service invoices and inspection records. If the seller cannot provide consistent records, treat the displayed mileage as unreliable and value the car accordingly.

2. Rear Accident History — Not Properly Rectified

HIGH

The rear of the vehicle shows clear signs of a **previous accident**. The repair was **not adjusted back to the proper factory fitting** — rear panels and the tailgate do not sit correctly. **Rust is visible on the boot**, indicating the repair was either incomplete or the protective coating was not restored, and moisture is getting in.

Left untreated, the rust will spread, and poor fitment can lead to water leaks into the boot, rattles and wind noise.

Recommendation: Have a body shop assess the rear structure (rear floor and chassis rails) before purchase. Budget for panel realignment and rust treatment. Ask the seller to disclose the accident and repair history.

3. Front Stabiliser Linkage Cracked

HIGH

A **crack was found on the front stabiliser (sway bar) link**. This part controls body roll when cornering. A cracked link can fail completely, causing knocking noises over bumps, reduced stability and less predictable handling.

Recommendation: Replace before the car is driven regularly. We recommend replacing front stabiliser links as a pair for balanced handling. Safety-related — should be fixed by the seller or deducted from the price.

4. Clutch Plate Area Leaking

MEDIUM

Leakage was found at the clutch plate area of the transmission. Leaks here can lead to clutch slipping, jerky gear changes and further damage to the clutch and transmission if not addressed. Transmission repairs on a hybrid can be costly.

Recommendation: Trace and fix the source of the leak (seal/gasket), then inspect the clutch pack for contamination and wear. Get a repair quotation before purchase and factor it into the price.

5. Rear Boot Stopper Missing

LOW

The **rear boot (tailgate) stopper is missing**. Without it the tailgate does not seat properly, which can cause rattling, paint chipping and poor sealing. This may be related to the rear accident repair (Item 2).

Recommendation: Replace the stopper — a minor, low-cost fix. Check tailgate alignment at the same time.

RECOMMENDED NEXT STEPS FOR THE BUYER

1. Request **full service records** and accident / insurance claim history from the seller to verify the mileage and rear repair.
2. Obtain repair quotations for Items 2–5 and use them to **renegotiate the price**, or request the seller to rectify before handover.
3. If the mileage cannot be verified, **reconsider the purchase** — an adjusted odometer is a serious concern for resale value and reliability.
4. The Right Workshop can provide a detailed repair quotation for all items listed above on request.

Inspected by (name & signature)

Date

This report reflects the condition of the vehicle observed at the time of inspection and is based on a visual and functional check without dismantling of components. Findings marked "suspected" are the inspector's professional opinion based on the evidence observed and are not a legal determination. Hidden defects or issues that develop after the inspection date may not be covered. This report is intended to support the buyer's purchase decision and should be read together with the vehicle's official records.

The Right Workshop · therightworkshop.com · +65 8952 1688