

Final Cushion mm

HUSKY

Run Sheet - CONFIDENTIAL

VALIDATING FORM

Product Name	1216CW110				
Material Number	11100				
Material Description	RSN CLR MKRN 2856-550042/				
Date Created	04/26/2018				

Tool Number	1216TRAY					
Resin/Aditive Number						
Resin/Aditive Descrip						
	Std.	Cert.				

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	

Standardization Info	Min.	Mid.	Max.		
Certifield Cycle Time :	51.40	52.9	52.90		
Final Part(s) Weight (g	575.110	578.0	580.890		

ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS

Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data						
Nozzle Tip %		Mold Gate Temp °F	tower	Fill Only Time	4.45	Machine Number: H407				
Nozzle Body %	25	Mold Fixed ½ °F	150	Fill Only Weight	515.0					
Adapter 1 (EX)	25	Mold Moving ½ °F	85	Steel Temp. "A" Side °F	149					
S/H Heat (EX)		Stripper or other °F		Steel Temp. "B" Side °F	115					
Barrel Head (EX)	580	Nozzle Tip Information		Melt Temp. °F	612					
Barrel Front (EX7)	600	Type GP, FT, NYL	GP	Valve Gate	VG1	VG2	VG3	VG4		
Barrel Center (EX6)	600	Length OAL (in.)	2 3/4	Open						
Barrel Center (EX5)	600	Orifice Size (in.)	1/4	Close						
Barrel Center (EX4)	600	Nozzle Body Information		PSI						
Barrel Center (EX3)	600	Length OAL (in.)	6.0	Delay						
Barrel Center (EX2)	600									
Barrel Rear (EX1)	580								_	
Injection Profile	Set	Recovery & Clamp I	Profile	Gas Assist	C1	C2	C3	C4		
Shot size in.	108.0	Pre-Pullback mm/s		Delay (Sec)						
Injection Velocity mm/s	8	Pre-Pullback Stroke m		Hold (Sec)						
Injection Velocity mm/s	22	Screw Start Delay		Exhaust (Sec)						
Injection Velocity mm/s	18	Screw Chg Position	103.0	Pressure 1 (PSI)						
Injection Velocity mm/s		Screw Recovery RPM	100	Time (Sec)						
Injection Velocity mm/s		Screw Recovery RPM	100	Pessure 2 (PSI)						
Injection Change Pos 1	108.0	Back Pressure 1	250.0	Time (Sec)						
Injection Change Pos 2	40.0	Back Pressure 2	10.0	Hot Tip Controller	Box 1	Box 2	Box 3	Box 4	Box 5	Box 6
Injection Change Pos 3		Post Pullback mm/s		Position 1 Gate/HB/Man	460					
Injection Change Pos 4		Post Pullback Stroke		Position 2 Gate/HB/Man						
Trans Pos. mm	10.00	Screw positon after SB	108.90	Position 3 Gate/HB/Man						
Injection Press Limit		Screw recovery time	13.10	Position 4 Gate/HB/Man						
Inj PSI at transfer		Cooling time secs	30.0	Position 5 Gate/HB/Man						
Injection time act. secs.	1202.00	Mold protect press	2000	Position 6 Gate/HB/Man						
Hold Press 1 PSI	500	Mold protect time		Start-Up Instructi	ons / Comr	nents				
Hold Press 2 PSI	380	Clamp tonnage	317	•						
Hold Press 1 secs	4.00	Injection pressure gauge								

380

7.1 Holding 2 gauge psi

Back pressure gauge psi
Back pressure gauge psi