

Hold Press 2 secs

Final Cushion mm

3.00 Holding 1 gauge psi

6.0 Holding 2 gauge psi

Back pressure gauge psi

Back pressure gauge psi

Version No.

VALIDATING FORM

HUSKY

1014FF168
11250
RSN CP360H POLYPROPYLE!
02/14/2018

Tool Number	1014FFSTACK				
Resin/Aditive Number					
Resin/Aditive Descrip					
	Std.	Cert.			

Colorant Number	
Colorant Descrip	
Color Percentage	
MacGuire Setting	2.00

Standardization Info	Min.	Mid.	Max.
Certifield Cycle Time :	26.40	27.9	27.90
Final Part(s) Weight (g	473.620	476.0	478.380

ALL DATA BELOW IS REFERENCE ONLY AND SETTINGS CAN BE ADJUSTED IF REQUIRED IN ORDER TO MEET PRODUCT STANDARDS										
Barrel Temperatures	Set	Mold Cooling Temps	Set	Reference Data	'					
Nozzle Tip %		Mold Gate Temp °F		Fill Only Time	4.00	Machine Number: H401				
Nozzle Body %		Mold Fixed ½ °F	65	Fill Only Weight	438.0					
Adapter 1 (EX)	420	Mold Moving ½ °F	65	Steel Temp. "A" Side °F	73					
S/H Heat (EX)	420	Stripper or other °F		Steel Temp. "B" Side °F	91					
Barrel Head (EX)	400	Nozzle Tip Information		Melt Temp. °F 419						
Barrel Front (EX7)	400	Type GP, FT, NYL		Valve Gate	VG1	VG2	VG3	VG4		
Barrel Center (EX6)	400	Length OAL (in.)	0.00	Open	135.0	135.0				
Barrel Center (EX5)	400	Orifice Size (in.)	0.00	Close						
Barrel Center (EX4)	395	Nozzle Body Inform	nation	PSI	120	120				
Barrel Center (EX3)	390	Length OAL (in.)	0.00	Delay						
Barrel Center (EX2)	385									
Barrel Rear (EX1)	380									
Injection Profile	Set	Recovery & Clamp I	Profile	Gas Assist	C1	C2	С3	C4		
Shot size in.	95.0	Pre-Pullback mm/s		Delay (Sec)						
Injection Velocity mm/s	75	Pre-Pullback Stroke m	3.00	Hold (Sec)						
Injection Velocity mm/s	35	Screw Start Delay	2.00	Exhaust (Sec)						
Injection Velocity mm/s	6	Screw Chg Position	50.0	Pressure 1 (PSI)						
Injection Velocity mm/s		Screw Recovery RPM	100	Time (Sec)						
Injection Velocity mm/s		Screw Recovery RPM	100	Pessure 2 (PSI)						
Injection Change Pos 1	85.0	Back Pressure 1	250.0	Time (Sec)						
Injection Change Pos 2	25.0	Back Pressure 2	250.0	Hot Tip Controller	Box 1	Box 2	Box 3	Box 4	Box 5	Box 6
Injection Change Pos 3		Post Pullback mm/s		Position 1 Gate/HB/Man	500	550				
Injection Change Pos 4		Post Pullback Stroke		Position 2 Gate/HB/Man	500	550				
Trans Pos. mm	15.00	Screw positon after SB	103.00	Position 3 Gate/HB/Man	500					
Injection Press Limit	2600	Screw recovery time	9.39	Position 4 Gate/HB/Man	500					
Inj PSI at transfer	1048	Cooling time secs	14.0	Position 5 Gate/HB/Man	500					
Injection time act. secs.	3.99	Mold protect press	1800	Position 6 Gate/HB/Man						
Hold Press 1 PSI	900	Mold protect time		Start-Up Instructions / Comments						
Hold Press 2 PSI	1000	Clamp tonnage	400							
Hold Press 1 secs	3.00	Injection pressure gauge	2030							

903

1001

249

253

Validated by: