

XD2000 Parameterization for Frequency Switching

Follow below Steps :

1. Press ESC Button and Go to **Complete settings (CSt-)**

2. Go to **-Motor parameters (MPA-)**

Motor Standard	:	50Hz
Nominal motor Power	:	As per the Motor Name plate
Nom Motor Voltage	:	As per the Motor Name plate
Nom Motor Current	:	As per the Motor Name plate
Nominal Motor Freq	:	As per the Motor Name plate
Nominal Motor Speed	:	As per the Motor Name plate
Max Frequency	:	As per Application / Motor Name plate
Motor Control Type	:	U/F VC Standard (Std)



3. Press ESC Button and Go to **Complete settings (CSt-)**

4. Go to **-Command and Reference (CrP-)**

Control Mode (CHCF)	:	[Separate] (SEP)
Cmd channel 1 (Cd1)	:	1- [Terminal] (tEr) [Run Command via Terminal DI1]
Ref Freq 1 Config (Fr1)	:	(Ai1) - Analog input AI1
Ref Freq 2 Config (Fr2)	:	(uPdt) - Ref Frequency via DI
Freq Switch Assign (rFC)	:	DI 4

5. Press ESC Button and Go to **Complete settings (CSt-)**

6. Go to **-Generic Functions (CSGF-) -> +/- Speed (uPd-) :**

+ Speed Assign (uSP)	:	DI5 - Digital Input DI5
- Speed Assign (dSP)	:	DI6 - Digital Input DI6
Ref Frequency Save (Str)	:	EEP - Save to EEPROM

Wiring Diagram:

