

First step: Inform the workshop operation content, inform the operation purpose, and sign the work ticket.



Second step: Prepare the tools kit, multimeter or clamp meter, and equipment for cleaning panels.



Third step: Choose the appropriate PPE (protective clothing, protective mask, arc flash-proof gloves, earplugs). PPE is required to be tested and within the validity period.



Fourth step: Check the history log and all parameters of the UPS from the display.



Fifth step: Open the UPS back panel cover.



Sixth step: Measure the voltage and current on the termination side of the UPS power input and output (P to P 400V and P to N 220V). Close the UPS back panel cover again.



Seventh step: Clean the UPS, especially the filter and fan module parts, from dust or foreign matter that enters.



Eighth step: Open the battery panel cover. Measure and make sure the battery voltage is in charging mode (13,5 - 13,8 VDC).



Ninth step: Clean the battery panel from dust or foreign matter that enters. Re-check the physical condition (corrosion or burn marks) of the battery and close the battery panel cover.

