

Redmi Note9 4G version is normally used without starting up, and the charging current is small

Failure description: The customer's mobile phone is in normal use, charged at night, and cannot be turned on the next day. Connect the charger + charge display adapter shows about 0.02 a, and it cannot be turned on. Several sets have been repaired in front. It should still be the power amplifier power supply IC problem.

Maintenance process: Shut down, remove the motherboard,



remove the power amplifier power supply IC shield with a hot

air gun at 355 degrees, blow for a few seconds, and add welding oil to return the chip.

Install the motherboard back, plug in the data cable to show that the current is normal, and the charging icon is displayed on the bright screen of the machine. Press the boot button, the mobile phone starts normally and enters the upgrade interface. It seems that the customer's mobile phone should be upgraded automatically in the middle of the night, waiting for the upgrade to be completed and successfully entering the system. Test the function of the mobile phone, and find that there is no signal when inserting the mobile phone Dial key input * # 06 #, send the data normally. Remove the master

Board, remove the power amplifier power supply IC and replant it back to the fault. The resistance of each pin of IC is normal. Check the IC model and find that it can be used with the power amplifier power supply IC of Changxiang 9. Find a material board, remove the chip and install it directly on the Note9 in Redmi, and repair the installation test fault perfectly.





Submitted by yuesuik, a member of Xinzhezao