

# Xiaomi note2 series first-class and second-class maintenance guide

Technical support internal document control: TSIMMN20 Xiaomi note2 series first-class and second-class maintenance guide V01

- Xiaomi note2 series first-class and second-class maintenance guide
  - Precautions for installing battery cover in Xiaomi Note2 series products
  - Precautions for replacing fingerprint module in Xiaomi Note2 series products
  - 1. SIM Card failure
  - 2. Speaker failure
  - 3. Touch screen function failure
  - 4. Switch on and off failure
  - 5. Physical (mechanical) key failure

## Precautions for installing battery cover in Xiaomi Note2 series products

- Before installing the battery cover, replace the battery cover back glue with a new one. First, clean up the residual glue left on the battery cover and the front shell assembly, and then attach the new back glue on the battery cover.
- The bright black battery cover should be covered with bright black battery cover glue, and the following two kinds of glue should be attached to the bright black battery cover correspondingly.  
Material name:  
After-sales left glue-battery cover-bright black (material number: SCNE010009400) After-sales right glue-battery cover-bright black (material number: SCNE010009600)
- Glacier Silver Battery Cover should be backed by Glacier Silver Battery Cover glue, and the following two kinds of glue should be attached to the silver blue battery cover.  
Material name:  
After-sales left glue-battery cover-glacier silver (material number: SCNE010009500) After-sales right glue-battery cover-glacier silver (material number: SCNE010009700)
- Please refer to the latest version of "Xiaomi Note 2 Disassembly and Assembly Quick Guide" for the specific mounting method of battery cover glue

## Precautions for replacing fingerprint module of Xiaomi Note2 series products

Fingerprint module and fingerprint module steel sheet are divided into two types: A\ B. It is required that Class A fingerprint module should be installed correspondingly with Class A fingerprint module steel sheet, and Class B fingerprint module should be installed correspondingly with Class B fingerprint module steel sheet, which cannot be mixed. During maintenance, the black film of steel sheet of Class A fingerprint module can be torn off to match Class B fingerprint module. The specific distinction method is as follows:



**B**类指纹模组对应**B**类指纹模组钢片安装。

## 1. SIM Cato failure

确认故障现象

故障现象为：SIM卡托插入后无法拔出或只能拔出一部分  
确认故障：拆机取出前壳组件后，观察SIM卡托插入位置是否存在台阶（正常前壳组件此处为平滑曲面），若存在台阶则说明SIM卡无法拔插为前壳组件卡住SIM卡托。



更换前壳组件维修

维修方法：更换前壳组件维修  
系统维修方法选择：205更换前壳组装件



验证结果

验证结果：装机测试，将卡托同时放入两张SIM卡，试验SIM卡托拔插正常。



其他问题  
分析解决

## 2. Speaker failure

• No

确认故障现象

故障现象为：扬声器播放声音小或者扬声器杂音。



校准扬声器功放维修

维修方法：进入CIT模式（“拨号键盘按\*#\*#6484#\*#\*”），选择第一项“扬声器功放校准测试”，点击校准，进行扬声器功放校准操作。  
系统维修方法选择：601一般软件维护



验证结果

验证结果：重启手机，播放音乐和用扬声器通话，分别将音量调节到不同大小，试听播放声音是否正常。

其他问题分析解决

### 3. Touch screen function failure

●

确认故障现象

故障现象为：触摸屏菜单键和返回键LED灯不亮，且按键无功能。



关闭“单按键使用”维修

维修方法：进入系统设置，点击“更多设置”选择按键设置，将“单按键使用”功能关闭。

系统维修方法选择：601一般软件维护



验证结果

验证结果：退出设置，观察按键灯是否同时亮起，且试用按键功能是否正常。



其他问题分析解决

#### 4. Switch on and off failure

• Do

确认故障现象

故障现象为：充电或电池激活后仍无法开机



深度刷机  
维修

维修方法：首先尝试充电30分钟以上或者电池激活，若仍无法开机请尝试深度刷机维修。具体操作方法请参见最新版本的《高通平台联芯平台及英特尔平台系列产品刷机指南》

系统维修方法选择：601一般软件维护



1. 检查设备是否处于解锁状态  
2. 检查设备是否处于刷机模式  
3. 检查设备是否处于刷机模式  
4. 检查设备是否处于刷机模式  
5. 检查设备是否处于刷机模式  
6. 检查设备是否处于刷机模式  
7. 检查设备是否处于刷机模式  
8. 检查设备是否处于刷机模式  
9. 检查设备是否处于刷机模式  
10. 检查设备是否处于刷机模式

连接成功，可以在设备管理器中看到正确的端口

其他问题  
分析解决

验证结果：重装手机，尝试是否能正常开机。



- Physical (mechanical)

确认故障现象

故障现象为：音量键或开关机键弹性弱，但按键功能正常。



清洁侧键维修

维修方法：拆机将电源键和音量键取下，然后用无尘布沾酒精分别清洁侧键表面和前壳侧键缝隙处，注意酒精不可过量，避免进入到机器内部，造成进液。

系统维修方法选择：407清洁清洗/调整重装



其他问题分析解决

验证结果：重装手机，用手按压音量键和开关机键，确认故障是否排除。