

This is sample data provided for CALIBER purposes only		ONE POINT LESSON (OPL)		OPL No: OPL-KC-4501-06 Sheet 1 of 1
OPL Title	Suction KO Drum Draining (FA-4510)	Discipline	Process / Operations	
Equipment	KC-4501 - RECYCLE GAS COMPRESSOR	Area / Unit	4500 - RECYCLE GAS SYSTEM	
Related Interlock	SEQ-4501 (SIL 2)	P&ID Ref	TJC-LLD-PID-4501	
Classification:	☐ Basic Knowledge	☐ Improvement	☒ Trouble Case	Aspect: P-Q-C-D-S-M-E

1. PURPOSE / OBJECTIVE

This One Point Lesson explains **suction ko drum draining (fa-4510)** for KC-4501 (RECYCLE GAS COMPRESSOR) in the RECYCLE GAS SYSTEM. Liquid carried over from the KO drum destroys valves and can bend piston rods; the boot must be drained regularly. The lesson gives operators and technicians the key knowledge and the correct step-by-step method so the task is done safely, correctly and consistently every time.

2. SAFETY PRECAUTIONS

Hazard note: this equipment is **HIGH CRITICAL** handling **Ethylene/Hexane/H2** at up to 16 barg / 150 degC. Observe the following before and during the task:

- Obtain the correct operating permit and brief the shift team before the task.
- Confirm hazardous fluids are isolated / inerted as required by procedure.
- Beware of flammable, hot, or high-pressure fluids; wear the correct PPE.
- Never defeat a safety interlock or trip without an authorised override permit.
- Have emergency actions and communications ready before starting.

3. TOOLS & MATERIALS REQUIRED

- Operating procedure & P&ID
- Radio / communication with panel
- Gas detector (O2 / LEL) as required
- Correct PPE for the fluid handled
- Sample containers & PPE for sampling
- Permit-to-work documentation

4. DETAILED PROCEDURE / STEPS

Step	Action	Check / Acceptance
1	Drain the FA-4510 boot every shift on the operator round	Permit valid & briefed
2	Watch LT-4510 level and the LSHH-4510 high-high trip	Parameter within limit
3	Never run the compressor with a high KO drum level	Interlock status confirmed
4	Report frequent liquid carryover to process for investigation	Change logged on DCS
5	Confirm the auto-drain (if fitted) is functioning	Handover to next shift

5. COMMON PROBLEMS & TROUBLESHOOTING

Symptom	Likely Cause	Action
High discharge temperature trip TSHH-4503, capacity drop	1st stage suction plate valve fractured	Replaced complete suction valve set, checked seat, leak tested
KC-4501 tripped on PSLL-4504 low lube oil pressure	Lube oil pump gears worn, relief valve set low	Overhauled lube oil pump, reset relief valve, verified 2.5 barg
High blow-by, low 2nd stage efficiency	PTFE piston rings worn beyond limit	Renewed 2nd stage PTFE piston and rider rings, honed cylinder

6. KEY LEARNING POINTS

- Liquid carried over from the KO drum destroys valves and can bend piston rods; the boot must be drained regularly.
- Respect the interlock SEQ-4501: e.g. PSLL-4504 trips at < 1.5 barg - never defeat it without a permit.
- Always cross-check the Datasheet limits and the P&ID TJC-LLD-PID-4501 before working on KC-4501.
- Record the work in the equipment history so the Knowledge Hub stays the single source of truth.

Prepared by	Reviewed by (Supervisor)	Approved by (Manager)	Date of Sharing
Panel Operator / Technician	Wahyu Setiadi (EMP-1113)	Zulkarnain Hasan (EMP-0901)	Thursday, 14 May 2026