

This is sample data provided for CALIBER purposes only		ONE POINT LESSON (OPL)		OPL No: OPL-CT-7801-02 Sheet 1 of 1
OPL Title	Gearbox Oil Level & Change (ISO VG 220)	Discipline	Mechanical	
Equipment	CT-7801 - COOLING TOWER CELL FAN	Area / Unit	7800 - COOLING TOWER SYSTEM	
Related Interlock	SEQ-7801 (SIL 1)	P&ID; Ref	TJC-LLD-PID-7801	
Classification:	☒ Basic Knowledge	☐ Improvement	☐ Trouble Case	Aspect: P-Q-C-D-S-M-E

1. PURPOSE / OBJECTIVE

This One Point Lesson explains **gearbox oil level & change (iso vg 220)** for CT-7801 (COOLING TOWER CELL FAN) in the COOLING TOWER SYSTEM. Low or degraded gearbox oil causes overheating (TSHH-7803) and gear failure high up on the fan deck. The lesson gives operators and technicians the key knowledge and the correct step-by-step method so the task is done safely, correctly and consistently every time.

2. SAFETY PRECAUTIONS

Hazard note: this equipment is **NON CRITICAL** handling **Circulating water / air** at up to atm / 50 degC. Observe the following before and during the task:

- Apply LOTO (Lock-Out Tag-Out) and prove zero energy before starting work.
- Isolate, depressurise, drain and purge the equipment; obtain a valid work permit.
- Wear the correct PPE: coverall, safety shoes, gloves, goggles and hearing protection.
- Beware of stored mechanical energy (springs, rotating inertia) and pinch points.
- Use certified lifting gear and correct manual-handling technique for heavy parts.

3. TOOLS & MATERIALS REQUIRED

- Standard mechanical hand tools & calibrated torque wrench
- LOTO padlocks and permit
- Laser/dial alignment kit (as applicable)
- Feeler gauges, dial indicator, seal/bearing pullers
- Correct spare parts and gaskets per the BOM
- Lifting gear and slings (certified)

4. DETAILED PROCEDURE / STEPS

Step	Action	Check / Acceptance
1	Check the gearbox sight-glass oil level	Isolation & LOTO verified
2	Sample the oil for water contamination and metal	Parts match BOM / spec
3	Change the ISO VG 220 (4.5 L) per the schedule	Torque / clearance to spec
4	Verify the oil pressure PSL-7807 after refill	No leak / smooth operation
5	Record the oil change and next due date	Record in equipment history

5. COMMON PROBLEMS & TROUBLESHOOTING

Symptom	Likely Cause	Action
Scheduled fan gearbox oil change	Routine - oil sample acceptable	Drained and refilled ISO VG 220, replaced breather
VSHH-7802 vibration alarm on CT-7801 fan	Leading-edge erosion on one FRP blade caused imbalance	Inspected blades, re-balanced fan, vibration normalised
TSHH-7803 gearbox oil temperature rising	Degraded oil and fouled oil cooler	Changed oil, cleaned oil cooler, verified temperature

6. KEY LEARNING POINTS

- Low or degraded gearbox oil causes overheating (TSHH-7803) and gear failure high up on the fan deck.
- Respect the interlock SEQ-7801: e.g. VSHH-7802 trips at > 9 mm/s - never defeat it without a permit.
- Always cross-check the Datasheet limits and the P&ID; TJC-LLD-PID-7801 before working on CT-7801.
- Record the work in the equipment history so the Knowledge Hub stays the single source of truth.

Prepared by	Reviewed by (Supervisor)	Approved by (Manager)	Date of Sharing
Panel Operator / Technician	Wahyu Setiadi (EMP-1113)	Arya Wibisono (EMP-0912)	Sunday, 31 May 2026