

MPLAB® ICD 3 DESIGN ADVISORY

Operational Issues

When designing applications that use the MPLAB[®] ICD 3, these operational issues should be considered:

- Oscillator Circuit Setup
- ICSP™ Implementation and Considerations
- Recommended Configuration
- · Alternate Configuration
- Communication Channel
- · Grounding and AC Applications
- · Correcting Crosstalk
- Hibernation

Refer to the "MPLAB® ICD 3 In-Circuit Debugger User's Guide" (DS51766) for general operational information.

OSCILLATOR CIRCUIT SETUP

Primary Oscillator

Often differences between the MPLAB IDE default settings and the unique target requirements cause the following message to display in the output window "The target device is not ready for debugging. Please check your configuration bit settings and program the device before proceeding." To correct this, set the Configuration bits to match the oscillator setting of the target configuration.

For debugging operations, the application (target) oscillator must be functioning before in-circuit debugging can take place. Ensure the oscillator configuration and the MPLAB IDE Configuration bit setup are configured properly. For example, if your application uses a 20 MHZ crystal oscillator, select the HS (High Speed) selection in MPLAB IDE. For any other applicable device oscillator modes, consult the device data sheet.

Crystal Oscillator

If the MPLAB ICD header or processor extension packs are used to connect to the target, there may be problems with starting the crystal resonator. To avoid potential problems, consider the following:

- 1. Ensure the crystal is connected near the device footprint.
- Keep all lines as short as possible in the target application without unnecessary discontinuities such as PCB vias and test points.
- 3. Minimize any capacitive loading on these nodes.
- 4. Avoid using a socket for the placement of the crystal and capacitor. Solder the devices directly to PCB pads.

ICSP™ IMPLEMENTATION AND CONSIDERATIONS

The MPLAB ICD 3 uses a serial signaling scheme to program and debug a target device. The signals utilized are a clock and a data signal. In most devices they are also mapped to a port (typically RB6 and RB7), but they are also defined in some data sheets as PGC and PGD or ICSPCLK and ICSPDAT.

Additionally, MCLR is also used as either a high voltage programming signal or as an attention indicator to the device.

In order to have trouble free in-circuit debugging, careful planning must be done by the designer to avoid any problems during the application development or production phase of the product.

RECOMMENDED CONFIGURATION

The signals PGC and PGD are active bidirectional signals driven by the MPLAB ICD 3 and target emulation device. If these signals can be kept free from any other passive circuits or active logic in the application, it will ensure trouble free debugging and programming sessions. Also, cable length and/or type may be negligible with this configuration.


Additionally, the MCLR signal is used by MPLAB ICD 3 to provide the voltage used for programming some devices or to signal attention. In instances where the application has a large capacitor, it will cause the signal rise and fall time to degrade. This will hinder the ability of MPLAB ICD 3 and the device to communicate effectively. It is recommended to keep the signal pulled up to VDD with a 10K resistor, and to utilize the power-on timer features of the device to ensure a proper power-up sequence.

ALTERNATE CONFIGURATION

In some cases, especially with low pin count devices, the pins must be utilized by the application.

If this is the case, as a minimum, a resistive isolation is required between the device and the application active node. This will ensure that both the application circuit and MPLAB ICD 3 are able to drive the PGC or PGD node to ground and to the proper VDD levels. Figure 1-1 depicts this configuration.

FIGURE 1-1: TYPICAL ICSP™ APPLICATION CIRCUIT



The resistive isolation value will differ depending on the application and how it is being used. Values ranging from 1K to 10K are suggested. In any case, ensure the levels on PGD and PGC can be driven to their appropriate logic voltage levels.

COMMUNICATION CHANNEL

Some devices have the flexibility to use one of several communication channels or pins for programming and debugging. These channels are generally referred to in data sheets as PGCx/PGDx, where x is channel number identifier. These channels are often multiplexed with some peripherals (I^2C^{TM} , SPI, A/D). If your application uses those peripherals and pins which are common to the default PGC/PGD pins, you must select a different channel and make provisions for the required ICSP connections.

Likewise, when using MPLAB IDE to communicate with the target using this new channel pin assignment, you must ensure that the Configuration bits in MPLAB IDE match the connection channel in your target.

GROUNDING AND AC APPLICATIONS

The MPLAB ICD 3 connects to earth ground from the USB connector interface through the PC.

For AC line powered applications which are not referenced to ground, this presents a path where the different system voltage potential can cause damage to both systems. In these instances, the MPLAB ICD 3 must be isolated. Carefully consider the ground system and signal return connections before connecting the MPLAB ICD 3 to the target.

For hot or floating applications, a USB self-powered isolated hub should be used between the PC and the MPLAB ICD 3 to provide isolation from the PC's earth ground through the USB cable (see Figure 1-2). USB isolated Hub such as the following are suggestions:

- High/Low-Speed 4-port USB HUB, Model UISOHUB 4, B&B Electronics Mfg. Co.
- High-Speed, 7-port USB HUB, Model HUB7P, SEALEVEL Systems, Inc.


WARNING



Using the MPLAB ICD 3 without ensuring ground isolation will result in damage to the MPLAB ICD 3 or the target system as the full AC mains voltage will be applied.

This condition can be hazardous to the operator in the form of an electric shock; therefore, take adequate precautions to avoid this situation.

FIGURE 1-2: EXAMPLE MPLAB® ICD 3 SETUP FOR NON-ISOLATED AC POWER SYSTEMS



WARNING



Using an optoisolated USB hub will create a hot area marked with the dotted line in Figure 1-2.


This condition can be hazardous to the operator in the form of an electric shock, therefore, take adequate precautions to avoid this situation.

CORRECTING CROSSTALK

In some cases a crosstalk problem may exist when the device is being programmed. Due to the locations of the PGC and PGD pins, crosstalk may degrade the signal and cause the MPLAB ICD 3 to fail programming of the target device. To correct this, try the following:

• Construct a RJ12 modular cable and replace the cable that comes with the MPLAB ICD 3. Keep the length as short as possible, preferably under 6 inches. Also, remove the jacket from the cable, so that the conductors are far apart from each other (especially the PGC and PGD signals). The standard MPLAB ICD 3 modular cable is wired as shown in Figure 1-3, that is, RJ12 pin 1 on one end connects to RJ12 pin 6 on the other end. This solves the problem in nearly all cases.

FIGURE 1-3: TARGET CONNECTOR PINOUT



- Note 1: Noise-inducing equipment (motors, light dimmers, etc.) must be on separate power strips from the target application and the MPLAB ICD 3.
 - 2: The use of any cable (other material, length, etc.) other than the one provided with the MPLAB ICD 3 may result in unreliable device behavior.

HIBERNATION

When using the MPLAB ICD 3 for prolonged periods of time, especially while the debugger is in emulation mode, disable the Hibernate mode in the Power Options Dialog window of the PC's operating system. Click on the **Hibernate** tab and clear or uncheck the "Enable hibernation" check box. This will ensure that all communication is maintained across all the USB subsystem components.

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families
 of its kind on the market today, when used in the intended manner and under
 normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee
 the security of their code. Code protection does not mean that we are
 guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, rfPIC and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, In-Circuit Serial Programming, ICSP, ICEPIC, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, PICkit, PICDEM, PICDEM.net, PICtail, PIC³² logo, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rfLAB, Select Mode, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2008, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.



Worldwide Sales and Service

Corporate Office Tel: 480-792-7200

Atlanta Tel: 678-957-9614

Boston Tel: 774-760-0087

Chicago

Tel: 630-285-0071

Dallas Tel: 972-818-7423

Detroit

Tel: 248-538-2250

Kokomo

Tel: 765-864-8360 Los Angeles

Tel: 949-462-9523 Santa Clara Tel: 408-961-6444

Toronto

Tel: 905-673-0699

Asia Pacific Office Tel: 852-2401-1200

Australia - Sydney Tel: 61-2-9868-6733

China - Beijing Tel: 86-10-8528-2100

China - Chenadu Tel: 86-28-8665-5511

China Hong Kong SAR Tel: 852-2401-1200

China - Nanjing

Tel: 86-25-8473-2460

China - Qingdao

Tel: 86-532-8502-7355

China - Shanghai Tel: 86-21-5407-5533

China - Shenyang Tel: 86-24-2334-2829

China - Shenzhen Tel: 86-755-8203-2660

China - Wuhan

Tel: 86-27-5980-5300 China - Xiamen

Tel: 86-592-2388138 China - Xian

Tel: 86-29-8833-7252

China - Zhuhai Tel: 86-756-3210040

India - Bangalore Tel: 91-80-4182-8400

India - New Delhi Tel:91-11-4160-8631

India - Pune Tel:91-20-2566-1512

Japan - Yokohama Tel: 81-45-471- 6166 Korea - Daegu

Tel: 82-53-744-4301 Korea - Seoul Tel: 82-2-554-7200

Malaysia Kuala Lumpur

Tel: 60-3-6201-9857

Malaysia - Penang Tel: 60-4-227-8870

Philippines - Manila Tel: 63-2-634-9065

Singapore

Tel: 65-6334-8870

Taiwan - Hsin Chu Tel: 886-3-572-9526

Taiwan - Kaohsiung Tel: 886-7-536-4818

Taiwan - Taipei Tel: 886-2-2500-6610

Thailand - Bangkok Tel: 66-2-694-1351

Austria - Wels Tel: 43-7242-2244-39

Denmark - Copenhagen

Tel: 45-4450-2828 France - Paris

Tel: 33-1-69-53-63-20 Germany - Munich Tel: 49-89-627-144-0

Italy - Milan Tel: 39-0331-742611

Netherlands - Drunen Tel: 31-416-690399

Spain - Madrid Tel: 34-91-708-08-90

UK - Wokingham Tel: 44-118-921-5869