

Gas Pipeline Compressor Procedures

Procedures for work on gas pipeline compressor stations, including compressor CS-3 and isolation valve GV-17. All hot work requires a hot-work permit.

1. Gas Detection Thresholds

Continuously monitor for flammable gas with a calibrated detector. Alarm thresholds are expressed as a percentage of the lower explosive limit (%LEL).

Level	Threshold	Action
Low alarm	10 %LEL	Investigate and ventilate
High alarm	20 %LEL	Stop work, evacuate the exclusion zone
Trip	40 %LEL	Automatic compressor shutdown

2. Exclusion Zones

Establish an exclusion zone around the work. For compressor CS-3 the exclusion-zone radius is 15 m during venting. For valve GV-17 operations the exclusion-zone radius is 8 m.

3. Hot-Work Permit Process

Obtain a hot-work permit before welding, grinding or any ignition source. Test the atmosphere, confirm it is below 10 %LEL, post a fire watch, and keep the permit on site. If gas is detected above 20 %LEL, stop work and contact your supervisor.