

FPS-3000 — VersaBus card trace worksheet

For the V-BUS XLTR (612-4803-400-G) and AP I/F (612-4448-401-F). Rebuilt 2026-07-29; supersedes the earlier edition.

Every expectation is a PREDICTION from the SBC firmware, not an observation. Where a check disagrees, the board wins - record what you find. Sources: refs_extracted/versabus_access_map.md, MC68153 datasheet, versabus_pinout.md.

Check 0 — the phase beacon: read the machine's own self-test progress

Costs nothing and needs no debugger. Every power-on self-test writes phase<<8 | subtest to CHANNEL_SELECT (\$FF0204) before it runs. Scope, latch or read that register during reset: the LAST value before a hang names the failing subtest. The suite runs \$0100 through \$2903 on a healthy machine and ends in the RTOS idle loop.

beacon	what it was testing when it stopped
\$01xx	CPU flags / arithmetic - fails before any chassis access
\$02xx	\$1FFF1 bit 6 <-> \$F70019 bit 3 inverse wiring
\$0300	ROM decode
\$0400	RAM address decode / byte lanes
\$0500	board status not reaching (x & \$3F31) == \$3F11
\$0600	VMOD control register pattern round-trip
\$0700	short-I/O window at \$F82000 must BUS ERROR
\$0800	I/O channel
\$0900	MC6840 PTM, its IRQ path, or \$1FFF1 bit 7 gating
\$1000	address-space boundary map
\$11xx-\$14xx	panel-bus interrupts and vectors
\$1500	CHANNEL_SELECT must be a clean read/write register
\$1600	XLTR register file, or the BIM population bit
\$17xx-\$18xx	DATA_HI page gating on the \$400000 window
\$1900	chassis memory data lines
\$1A00	AP I/F window
\$2000	RAM address uniqueness
\$22xx-\$23xx	chassis bulk access / A14 decode

Beacon observed: _____ Boot completes to idle loop? Y / N

Check 1 — identify the three BIM packages

Look for three 40-pin DIPs. MC68153 is expected; any part with the same pinout is equally consistent. The parts survey did NOT find them - this is a genuine open question, not a formality.

package ref	part number as marked	date code	pin 1 OK?

Confirm before trusting: pin 3 = CS, pins 38/39/40 = A1/A2/A3, pins 28,29,32-37 = D0-D7, pin 18 = CLK, pin 4 = DTACK.

Check 2-4 — interrupt level, daisy chain, address decode

Check 2 — the interrupt level

The firmware writes \$5F to five channel control registers and \$5E to one. Per the MC68153 datasheet bits 0-2 choose which IRQ output the chip asserts, so \$5F = IRQ7 and \$5E = IRQ6. Buzz the pins and the question closes.

BIM IRQ pin	signal	VersaBus P1 pin	connected? Y/N	notes
8	IRQ1*	87		
12	IRQ2*	88		
13	IRQ3*	89		
14	IRQ4*	90		
15	IRQ5*	91		
16	IRQ6*	92		
17	IRQ7*	93		

Prediction: pin 17 wired on the BIMs at \$FF0240 and \$FF0250; pin 16 on the one at \$FF0230. If IRQ5* is the connected pin instead, the datasheet reading is wrong. Either result is useful - record which pins go anywhere at all.

Check 3 — the IACK daisy chain

Five enabled channels request the same level, so IACKIN*/IACKOUT* decides who wins a tie. Establish the order.

from	pin	to	pin	connected?
BIM ____ IACKOUT*	7	BIM ____ IACKIN*	6	
BIM ____ IACKOUT*	7	BIM ____ IACKIN*	6	
VersaBus IACKIN		first BIM IACKIN*	6	
last BIM IACKOUT*	7	VersaBus / next card		

Record the physical left-to-right order on the card as well as the electrical order.

Check 4 — address decode and chip select

Each BIM answers a 16-byte window; A1-A3 select the register inside, so A4 and above decode into CS.

window	registers	A6	A5	A4	which package has this CS?
\$FF0230-\$FF023F	BIM0 CR0-3, VR0- 0	1	1		
\$FF0240-\$FF024F	BIM1 CR0-3, VR0- 1	0	0		
\$FF0250-\$FF025F	BIM2 CR0-3, VR0- 1	0	1		
\$FF0200-\$FF021B	XLTR control file0	0	0		

A4 and A5 alone do NOT separate the windows: BIM1 and the XLTR file both read A4=0, A5=0. A6 is the deciding bit.

Check 5-6 — register layout, interrupt sources

Check 5 — register layout confirmation

Inferred from firmware writes: CRn and VRn are the same channel. If the board disagrees, the whole channel-to-task mapping in the access map is wrong.

offset	A3	A2	A1	register	channel	firmware writes
+\$0	0	0	0	CR0	ch0	\$5E or \$5F or \$00
+\$2	0	0	1	CR1	ch1	\$00
+\$4	0	1	0	CR2	ch2	\$5F
+\$6	0	1	1	CR3	ch3	\$5F or \$00
+\$8	1	0	0	VR0	ch0	vector number
+\$A	1	0	1	VR1	ch1	vector number
+\$C	1	1	0	VR2	ch2	vector number
+\$E	1	1	1	VR3	ch3	vector number

The address arrives as A01-A03 and reaches the BIM as A1-A3 (pins 38,39,40). Confirm no swap: reversed A1/A3 would exchange the CR and VR halves and everything above would still look self-consistent.

Check 6 — who drives the device interrupt inputs

The four INT inputs are what the chassis pulls to request service. Tracing them backwards names each task's owner.

BIM	INT pin	name	firmware owner (predicted)	what actually drives it
BIM1	23	INT2	TCBXP1I (XP-32 channel 1)	
BIM1	24	INT3	TCBXP2I	
BIM2	19	INT0	TCBXP3I	
BIM2	22	INT1	TCBXP4I	
BIM2	23	INT2	TCBI01I (host link)	
BIM0	19	INT0	TCBRDHC, vector \$41	

The last row matters most. Vector \$41 reaches F04930, the handler that receives the chassis command stream - whatever drives BIM0 INT0 is the chassis's request line for SBC service.

Check 7-8 — AP I/F windows, the Am29116 pair

Check 7 — AP I/F channel windows [CORRECTED - the earlier edition had three of four roles wrong]

Four windows on a 32-byte stride. The card carries eight Am29705 16x4 TWO-PORT RAMs = 32 bits of width.

offset	ch1	ch2	ch3	ch4	role
+\$04	\$FF0044	\$FF0064	\$FF0084	\$FF00A4	write port
+\$08	\$FF0048	\$FF0068	\$FF0088	\$FF00A8	32-bit data, HIGH half
+\$0A	\$FF004A	\$FF006A	\$FF008A	\$FF00AA	32-bit data, LOW half
+\$0E	\$FF004E	\$FF006E	\$FF008E	\$FF00AE	command/trigger, \$8000 fires

+\$08 and +\$0A are ONE 32-bit register, not data + status. \$FF0048 is never read by the ROM. Do NOT look for a '\$4F status value' - that came from our own emulator, not the hardware, and the earlier edition was wrong to ask.

question	finding
Am29705 designators (expect 8)	
Do all four channels share them, or silicon per channel?	
Ribbon connector 1: pin count / signals	
Ribbon connector 2: pin count / signals	
Which pins carry the host-side 32-bit path?	

The host-side counterpart card is missing, so its pinout has to come off this card.

Check 7b — bus mastership

The SBC never asserts a VersaBus transfer request: \$1FFF0, the control register half holding Transfer Request and Block Transfer Request, is written \$00 every time. So the CHASSIS masters the bus and DMAs into SBC RAM.

question	finding
Which card drives BR*/BGACK* on P1?	
Does the AP I/F or the XLTR contain the DMA address counter?	
What writes SBC RAM \$10AA and \$105E? (firmware never does)	

Check 8 — the two Am29116 on the XP32 EXEC card

The owner counts two; the photo survey read one. Settle it before any PROM comes off - it decides whether a dump holds one instruction stream or two.

question	why it matters	finding
How many Am29116 packages?	survey says 1, owner says 2	
One shared 16-bit field, or 16 each on the bus?	one or two	
Carry / status link between them?	cascaded = one 32-bit ALU	