

CNC TRAY CAPTURE

one tool, about a minute

1 LAY

Take a capture sheet: the smallest size the tool lies in with a finger's width of clear paper all round. Lay the tool FLAT inside the window, on its widest face, as it sits in the drawer, clear of the border line. Write its TAG (T0__, from the drawer label) in the TAG box.

2 MEASURE

Measure the tool's tallest point above the paper with the ruler, in mm. Write it in the HEIGHT box.

3 PHOTO

Stand over the sheet. Phone flat, arm's length up: the whole sheet in frame with room around it (about a third of the screen), all four corner squares showing. No flash, no lamp shadow. Do not move the tool.

4 FORM

Open the form "CNC tray capture": tag, height in mm, the photo. Done. The software reads the corner squares to know which paper you used and takes the tool's own outline from the photo. The tray regenerates; a rejected sheet comes back with one line saying why.

WHEN NOT TO PHOTOGRAPH

IT DOES NOT FIT THE WINDOW

Take a bigger sheet: LETTER, then TABLOID. If the tool is a plain rectangular slab, do not photograph it at all: write L, W and thickness in the boxes and submit the sheet.

IT WILL NOT LIE FLAT, OR IT SHINES

A tool that rocks or stands on a knob throws its outline: prop it level with a scrap of card. A bright reflection running along an edge can cut that edge off the outline: turn the sheet under the light and shoot again. Look at the preview the software posts back.

One tool per sheet. Never a hand in the window, never a tool on its edge, never a lamp or a flash throwing a hard shadow.

Sheets and the ruler live in Drawer 1. Print at 100%: the bar at the bottom must measure 100mm.