ETAS RTA-BSW v12.7.0

RTA-BSW Release Notes

www.etas.com

Copyright

The data in this document may not be altered or amended without special notification from ETAS GmbH. ETAS GmbH undertakes no further obligation in relation to this document. The software described in it can only be used if the customer is in possession of a general license agreement or single license. Using and copying is only allowed in concurrence with the specifications stipulated in the contract.

Under no circumstances may any part of this document be copied, reproduced, transmitted, stored in a retrieval system or translated into another language without the express written permission of ETAS GmbH.

© Copyright 2025 ETAS GmbH, Stuttgart

The names and designations used in this document are trademarks or brands belonging to the respective owners.

ETAS RTA-BSW 12.7.0 - RTA-BSW Release Notes R01 EN – 05.2025

Contents

1 Introduction 4

1.1 Definitions and Abbreviations 4

1.2 References 4

1.3 Conventions 4

1.4 User Documentation 4

2 Product Definition 5

2.1 Functions at a Glance 5

2.2 General Description 7

2.3 Delivery 7

2.4 Installation 7

2.5 Licensing 7

3 Change Set 8

3.1 New Features and Improvements 8

4 Known Issues 13

4.1 Critical Issues 13

4.2 Major Issues 13

4.3 Minor Issues 14

5 Hotfix Information 26

6 Contact, Support and Problem Reporting 27

6.1 Technical Support 27

6.2 General Enquiries 27

1 Introduction

1.1 Definitions and Abbreviations

Term/Abbreviation	Definition
BSW	AUTOSAR Basic Software module. AUTOSAR defines a comprehensive BSW architecture consisting of OS, RTE, service, interface and driver BSW modules that provide a device independent ECU abstraction to ASW and thus promote SWC reuse and relocation. See Chapter 2 for a list of AUTOSAR BSW modules.
HW	Hardware
KIR	Known Issue Report - For severe Problem Reports which occur after a release, ETAS has introduced the Known Issue Report to inform affected customer immediately. The current Known Issues of former versions can be found on the ETAS website: http://www.etas.com/kir
PR	Problem Report
SW	Software

1.2 References

1. RTA-CAR User Guide, v12.7.0, ETAS GmbH
2. RTA-BSW Reference Guide, v12.7.0, ETAS GmbH

1.3 Conventions

The following typographical conventions are used in this document:

Choose **File→Open**.	Menu commands are shown in boldface.
Click **OK**.	Buttons are shown in boldface.
Press <ENTER>.	Keyboard commands are shown in angled brackets.
The 'Open File' dialog box is displayed.	Names of program windows, dialog boxes, fields, etc. are shown in quotation marks.
Select the file *setup.exe*	Text in drop-down lists on the screen, program code, as well as path- and file names are shown in italics.
A *distribution* is always a one-dimensional table of sample points.	General emphasis and new terms are set in italics.

1.4 User Documentation

The RTA-CAR User documentation in PDF format can be found on the CD.

2 Product Definition

2.1 Functions at a Glance

This release of RTA-BSW supports the following features:

- Generate software modules compatible with AUTOSAR.
- Provide access to the following stacks, as controlled by license features:

Common

Bfx, ComStack, Compiler, Crc, EcuC, Efx, Ifl, Ifx, Mfl, Mfx, Platform, Rba_ArxmlGen, Rba_BswSrv, Rba_DiagLib, Standard

RTA-BASE

BswM, BswM_PB_Variant_Only, BswM_PreCompile_and_PB_Variant, Det, EcuM, StbM, Tm

RTA-CAN

CanIf, CanNm, CanNm_PB_Variant_Only, CanNm_PreCompile_and_PB_Variant, CanSM, CanTSyn, CanTp, CanTp_PBL, CanTp_PBS, CanTp_PC

RTA-COM

Com, ComM, ComXf, IpduM, LdCom, Mirror, Nm, PduR, Rba_ComStackCdd, Rba_XCoreCdd, Rba_Xfrm

RTA-DIAG

Dcm, Dem, Dlt, FiM, FiM_PBL, FiM_PBS, FiM_PC, Rba_DemObdBasic

RTA-ETH

DoIP, DoIP_PBL, DoIP_PBS, DoIP_PC, EthIf, EthSM, EthTSyn, Rba_EthArp, Rba_EthAutoIp, Rba_EthDHCP, Rba_EthDHCPv6, Rba_EthICMP, Rba_EthIPv4, Rba_EthIPv6, Rba_EthIcmpV6, Rba_EthNdp, Rba_EthTcp, Rba_EthUdp, Sd, SoAd, SomeIpTp, SomeIpXf, TcpIp, UdpNm

RTA-ETHSEC

Rba_EthAh, Rba_EthIPsec, Rba_EthIke2, Rba_EthTls

RTA-FRAY

FrIf, FrNm, FrNm_PB_Variant_Only, FrNm_PreCompile_and_PB_Variant, FrSM, FrTp, FrTp_PB_Loadable, FrTp_PB_Selectable, FrTp_PreCompile

RTA-HWD(Can)

CanTrcv

RTA-HWD(Eth)

EthTrcv, EthTrcv_11_Common, EthTrcv_11_StdAutomPhy

RTA-HWD (Fray)

FrTrcv

RTA-HWD (Lin)

LinTrcv

RTA-J1939

J1939Dcm, J1939Nm, J1939Rm, J1939Tp, J1939Tp_PB_Loadable, J1939Tp_P-B_Selectable, J1939Tp_PreCompile

RTA-LIN

LinIf, LinSM

RTA-MEM

Ea, Fee, MemAcc, MemIf, NvM, Rba_EaFs2, Rba_FeeFs1x, Rba_FeeFs2, Rba_FeeFs3, Rba_MemLib, Rba_MemWrprMemAcc

RTA-RipsPlugins

Rte_Rips, Rte_Rips_CSSafety, Rte_Rips_CSXfrm, Rte_Rips_SRCom, Rte_Rips_Sig2Srv

RTA-SAFE

E2E, E2EXf, WdgIf, WdgM

RTA-SEC

CryIf, Crypto, Csm, IdsM, KeyM, Rba_CryptoAuCSC, Rba_CryptoAuHSM3, Rba_CryptoCCL, Rba_CryptoHSM, SecOC

RTA-SWCL

Rba_CCL

RTA-XCP

Xcp

- Generate BSW configuration as part of an EcuC value collection for the following modules:
    - Can, CanIf, CanNM, CanSM, CanTp, Com, ComM, IpduM, Nm, PduR (derived from an ISOLAR-AB import of DBC files)
    - Fee, MemIf, NvM, Ea, rba_MemLib
    - CanTSyn (Derived from a pre defined system configuration)
    - Dcm, Dem (derived from ISOLAR-AB import of ODX file)
    - Fr, FrIf, FrNm, FrSM, FrTrcv (derived from ISOLAR-AB import of FIBEX file)
    - Lin, LinIf, LinSM (derived from ISOLAR-AB import of LDF files)
    - ComXf, E2EXf, Xfrm, rba_SysElem
    - Eth, EthIf, EthSm, EthTrcv, EthTSyn, SoAd, Sd, TcpIp, UdpNm, DoIP
    - LdCom

    - IdsM

- Generate code for any correctly licensed module from a valid BSW configuration.
- Generate system configuration artefacts to allow the RTE to work with generated modules.

2.2 General Description

2.2.1 System Prerequisites

It is expected that the computer will meet the minimum system requirements for the target version of ISOLAR-AB. Please refer to the ISOLAR-B Getting Started Guide for the exact requirements.

2.2.2 Software Prerequisites

Product	Version
ISOLAR-AB	v12.7.0

2.3 Delivery

The installation of RTA-BSW is included in the installation of RTA-CAR. Please see the RTA-CAR User Guide for more information All software documentation is available in the Portable Document Format (PDF), which requires Adobe Reader.

2.3.1 Used 3rd Party Software

See OSS Attributions Document

2.4 Installation

The RTA-CAR User Guide[1] describes how to install RTA-BSW and how to start using the product.

2.5 Licensing

RTA-BSW is protected by ETAS License Manager. You will need a valid license key in order to use RTA-BSW.

The RTA-CAR User Guide[1] describes how to obtain and activate licenses.

3 Change Set

3.1 New Features and Improvements

ID	Component	Summary
ARC-8914	E2EServices	[E2EServices] E2E Profile P07m: Capability requirements and Feature testing
ARC-7981	Diag	[Diag] Dcm $29 extensions
ARC-9329	SecServices	[CryptoAuCSC] Additon of Priority Usage to Several APIs
ARC-8103	SecServices	[KeyM] Additonal certificate handling enhancements
ARC-5665	SecServices	[CryptoAuHSM3] Develop feature: Key Exchange
ARC-9295	SecServices	[CryptoAuCSC] Addition of Retrieval of Symmetric Keys
ARC-7503	SecServices	[CryptoHSM] Support asynchronous processing mode for Main Fuction async close session
ARC-4131	Diag	[Diag] Solution to support DcmDspDataByteSize as per the latest autosar spec
ARC-7202	Diag	[Diag] Support of DcmDspSupportedAddressAndLengthFormatIdentifier for Request Download service ($34)
ARC-7252	Diag	[Diag] Avoid calling read data element function to capture freeze frame data in case of PASSED report
ARC-3249	Diag	[Diag] Implement RoE subfunctions (0x07 & 0x09) as per ISO 14229-1 2020-02
ARC-5343	Diag	[Diag] Fim Master Satellite solution
ARC-3010	RTE-RipsPlugins	[Rte_Rips_SRCom] UX Improvements
ARC-3061	SecServices	[CryptoAuHSM3] Develop feature: CSAI error reporting
ARC-2780	EthStack	[EthSec][TLS][1.3] Support Cipher Suite TLS_CHACHA20_POLY1305_SHA256 (Value: 0x1303)
ARC-3878	LinStack	[LinStack][LinIf] Linif_TxConfirmation response_error signal clearing
ARC-3214	SecServices	[CryptoHSM] Allow the possibility to not persist the keys during the KeyElementCopy operation based on CycurHSM2
ARC-3222	SecServices	[CryptoHSM] Support asymmetric encryption using RSA-OAEP with 3072 bit and 4096 bit key length based on CycurHSM2
ARC-7655	TimeServices	[TimeServices][EthTSyn] Implementation of IDS Sensors - ICV/Freshnessvalue, Master and Slave (Prototype)

ARC-3067	SecServices	[CryptoAuHSM3] Develop feature: Signature service based on CycurHSM3
ARC-8742	EthStack	[SD] Provide SD parameter defintion file to support Secure SOME/IP with ACL
ARC-6615	EthStack	[SoAd] Implementation of ACL in SocketAdapter to support Secure SOME/IP with ACL
ARC-7656	TimeServices	[TimeServices][CanTSyn] Implementation of IDS Sensors - ICV and Freshness counter - Release
ARC-9005	EthStack	[EthSec][TLS][1.3] Use keypair generation service provided for ECDH_SECP521R1 group
ARC-8312	EthStack	[rba_EthArp] ARP entries shall not be updated on receiving IP frame if ARP protocol is in enabled state.
ARC-7967	EthStack	[EthStack][SoAd] Improve SoAdTxPduHeaderId description and validation in SoAd
ARC-6156	EthStack	[Tcplp] Support graceful closing of Tcp sockets during No_comm sequence
ARC-5648	EthStack	[DoIP] EID/GID functionality mismatch after interface introduction
ARC-9346	TimeServices	[TimeServices][EthTsyn] Minor update in Paramdef required for EthIfFrameConfig reference
ARC-6969	FrStack, CanStack, LinStack	[FrStack][CanStack][LinStack] Introduce template for Bus_GeneralTypes.h, to allow adaptation in line with project requirements.
ARC-8561	ComServices	[XCoreCdd] Support to generate MemMap for Multi-Partition for multi-ASIL use cases
ARC-7973	ComServices	[PduR] PduR shall support both QUEUE + FIFO features in a single project
ARC-6896	TimeServices	[TimeServices][EthTSyn] Pdelay calculation allowed only in lowest time domain id and pdelay response allowed in all time domains, when configured
ARC-8304	ComServices	[Comservices][Mirror] MirrorNetworkId parameter shall be made as configurable by user
ARC-8722	ComServices	[XCP] XCP Padding activation by configuration (Up to 8 bytes for all XCP frames)
ARC-5307	Diag	[Diag] DcmDspSessionRow final response from application when configured as 'DCM_OEM_BOOT_RESPAPP' or 'DCM_SYS_BOOT_RESPAPP'
ARC-8522	CanStack	[CanStack] Adaptations required in CanNm as part of Java-21 migration
ARC-8162	Diag	[Diag] Runtime optimization of Dem_SetEventStatus
ARC-8049	SecServices	[IdsM] AR API harmonization for Enable/disable Transmission

ARC-8463	CUCEL	[CUCEL] New AddressMethod support in CUCEL-SwAddrMethod to support the address methods VAR_NON_CACHED_NON_SHARED_CLEARED and VAR_INIT_LOCK_SEMA
ARC-8576	RTE-RipsPlugins	[RTE][CSSafety] Support Mapping to OsTasks of re-entrant server runnables
ARC-8391	CUCEL	EcuC module to support meta-data related to IEEE1722-TP module
ARC-8401	Diag	Update the DEM module to make DemFreezeFrame an optional parameter according to AUTOSAR
ARC-8306	LinStack	[LinIf] Support for NRC78 when for error indication case
ARC-8145	E2EServices	[E2EServices] Provide E2EXf parameter defintion file support of E2E Profile P08m
ARC-7924	E2EServices	E2EXF module supports uint32 for GM custom profile 01
ARC-7405	WdgS	[WdgM] Validation check for Alive Supervision when expected and minimum margin values are identical
ARC-7290	EthStack	[EthSec][TLS][1.2] Support Cipher Suite TLS_P-SK_WITH_AES_128_GCM_SHA256
ARC-7289	EthStack	[EthSec][TLS][1.2] Support Cipher Suite TLS_P-SK_WITH_CHACHA20_POLY1305_SHA256
ARC-4911	SecServices	[CryptoCCL] Separate HKDF Extract and Expand operation as two separate accessible APIs
ARC-9424	CUCEL	EcuC module to support KeepLocalPduBuffer configu-ration parameter for IEEE 1722 TP feature
ARC-9034	WdgS	[WdgS][WdgM] Update for WdgM validation to handle naming convention for WdgM configurations with single master mainfunction
ARC-8743	EthStack	[EthSec][TLS] Expand the Record size limit support for TLS 1.3 and boundary condition Testing on TLS 1.2 for same feature
ARC-8708	SecServices	[CryptoHSM] 3072 bit RSA keys shall be useable with RSA PKCS V1.5 for digital signatures
ARC-7571	RTE-RipsPlugins	RIPS Sig2Srv plugin shall support data conversion for transforming SignalGroups
ARC-7137	SecServices	[KeyM] Report security events with versioned context data
ARC-7136	SecServices	[SecOC] Report security events with versioned context data
ARC-5710	CanStack	[CanIf] Fix CanIfCtrlTrcvRef Issue when CanIfTr-cvWakeupSupport is True

ARC-5705	Diag	[Diag] Attempt counter decremented on delay time expiry
ARC-5371	Diag	[Diag] Memory optimization for event attributes
ARC-6100	RTE-RipsPlugins	SRCom RIPS shall call the RteSerialData.RteCallBack-Function with transformerError only when E2E transformer is involved
ARC-6099	RTE-RipsPlugins	Sig2Srv RIPS shall call the RteSerialData.RteCallBack-Function with transformerError only when E2E transformer is involved
ARC-5592	SecServices	[IdsM] Support versioning of security events in a backward compatible way
ARC-9347	SecServices	[Crypto][CryptoAuCSC] Enhance multithreading robustness
ARC-8808	SecServices	[CryptoAuHSM3] X.509v3 customer certificate handling via CycurHSM3-based CryptoDriver
ARC-8040	SecServices	[Crypto][CryptoAuCSC] Support input and output buffering of data
ARC-5188	SecServices	[CryptoHSM] Seperate HKDF Extract and Expand operation as two accessible APIs
ARC-2237	ConfGen	Confgen shall generate Default EcucValues for Det when it is a required dependency of a configured BSW module. (CanIf, J1939RM, J1939NM)
ARC-7300	ConfGen	Update rule for creating comXf configurations for signalgroup
ARC-3836	ConfGen	Enhancements on LIN configuration import: improvements to LDF importer to support signal groups, E2E and FrameTriggerings
ARC-8778	ConfGen	ConfGen plugin compatible with Eclipse 2024-09 (4.33) and Java 21
ARC-7928	ConfGen	Add to ConfGen the ability to generate a CryptoAuHSM3 configuration
ARC-7590	ConfGen	ConfGen support for E2E profile 7m
ARC-7747	EthStack	Support for Nagle algorithm in TCP-IP, according to IETF RFC 896
ARC-9033	ESM	[ESM][EcuM]EcuM missing Semicolon when Calling StartOS
ARC-8523	Transformers	Adaptations required in SomeIpXf package as part of Java-21 migration
ARC-6978	CanStack	[CanIf] Support for mixed mode operation STANDARD and EXTENDED frames in CanIf on same channel
ARC-9939	SecServices	[Crypto][CryptoAuCSC][CryptoAuHSM3] Robustness and quality enhancements

ARC-4917	RTE-RipsPlugins	RIPS Sig2Srv plugin shall support data conversion for transforming Signals
ARC-9083	ESM	[ESM] Update EcuMDriverInitItem parameter in EcuM-DriverInitListZero to set NULL_PTR
ARC-9644	BSMM	[BSMM][BswM] ARXML declaration of BSW critical section aka ExclusiveArea
ARC-6613	EthStack	[Sd] Implementation of ACL in ServiceDiscovery
ARC-6617	EthStack	Feature testing of SOME/IP-ACL
ARC-10791	ESM	[ESM][EcuM] EcuMEcuMRbNvMCallbackSignature is configured when ecuMRbDisableNvM is active, and a validation warning necessitates further investigation
ARC-655	SecServices	Implement new concept & API: Job context interface
ARC-7600	E2EServices	[E2EServices] Provide E2EXf parameter defintion file support of E2E Profile P07m
ARC-8388	ConfGen	Support for IEEE1722-TP module
ARC-5385	BSMM	Provide Exclusive Area information in BswM
ARC-7792	ConfGen	[MACsec]support for PAE
ARC-6616	ConfGen	Support for importing Sd and SoAd configuration from system template
ARC-1829	ConfGen	[MACsec] Generic Importer Support
ARC-8761	SecServices	[SecOC] Enable maximum PduLength for PduLengthTypes
ARC-8761	SecServices	[SecOC] Enable maximum PduLength for PduLengthTypes
ARC-8660	SecServices	[CryptoHSM] Use KeySetValid API to store crypto-graphic keys permanently
ARC-8390	ComServices	[CSV][LSduR][Prototype] Extend PduR Script to support IEEE1722Tp and EthIf

4 Known Issues

4.1 Critical Issues

No Known Issues

4.2 Major Issues

4.2.1 [rba_FeeFs1x] Entering HighSpeedMode or Cancelling ongoing Job might lead to subsequent write Jobs resulting in failure

```
Defect-704504

Failure:
In the rba_FeeFs1x component, if an ongoing write job is cancelled then subsequent write jobs might
result in failure.
Ongoing jobs are cancelled when the user of the Fee invokes Fee_Cancel API or the user requests
HighSpeedMode operation via the Fee_Rb_EnterHighSpeedMode API.

Impact:
Subsequent Fee_Write, Fee_InvalidateBlock, Fee_Rb_BlockMaintenance jobs might be termintated with
MEMIF_JOB_FAILED.

Impact on FFI (Safety):
- Can the defect directly lead to an endless loop: NO
- Can the defect directly lead to an unexpected memory overwrite: NO
- Can the defect directly lead to an out-of-sequence data buffer usage: NO
- Can the defect directly lead to an exception / reset: NO
- Can the defect directly cause an unexpected, huge number of interrupts: NO

Configuration:
- Affected Configuration: Projects are only affected when all the below conditions are met

1) (FeeRbFsSelect == 'FS1X') AND (FeeRbEnterAndExitHighSpeedModeApis == 'true')
OR
2) (FeeRbFsSelect == 'FS1X') AND (FeeRbCancel == 'true')

Note: If FeeRbEnterAndExitHighSpeedModeApis is true, then FeeRbCancel will also be true otherwise there
will be build abort.

Hint: Check the value of FeeRbFsSelect, FeeRbEnterAndExitHighSpeedModeApis and FeeRbCancel inside the
generated file Fee_EcucValuesPro.arxml.
 If the FeeRbFsSelect is not present in the Fee_EcucValuesPro.arxml, then default value is
(FeeRbFsSelect = 'FS1X')

- Affected Hardware/Device: All
- Compiler Dependency: None

Defective Files:
.Mem.Fee_Stc.rba_FeeFs1x:rba_FeeFs1x_Init.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.2.2 [Dem] Passed status in not updated in the event memory for replacement events

```
Defect-705258

Failure:
When a storage condition is re-enabled, the corresponding replacement event is handled as Passed in the
Event Status, but the same is not updated in the event memory.

Impact:
Incomplete processing of event memory entries corresponding to replacement events.

Impact on FFI (Safety):
 Can the defect directly lead to an endless loop: NO
 Can the defect directly lead to an unexpected memory overwrite: NO
 Can the defect directly lead to an out-of-sequence data buffer usage: NO
 Can the defect directly lead to an exception / reset: NO
 Can the defect directly cause an unexpected, huge number of interrupts: NO

Configuration:
Affected Configuration:
 Dem.DemGeneral.DemEventCombinationSupport is configured as DEM_EVCOMB_ONSTORAGE (AND)

Dem.DemEventParameter.DemStorageConditionGroupRef.DemStorageConditionRef.DemStorageConditionReplacementEventRef
```

```
is configured for any event
Affected Hardware/Device: All
Compiler Dependency: None

Defective Files:
 .Diagnosis.Dem:Dem_Main.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3 Minor Issues

4.3.1 [Crc] Algorithm used to prepare IFX HW acceleration is too slow (runtime problem)

```
Defect-457724

Failure:
The algorithm is used for Crc calculation is too slow and thus it is not worthwhile to use. Note that
there are no issues in the functionality of code, CRC calculation is proper and giving the correct
result however the implementation is not runtime efficient.
Hence this is a performance related issue.

Impact:
Impacted when larger size (Kb) of input data is given for Crc hardware calculation method.

Affected Configuration:
/AUTOSAR_Crc/EcucModuleDefs/Crc/CrcGeneral/CrcRbHardware/CRC_HW_IFX_DEV2_40NM,
/AUTOSAR_Crc/EcucModuleDefs/Crc/CrcGeneral/CrcRbHardware/CRC_HW_IFX_DEV3_40NM,
/AUTOSAR_Crc/EcucModuleDefs/Crc/CrcGeneral/CrcRbHardware/CRC_HW_IFX_DEV4_40NM,
/AUTOSAR_Crc/EcucModuleDefs/Crc/CrcGeneral/CrcRbHardware/CRC_HW_IFX_DEV5_40NM,
/AUTOSAR_Crc/EcucModuleDefs/Crc/CrcGeneral/CrcRbHardware/CRC_HW_IFX_DEV4_65NM

Defective Files:
.E2EServices.Crc:Crc_Prv_Ifx_Hw.h

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.2 [rba_EthTcp] TLS Tx Buffer not released from TCP

```
Defect-658383

Failure:
When SoAd header is enabled and Application data is triggered via SoAd_IfTransmit API, then rba_EthTcp
module shall query the available TLS buffer through rba_EthTls_ProvidePlainTextBuffer() API to fill the
application data. Since received TLS buffer is less than the required buffer it couldn't be used as it
was not freed.

Impact:
Since TLS TX buffer is sequential and circular buffer, Communication is interrupted if TLS Tx buffer is
not freed during this scenario. That means, no communication is possible on this TX buffer anymore.

Configuration:
- Affected Configuration: SoAdIf is TRUE, SoAdPduHeaderEnable is TRUE and TLS is enabled for the
particular socket for secure communication.
- Affected Hardware/Device: NA
- Compiler Dependency: NA

Defective Files:
.EthStack.rba_EthTcp:rba_EthTcp_Tls.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.3 [rba_EthIPv4] Fragments with more fragments (MF) bit 1 and with invalid length (not multiple of 8) are accepted instead of discarding.

```
Defect-659945

Failure:
During reassembly of IPv4 fragments, fragments which are having MF bit set to 1 with invalid length are
accepted. Due to this, reassembly process won't be completed and Reassembly time-out occurs.

Impact:
Reassembly process is interrupted and Reassembly time-out occurs.
```

```
Configuration:
- Affected Configuration: When IPv4 reassembly is enabled.
- Affected Hardware/Device: N/A
- Compiler Dependency: N/A

Defective Files:
.EthStack.rba_EthIPv4:rba_EthIPv4_Receive.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.4 [SoAd] Missing SchM_Exit call in SoAd_AddFragmented-DataInIFRxBuffer

```
Defect-679925

Failure:
Missing SchM_Exit call in SoAd_AddFragmentedDataInIFRxBuffer
In a multicore environment, upon receiving SoAd pdu data, interrupt Locks are applied, however in
certain conditions unlocking is not performed.

Impact:
Software enters TRAP

Configuration:
- Affected Configuration: SoAd is used in multicore environment where SoAd Schm locks are configured
- Affected Hardware/Device: All
- Compiler Dependency: None

Defective Files:
.EthStack.SoAd:SoAd_RxBuffer.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.5 [Dcm] DTC record update is not enabled back when the the current extended data record request is cancelled because of protocol preemption

```
Defect-689135

Failure:
DTC record update is not getting re-enabled when the current service processing of RDTC sub-functions
$04, $06, $10, $18 or $19 is cancelled because of protocol preemption.

Impact:
The sub-functions $04, $06, $10, $18 and $19 of RDTC service($19) won't get a positive response until
an ECU reset, once the same request was pre-empted by another high prio request.

Configuration:
Affected Configuration: sub-function $04, $06, $10, $18 or $19 of RDTC service($19) is configured and
protocol pre-emption is active in the project.

Defective Files:
.Diagnosis.Dcm:DcmDspUds_Rdtc.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.6 [rba_EthTcp] TCP Connection Established with Wildcard Remote Port

```
Defect-691546

Failure:
- when client sends SYN with local port as 0, then ECU should reject it with RSTACK but ECU sending
SYN_ACK, so connection is establishing.
- As per AUTOSAR, port 0 is wildcard (i.e. ANY available port, not a specific port), connection should
establish only with a specified port number.

Impact:
- Non-compliance with AUTOSAR standards.


Configuration:
- Affected Configuration: NA
- Affected Hardware/Device: NA
- Compiler Dependency: NA
```

```
Defective Files:
.EthStack.rba_EthTcp:rba_EthTcp_CheckFrameAndCopyToSocket.c

 ARCCOM-4782

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.7 [CanTp] :Unexpected DET report error upon unexpected FC received from Network

```
Defect-692544

Failure:
Unexpected DET report error CANTP_E_PARAM_CONFIG upon unexpected FlowControl Frame received from
Network.

Impact:
This is violation of the CanTP Autosar Requirements ,due to this the projects that have DET mapped to
DTC/DFC will log unwanted DTC/DFC .
The CanTp Sequence will be considered invalid and the upper layers stopped from receiving additional
data .

Configuration:
- Affected Configuration: Project's which have config parameter CanTpDevErrorDetect set true.
- Affected Hardware/Device:All
- Compiler Dependency:None

Defective Files:
.CanStack.CanTp:CanTp_Prv.h

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.8 [SoAd]] Compilation error when RxPdus are not configured at all in a project.

```
Defect-694028

Failure:
Compilation error when only TxPdus (PduRoutes) are configured and not a single RxPdu (Socket Route) is
configured.

Impact: Compilation failure.

Impact on FFI (Safety):
- Can the defect directly lead to an endless loop: NO
- Can the defect directly lead to an unexpected memory overwrite: NO
- Can the defect directly lead to an exception / reset: NO

Configuration:
- Affected Configuration: When only TxPdu's are configured.
- Affected Hardware/Device: all
- Compiler Dependency: None

Defective Files:
.EthStack.SoAd:SoAd_PBcfg_c.xpt

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.9 [Dcm] Compiler Error due to implicit declaration of Dem interfaces

```
Defect-695086

Failure:
Compiler error due to implicit declaration of the following functions because of missing inclusion of
'Dem_Dcm.h'
Dem_SetDTCFilterByReadinessGroup
Dem_SetDTCFilterByExtendedDataRecordNumber
Dem_DcmGetAvailableOBDMIDs
Dem_DcmGetDTCOfOBDFreezeFrame
Dem_DcmGetDTRData
Dem_DcmGetNumTIDsOfOBDMID
Dem_DcmReadDataOfOBDFreezeFrame

Impact:
Software build failure.

Configuration:
If the Dem component integrated in the project is not from /RTA-CAR AND if the dem.h does not provide
```

```
the declaration of the above listed functions AND one of the below listed condition is satisfied

1. Service $19 subfunction $1A is configured
2. Service $19 subfunction $56 is configured
3. Service $19 subfunction $05 is configured
4. OBD service $06 is configured
5. OBDonUDS is configured with DIDs in the range 0xF6xx

Defective Files:
.Diagnosis.Dcm:DcmDspUds_Rdtc_ReportDTCInfoByDTCReadinessGrpID.c
.Diagnosis.Dcm:DcmDspUds_Rdtc_ReportSupportedDTCExtDataRecord.c
.Diagnosis.Dcm:DcmDspObd_Mode6.c
.Diagnosis.Dcm:DcmDspUds_Rdbi.c
.Diagnosis.Dcm:DcmDspObd_Mode2.c
.Diagnosis.Dcm:DcmDspUds_Rdtc_GetFreezeFrameDataByRecord.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.10 [PduR] CanTp to CanIF routing path configured with RPG throws StackOverflow exception during SW-Build

```
Defect-696567

Failure:
EvaluationException : Index -2 out of bounds for length 2
templates::PduR::common::PduR_GenUtils_If_PBcfg_c.ext[6280,177] on line 124
'.PduR_getEcuFromRoutingPath().pduR.PduR_getComMCRoutes(.PduR_getCurrentVariant()).PduR_getUniqueRoutingPathsForSrc(.PduR_getCur

Impact:
Unable to run BSW PduR_Generate_PB action and goes into exception.

Configuration:
Configuration:
 Affected Configuration: Routing paths from CanTp to CanIf are configured with RoutingPathGroup or
There are Multi Cast routing paths from CanTp to CanIf1 and CanTp to CanIf2 where PduR/PduRBswModules
"CanTp" has PduRCommunicationInterface and PduRUpperModule set to "true"
 Affected Hardware/Device: All
 Compiler Dependency: None

Defective Files:
.ComServices.PduR.scripts:PduR_GenUtils_If_PBcfg_c.ext

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.11 [Dcm] Incorrect check for max memory size on defining a Dynamically defined DID for a single memory record (sub-function 0x02 - defineByMemoryAddress)

```
Defect-696867

Failure:
Wrong length check applied while processing 0x2C with the sub-function 0x02(defineByMemoryAddress) for
single memory record.

Impact:
NRC 0x31 is sent out even when the length of requested memory record is equal to the max size
configured for DDDI.

Configuration:
 Affected Configuration: Service $2C with sub-function 0x02(defineByMemoryAddress) is configured
 Affected Hardware/Device: NA
 Compiler Dependency:NA

Defective Files:
.Diagnosis.Dcm:DcmDspUds_Dddi.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.12 [rba_EthTcp] Mismatch in Data Types for Delay ACK Timer Variables(DlyAckTmr_u8 and DlyAckTimeOut_u32) Causes Delayed ACK Feature to Malfunction

```
Defect-697138

Failure:
The DlyAckTmr_u8 variable's type uint8 has a maximum value of 255, which is insufficient to handle the
```

```
required DlyAckTimeOut_u32 value of more than 255. The DlyAckTimeOut_u32 parameter in the
rba_EthTcp_IncrDlyAckTimer function is of type uint32 and DlyAckTmr_u8 is of type uint8 leading to a
type mismatch.

Impact:
The failure to accommodate the DlyAckTimeOut_u32 value in the DlyAckTmr_u8 variable results in a type
mismatch that significantly affects the operation of the rba_EthTcp_IncrDlyAckTimer function.
Specifically, because DlyAckTmr_u8 can only hold values up to 255, any timeout values greater than 255
will lead to incorrect timer increments. Since the DlyAckTmr_u8 variable can only store values up to
255, if the DlyAckTimeOut_u32 is greater than 255 then the delayed ACK timeout will never occur, and
the ACK frame will not be sent. The remote will keep re-transmitting unacknowledged data and close the
connection after maximum retries.

Configuration:
- Affected Configuration: TcpIpTcpDlyAckEnabled is enabled and TcpIpTcpDelayedAckTimeout is configured
to a value greater than 0.255s (255ms) and TcpIpMainFunctionPeriod is configured to 0.001s (1ms).
- Affected Hardware/Device: N/A
- Compiler Dependency: N/A

Defective Files:
.EthStack.rba_EthTcp:rba_EthTcp_SocketTable.c
.EthStack.rba_EthTcp:rba_EthTcp_Tmr.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.13 [CanIf] : Wrong declaration of loop control variable Index_u8 leading to endless loop during filtering of Rx PDU in CanIf_Rxindication

```
Defect-697720

Failure:
In CanIf_Rxindication API, the loop control variable Index_u8 is of datatype uint8 which can hold a
maximum value of 255.
When the user has configured more than 255 RxPDUs under a HRH, during the Rx Filtering the loop
variable Index_u8 will wrap around to 0 after incrementing from 255.
In this scenario, loop condition never fails and program does not exit the loop.

Impact:
Since the loop control variable Index_u8 is wrongly declared as uint8 instead of uint32, the system
gets struck in an endless loop leading to a trap situation.

Configuration:
- Affected Configuration: Projects which have RxPdus and Configurations where more than 255 RxPdus are
configured under the same HRH
- Affected Hardware/Device: All
- Compiler Dependency: All

Defective Files:
.CanStack.CanIf:CanIf_RxIndication.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.14 [Dcm] Incorrect values generation for DCM_CFG_DEFAULT_P2MAX_TIME and DCM_CFG_DEFAULT_P2STARMAX_TIME

```
Defect-698911

Failure:
Incorrect generation of macro values DCM_CFG_DEFAULT_P2MAX_TIME and DCM_CFG_DEFAULT_P2STARMAX_TIME

Impact:
Due to incorrect generation of macro values P2 Timeout and/or P2* Timeout may occur earlier than
expected. The timeout occurs one main cycle call earlier than expected, i.e., the deviation observed is
based on configured value of DcmTaskTime.
Additionally, if the macro values are used externally (external services/Application code) unexpected
behavior will also be observed.


Configuration:
 Affected Configuration: DcmRbDspSesSecUsedInProtocol is not configured/Configured as UDS.
 Hint : The rounding error will only be observed when DcmDspSessionP2ServerMax and
DcmDspSessionP2StarServerMax for Default Session are configured to values close to their thresholds
where floating-point inaccuracies occur. Verify the generated output to confirm if project is impacted.

 Affected Hardware/Device: NA
 Compiler Dependency: NA

Defective Files:
.Diagnosis.Dcm:DcmDspUdsCfgHTask.java

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.15 [Dcm] Global variable for Asynchronous server call point handling is not reset for routines after a session timeout

```
Defect-699795

Failure:
Global variable used for tracking sequence of Rte calls for Asynchronous server call point handling is
not reset for routines after a session timeout

Impact:
Followed by a stop in Routine services due to a session timeout, if a tester request for Start
subfunction for the same RID is sent then unexpected negative response is observed due to improper
handling of RID state after the previous routine service stop.
(Unexpected negative response is observed as DCM returning Pending continuously. If limited number of
pending response is allowed then finally NRC 10 response is received)


Configuration:
- Affected Configuration: Asynchronous server call point handling is enabled
(DcmRbDspRoutineUseAsynchronousServerCallPoint is set to TRUE) AND DcmRbDspStopRoutineOnSessionChange
is set to TRUE for Routine Identifier.
- Affected Hardware/Device: NA
- Compiler Dependency: NA

Defective Files:
(before AR45.5)
.Diagnosis.Dcm:DcmDspUds_Rc_Lcfg_C.xpt

(from AR45.5)
.Diagnosis.Dcm:DcmDspUdsRcLcfg_C.ftl

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.16 [Sd] Sd will not process SubscribeEventGroup as StopSubscribeEventGroup on reboot detection.

```
Defect-699954

Failure:
1. Client has already subscribed to the EventGroup and Events are getting transmitted.
2. Client sends the frame due to which Server will detect the reboot of Client.
3. Reboot is processed on Server Side and EventGroup data structure is initialized to process
StopSubscribeEventGroup.
4. This initialization is done always from index 0 of Server service data structure.

Impact:
1. The StopSubscribeEventGroup will not be processed for intended Eventhandler but for one of the first
configured Server service Eventhandler .
2. Due to this Events for unintended EventGroup might be stopped.

Configuration:
- Affected Configuration: When more than one
/AUTOSAR_Sd/EcucModuleDefs/Sd/SdConfig/SdInstance/SdServerService is configured, and Service Service
has /AUTOSAR_Sd/EcucModuleDefs/Sd/SdConfig/SdInstance/SdServerService/SdEventHandler configured.
- Affected Hardware/Device: All
- Compiler Dependency: None

Defective Files:
.EthStack.Sd:Sd_MsgInterpreter.c
Arc.Bsw.EthStack.Sd:Sd_MsgInterpreter.c

ARCCOM-6247

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.17 [Dcm] Issue with Extended Session Transition when protocol type is KWP

```
Defect-700789

Failure:
An issue was observed in the generation of Dcm_Dsld_KWPsupported_sessions_acu8[], where an extra
element is incorrectly added when DcmRbDspKWPDefaultSesRef is configured and the protocol along with
DcmRbDspSesSecUsedInProtocol is set to KWP. This leads to incorrect referencing during session
transitions.
```

```
Impact:
Session transition from Default to Extended is not happening for a valid extended session request, when
protocol is configured as KWP.

Configuration:
The defect occurs when the protocol configured is KWP, DcmRbDspSesSecUsedInProtocol is configured as
KWP and DcmRbDspKWPDefaultSesRef is default session.

Defective Files:
.Diagnosis.Dcm:DcmLcfgDslCTask.java

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.18 [EcuM] Multicore synchronization for sleep is not performed within the EcuM.

```
Defect-700833

Failure:
Sleep is not performed in case of multicore project due to lack of synchronization across master and
slave core.

Impact:
This defect is only impacted for Multicore project which has configured EcuMSleepMode.Sleep request is
reverted back In EcuM when master core main function is executed before the slave core's

Impact on FFI (Safety):
Can the defect directly lead to an endless loop: NO
Can the defect directly lead to an unexpected memory overwrite: NO
Can the defect directly lead to an exception / reset: NO

Configuration:
- Affected Configuration:EcuM->EcuMConfiguration->EcuMCommonConfiguration->EcuMSleepMode
- Affected Hardware/Device:Nil
- Compiler Dependency:Nil

Defective Files:
.ESM.EcuM:EcuM_MainFunction.c
Hint: No comments allowed after each Defective file name (<COMPONENT>:<FILE>).

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.19 [Dem] GeneralCBMonitorStatusChanged R-Port is not generated for some configurations

```
Defect-701029

Failure:
Dem invokes the GeneralCBMonitorStatusChanged callback in the source file but does not generate the
related R-port in the SWCD file.

Impact:
The software build process is aborted due to the compilation error and the executable cannot be
generated.

Impact on FFI (Safety):
 Can the defect directly lead to an endless loop: NO
 Can the defect directly lead to an unexpected memory overwrite: NO
 Can the defect directly lead to an out-of-sequence data buffer usage: NO
 Can the defect directly lead to an exception / reset: NO
 Can the defect directly cause an unexpected, huge number of interrupts: NO

Configuration:
 Affected Configuration: (Dem.DemGeneral.DemGeneralInterfaceSupport is true) and
(Dem.DemConfigSet.DemEventParameter.DemCallbackMonitorStatusChanged is not configured for any event)
 Affected Hardware/Device: All
 Compiler Dependency: None

Defective Files:
.Diagnosis.Dem:Dem_Cfg_SWCD_arxml.xpt

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.20 [LinIf] Incorrect assignment of NAD in AssignNad service

```
Defect-701880
```

```
Failure :
Incorrect node address received from the positive response of the AssignNAD node configuration service
with Service ID (SID) as B0.

Impact:
The slave has returned an erroneous positive response to the master. As a result, the response
containing the new NAD may lead to address conflicts.

Configuration:
 Affected Configuration: LinIf is used as a Slave Node
(/AUTOSAR_Lin/EcucModuleDefs/Lin/LinGlobalConfig/LinChannel/LinNodeType is LinIfSlave) .
 Affected Hardware/Device:No
 Compiler Dependency:No

Defective Files:
.LinStack.LinIf:LinIf_Tp_Slave.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.21 [BswM] Removal of E002900 RTE implementation requires OsResource 'Rte_EA_BSWImpl29_BSWIMPL_BswM_BswMEA'

```
Defect-701891

Failure:
Error E002900/Warning W002900 ( The RTE implementation requires OsResource
'Rte_EA_BSWImpl29_BSWIMPL_BswM_BswMEA') occurs during the RTE execution when strict-config-check=on /
strict-config-check=off. This warning expects a OsResource configuration when the EcuCRbLegacySchMInUse
parameter is set to true or unconfigured. But Rte_EA_BSWImpl29_BSWIMPL_BswM_BswMEA should not be
generated in case of EcuCRbLegacySchMInUse parameter is set to true or unconfigured.

Impact:
This error/warning arises only when the project does not configure the EcuCRbLegacySchMInUse parameter
and sets the EcuCRbLegacySchMInUse parameter to true. Project is not impacted only when
EcuCRbLegacySchMInUse parameter is configured to false.

Impact on FFI (Safety):
- Can the defect directly lead to an endless loop: NO
- Can the defect directly lead to an unexpected memory overwrite: NO
- Can the defect directly lead to an exception / reset: NO
- Can the defect directly cause an unexpected, huge number of interrupts: NO

Configuration:
- Affected Configuration: EcuC->EcuCRbSettings->EcuCRbLegacySchMInUse
- Affected Hardware/Device: No
- Compiler Dependency: No

Defective Files:
.BSMM.BswM:BswM_Cfg_BSWMD_arxml.xpt

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.22 [CanTrcv] : Wake up reason is not updated by calling CanTrcv_GetBusWuReason for Dio Devices

```
Defect-702304

Failure:
CanTrcv_GetBusWuReason() API returns E_NOT_OK and the wake up reason is never updated for Dio Devices
in case of a wake up detected.

Impact:
The user is not able to detect the wake up reason for Dio devices, further impact to be analyzed by the
project.

Configuration:
 Affected Configuration: Projects where CanTrcvRbHardwareType is configured as TJA1041, TJA1043,
TLE6251, TJA1463 or ATA6571 AND CanTrcvWakeUpSupport configured as "CANTRCV_WAKEUP_BY_POLLING".
 Affected Hardware/Device: TJA1041, TJA1043, TLE6251, TJA1463, ATA6571
 Compiler Dependency: None

Defective Files:
.CanStack.CanTrcv:CanTrcv_FetchWakeUp.c
.CanStack.CanTrcv:CanTrcv_PrepareWakeUp.c
.NetDrvLS.CanHwComps.CanTrcv:CanTrcv_FetchWakeUp.c
.NetDrvLS.CanHwComps.CanTrcv:CanTrcv_PrepareWakeUp.c
Arc.Bsw.NetDrvLS.CanHwComps.CanTrcv:CanTrcv_FetchWakeUp.c
Arc.Bsw.NetDrvLS.CanHwComps.CanTrcv:CanTrcv_PrepareWakeUp.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.23 [CanTrcv] : CanTrcv_SetPNActivationState() request is not processed for TCAN1145

```
Defect-702308

Failure:
CanTrcv_SetPNActivationState() returns E_OK but the PN activation state is not actually changed in the
hardware for TCAN1145.

Impact:
User will not be able to disable or enable the partial networking after initialization of CanTrcv
driver.

Configuration:
 Affected Configuration: Projects where CanTrcvRbHardwareType is configured as TCAN1145 and
CanTrcvHwPnSupport is set as True.
 Affected Hardware/Device: TCAN1145
 Compiler Dependency: None

Defective Files:
.CanStack.CanTrcv:CanTrcv_PrepareWakeUp.c
.NetDrvLS.CanHwComps.CanTrcv:CanTrcv_PrepareWakeUp.c
Arc.Bsw.NetDrvLS.CanHwComps.CanTrcv:CanTrcv_PrepareWakeUp.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.24 [Dem] Datatype of internal variables is too small in some configurations

```
Defect-703584

Failure:
The following internal variables are defined with a datatype that is too small to hold the complete
range of possible values:
 Dem_AllEventsStatusChangedFnc[]
 Dem_AllMonitorsStatusChangedFnc[]
 Dem_AllDTCGroupsParam[]
 Dem_DtcGroupIdMapToDtcId[]
 Dem_Cfg_J1939IumprGroupSPN[]
 Dem_Cfg_EnvFreezeFrame[]
 Dem_Cfg_EnvEventId2EnvData[]
 rba_DemObdBasic_EventId2WWHOBDFreezeFrame[]
 Dem_MapEvMemToDTCGroupCount[]
 Dem_Cfg_EnvFreezeFrame2Did[]

Impact:
An overflow may occur in the data structures mentioned above, leading to wrong data values being
stored, reported, or processed.

Impact on FFI (Safety):
 Can the defect directly lead to an endless loop: NO
 Can the defect directly lead to an unexpected memory overwrite: NO
 Can the defect directly lead to an out-of-sequence data buffer usage: NO
 Can the defect directly lead to an exception / reset: NO
 Can the defect directly cause an unexpected, huge number of interrupts: NO

Configuration:
- Affected Configuration:
 - Count (Dem.DemConfigSet.DemEventParameter.DemCallbackEventUdsStatusChanged) > 255 OR
 - Count (Dem.DemConfigSet.DemEventParameter.DemCallbackMonitorStatusChanged) > 255 OR
 - Count (Dem.DemGeneral.DemFreezeFrameClass) > 255 OR
 - Count (Dem.DemGeneral.DemRatio) > 255 OR
 - (Count (Dem.DemGeneral.DemEventMemorySet.DemUserDefinedMemory) + Count
(Dem.DemGeneral.DemEventMemorySet.DemUserDefinedMemory.DemGroupOfDTC) + Count
(Dem.DemGeneral.DemEventMemorySet.DemPrimaryMemory.DemGroupOfDTC)) > 254
- Affected Hardware/Device: All
- Compiler Dependency: None

Defective Files:
.Diagnosis.Dem:Dem_Events_DataStructures_Cfg.xpt
.Diagnosis.Dem:Dem_Prv_J1939Dcm.c
.Diagnosis.Dem:Dem_DTCs_Cfg_h.xpt

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.25 [Dcm] Opstatus Fails to Reset to DCM_INITIAL During Condition Check Read (Service 0x22)

```
Defect-703681

Failure:After processing the condition check read function for the first signal(DCM_E_PENDING followed
by E_OK), OpStatus remains DCM_PENDING for the following signals of a DID.

Impact:
Once the first signal of the DID has been processed, the OpStatus will be always DCM_E_PENDING for the
remaining signals of the DID during the condition check read function call.

Configuration:
 Affected Configuration: Service $22 supported. DID with multiple signals, DataUsePort to
USE_DATA_ASYNCH_CLIENT_SERVER and UseAsynchronousServerCallPoint to TRUE.
 Affected Hardware/Device: NA
 Compiler Dependency:NA

Defective Files:
.Diagnosis.Dcm:DspUds_Did_Support.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.26 [CanTrcv] : TCAN1145 is not able to wake-up by pattern when partial networking is configured as not supported

```
Defect-704081

Failure:
When Partial networking feature is disabled in configuration, TCAN1145 does not wake up by pattern and
only wakes up after 32 frames, by exceeding error frame counter.

Impact:
User will not be able to wake up Trcv by pattern, hence no communication possible with the node via
passive wakeup.

Configuration:
 Affected Configuration: Projects where CanTrcvRbHardwareType is configured as TCAN1145 and
CanTrcvHwPnSupport is set as False.
 Affected Hardware/Device: TCAN1145
 Compiler Dependency: None

Defective Files:
.CanStack.CanTrcv:CanTrcv_PBcfg.c
.CanStack.CanTrcv:CanTrcvProc.java
.NetDrvLS.CanHwComps.CanTrcv:CanTrcv_PBcfg.c
.NetDrvLS.CanHwComps.CanTrcv:CanTrcvProc.java
Arc.Bsw.NetDrvLS.CanHwComps.CanTrcv:CanTrcv_PBcfg.c
Arc.Bsw.NetDrvLS.CanHwComps.CanTrcv:CanTrcvProc.java

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.27 [PduR] Truncation of Positive Integer in ConfLen Field Assignment of PduR_Buf_If_dynamic Structure

```
Defect-704763

Failure:
Compiler warning [MISRA C:2012 Rule 10.3 QAC_2900 ] "Implicit Truncation of Positive Integer Constant
in Smaller Unsigned Type".

Impact:
Gateway will not copy all data of the Pdu if Pdu size is greater than 255 but less than the configured
value.

Configuration:
 Affected Configuration: PduRBswModules with PduRCommunicationInterface as True and PduRTriggerTransmit
as True. PduRRoutingPath: PduRSrcPdu : Lower Layer IF and PduRDestPdu : Lower Layer IF configured as
gateway
 Affected Hardware/Device: All
 Compiler Dependency: None

Defective Files:
.ComServices.PduR.scripts:PduR_Gw_IfBuf_PBcfg_c.xpt

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.28 [CanTrcv] : SPI communication aborts sporadically when CanTrcv tries to access TJA1145 device

```
Defect-704956

Failure:
SPI communication aborts sporadically when CanTrcv tries to access TJA1145 device.

Impact:
CanTrcv will not be able to control the TJA1145 device as SPI communication fails.
It may lead to Can communication failure.

Configuration:
 Affected Configuration:
 CanTrcvRbHardwareType is configured as TCAN1145, TJA1145, TLE9255, ATA6570 or ATA6572
 AND
 SPI communication is configured as Asynchronous (see CANTRCV_SPI_TRANSMIT defined in
CanTrcv_Cfg_IntCode.h).
 Affected Hardware/Device: All SPI devices (TCAN1145, TJA1145, TLE9255, ATA6570 and ATA6572).
 Compiler Dependency: None

Defective Files:
.CanStack.CanTrcv:CanTrcv_MainFunction.c
.NetDrvLS.CanHwComps.CanTrcv:CanTrcv_MainFunction.c
Arc.Bsw.NetDrvLS.CanHwComps.CanTrcv:CanTrcv_MainFunction.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.29 [Dem] Missing check for the active protocol when retrieving OBDonUDS freeze frame

```
Defect-705110

Failure:
The callback function configured under Dem.DemGeneral.DemGeneralOBD.DemRbGeneralOBD.DemRbOBDProtocolFnc
indicates the protocol used for communication with the scan tool. In case of detecting malfunctions,
Dem captures the OBDonUDS freeze frame only if the used protocol is OBDonUDS (i.e., the callback
returns DEM_RB_J1979_2). However, the APIs to read the freeze frame contents do not check for the used
protocol.

Impact:
1. For the UDS requests 0x19 04 00 and 0x19 04 F0, a positive response with random data is sent to the
tester, instead of a negative response.
2. If the configuration parameter DemRbProvidesOBDSnapshotDataAsPartOfUDSRequestForRecordFF = true,
then records 0x00 and 0xF0 (with random data) are sent as part of the response for the UDS request 0x19
04 FF.
Note: Some affected versions of the software do not support the parameter
DemRbProvidesOBDSnapshotDataAsPartOfUDSRequestForRecordFF. In such cases, only the first point above is
relevant.

Configuration:
- Affected Configuration: (Dem.DemGeneral.DemGeneralOBD.DemRbGeneralOBD.DemRbOBDProtocol =
DEM_RB_BOTH_PROTOCOL)
- Affected Hardware/Device: All
- Compiler Dependency: None

Defective Files:
.Diagnosis.Dem:Dem_EvMem.c
.Diagnosis.Dem:DemEvMemApi.c

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.30 [Dcm] The value of DcmDspSecurityDelayTime is incorrectly generated in the code

```
Defect-706201

Failure:
The security delay count of DcmDspSecurityDelayTime and DcmDspSecurityDelayTimeOnBoot is generated
incorrectly because of incorrect rounding mechanism.

Impact:
Security attempt delay time will be more than what is configured.
Security delay time on boot will be less than what is configured.

Configuration:
Where DcmDspSecurityDelayTime and DcmDspSecurityDelayTimeOnBoot are configured.(Security Access Service
```

```
is activate (0x27))
Important: Not all configured values are affected, the rounding error may not occur for certain
combination of DcmTaskTime and DcmDspSecurityDelayTime/DcmDspSecurityDelayTimeOnBoot. Please check that
the generated value of delay timers in Dcm_Dsp_Security[] is matching with the following calculation:
ConfiguredDelayTime/DcmTaskTime.

Defective Files:
.Diagnosis.Dcm:DcmDspUdsSecaTask.java

Contact ETAS to discuss the latest updates and workarounds.
```

4.3.31 [Dcm] Functional tester present doesn't work if parallel tester is enabled

```
Defect-706335

Failure:
if DcmRbMaxRequestsInParallel is configured as 2, then the The S3 timeout is not reloaded on reception
of functional tester present request from the same connection through which the non default session was
requested.

Impact:
ECU does not remain in non-default session even though TesterPresent service request is sent to keep
ECU in Non-Default session

Configuration:
 Affected Configuration: ParallelTester feature enabled (DcmRbMaxRequestsInParallel configured to 2)
 Affected Hardware/Device: NA
 Compiler Dependency: NA

Defective Files:
.Diagnosis.Dcm:Dcm_Prv_Dsl_Reception.h

Contact ETAS to discuss the latest updates and workarounds.
```

5 Hotfix Information

No hotfixes for RTA-BSW v12.7.0 are available at this time.

6 Contact, Support and Problem Reporting

6.1 Technical Support

Technical support is available to all RTA users with a valid support contract. If you do not have a valid support contract, please contact your regional sales office (see below).

The best way to get technical support is by email. Any problems or questions about the use of the product should be sent to: rta.hotline@etas.com

If you prefer to discuss your problem with the technical support team, you can all the support hotline on: +44 (0)1904 562624

The hotline is available during normal office hours (0900-1730 GMT/BST)

In either case, it is helpful if you can provide the following relevant information when contacting technical support:

- Your support contract number
- The versions of the ETAS tools you are using
- The version of the compiler tool chain you are using
- The command line (or reproduction of steps) that result in an error message
- The error messages or return codes you received (if any)
- Your .xml and .arxml files
- Your OS configuration files
- The diagnostic.dmp file (if it was generated)

6.2 General Enquiries

6.2.1 ETAS Global Headquarters

ETAS GmbH Borsigstrasse 24 70469 Stuttgart Germany	Phone:	+49 711 3423-0
	Fax:	+49 711 3423-2106
	WWW:	www.etas.com

6.2.2 ETAS Local Sales and Support Offices

Contact details for your local sales office and local technical support team (where available) can be found on the ETAS web site:

ETAS subsidiaries	WWW:	www.etas.com/en/contact.php
ETAS technical support	WWW:	www.etas.com/en/hotlines.php