

HOME INSPECTION REPORT

Property: 2847 Winfield Blvd, San Jose, CA 95128

Inspection Date: April 28, 2026

Report #: INS-2025-04281

Prepared for: David & Maria Santos

Prepared by: Robert Anderson, ASHI Certified Inspector #247891

Anderson Home Inspections, LLC

License #HI-2019-04872 | (408) 555-0147

NOTICE: This report is the exclusive property of Anderson Home Inspections, LLC and the client(s) named above. Use by any unauthorized persons is prohibited. This inspection was performed in accordance with the Standards of Practice of the American Society of Home Inspectors (ASHI).

EXECUTIVE SUMMARY

This single-family residence was built in 2006 and contains approximately 1,847 square feet of living space. The property features 3 bedrooms, 2.5 bathrooms, an attached 2-car garage, and a landscaped rear yard. The home is served by city water and sewer, natural gas, and 200 amp electrical service.

SUMMARY OF SIGNIFICANT FINDINGS:

- [SAFETY] Exposed wiring junction box in garage lacks cover plate. Repair immediately.
- [SAFETY] Absence of GFCI protection at two exterior outlets. Upgrade recommended.
- [MAJOR] Roof composition shingles show significant granule loss and curling on south-facing slope. Estimated remaining life 2-4 years. Budget for replacement (\$12,000-\$18,000).
- [MAJOR] Evidence of past moisture intrusion at master bedroom ceiling. Stain is dry and appears inactive but source should be confirmed. Possible flashing or roof-related.
- [MAJOR] HVAC condenser unit (18 years old) showing corrosion on condenser coils. Functional but nearing end of useful life. Budget for replacement (\$4,000-\$7,000).
- [MODERATE] Hairline crack in foundation east wall, approximately 3 feet horizontal. Appears cosmetic/settling. Monitor for changes. If crack widens, consult structural engineer.
- [MODERATE] Two garage outlets tested open ground. Repair needed for safety.
- [MODERATE] Kitchen faucet has slow drip. Washer replacement needed (~\$150).
- [MINOR] Driveway hairline crack near garage apron. Seal to prevent water infiltration.
- [MINOR] Caulking deteriorated at multiple window frames. Recaulk for weatherproofing.
- [MINOR] Fence post at rear property line shows wood rot at base. Replace before failure.

ROOFING

Type:	Composition shingle (architectural)
Age:	Approximately 18 years (original to construction)
Condition:	DEFICIENT - Significant granule loss observed on south-facing slope. Multiple areas of curling and lifting shingles. Ridge cap appears intact. Flashing at chimney and vent pipes shows minor deterioration. Gutters and downspouts functional with minor debris accumulation.
Estimated Remaining Life:	2-4 years
Estimated Replacement Cost:	\$12,000-\$18,000 for complete re-roof
Recommendation:	Obtain quotes from licensed roofing contractors. Plan for replacement within 2-3 years. Monitor for any active leaks, especially at flashing points.

EXTERIOR

Siding:	Fiber cement (HardiePlank). Good condition overall. Minor paint touch-up needed at north wall.
Trim:	Wood trim at eaves. No visible rot or damage.
Windows:	Dual-pane vinyl. Functional. Caulking deteriorated at 4 window frames - recaulk recommended.
Doors:	Front entry: fiberglass, good condition. Sliding glass: aluminum frame, tracks need cleaning, rollers functional.
Driveway:	Concrete. Hairline crack near garage apron (~4 feet long). Cosmetic. Seal to prevent water infiltration.
Walkways:	Concrete front walkway. Good condition, no trip hazards.
Fence:	Wood privacy fence. Generally good. One post at rear shows wood rot at base - replace.
Grading/Drainage:	Positive grade away from foundation on 3 sides. East side appears level - monitor during rain.

FOUNDATION/STRUCTURE

Type:	Concrete perimeter foundation with slab-on-grade
Condition:	MARGINAL - Hairline horizontal crack on east wall exterior, approximately 3 feet long. Crack width is less than 1/8 inch and appears consistent with normal settling. No displacement or vertical offset observed. Interior inspection shows no corresponding cracks.
Crawl Space:	N/A - slab-on-grade construction
Recommendation:	Monitor crack width seasonally. Mark endpoints with pencil and date. If crack widens beyond 1/4 inch or shows vertical displacement, consult a licensed structural engineer. Estimated cost for engineer evaluation: \$400-\$600.

ELECTRICAL

Panel:	200 amp main panel in garage. Square D brand. All breakers labeled. No double-tapped breakers.
Wiring Type:	Copper throughout (Romex NM-B). Appropriate for 2006 construction.
Outlets/Switches:	Tested representative sampling. Two garage outlets showed open ground - repair needed. All GFCI outlets in kitchen and bathrooms tested and functioning.
Deficiency:	SAFETY: Exposed junction box in garage ceiling lacks cover plate. Must be repaired immediately. Estimated cost: \$50-\$100.
Deficiency:	SAFETY: Two exterior outlets lack GFCI protection. Current code requires GFCI for all exterior outlets. Estimated cost: \$150-\$300 for electrician upgrade.

PLUMBING

Supply Lines:	Copper main. PEX distribution (typical for 2006 construction). Good condition.
Drain Lines:	ABS drain/waste/vent. Functional. All drains tested, no slow drains detected.
Water Heater:	AO Smith 50-gallon gas water heater. Installed 2020 (sticker confirms). Properly strapped per CA requirements. T&P valve present and discharge pipe properly routed.
Fixtures:	Kitchen faucet: Slow drip from spout when off. Likely needs washer replacement (\$100-\$150). All other fixtures functional with adequate flow and drainage.
Hose Bibs:	Two exterior hose bibs tested. Functional, no visible leaks.

HVAC

Heating:	Lennox forced-air gas furnace. Approximately 18 years old (original). Functional at time of inspection. Filter was dirty - recommend replacement.
Cooling:	Lennox split system A/C. Condenser unit 18 years old. Condenser coils show corrosion. Unit produced 17°F temperature differential at registers (acceptable range: 15-20°F). Functional but nearing end of useful life.
Estimated Remaining Life:	2-5 years for both furnace and condenser
Estimated Replacement Cost:	\$4,000-\$7,000 for A/C condenser; \$3,000-\$5,000 for furnace; \$7,000-\$11,000 for complete system replacement
Ductwork:	Flex duct in attic. Connections appear secure. Minor compression at one run - may reduce airflow to master bedroom.
Thermostat:	Nest programmable thermostat. Functional.

INTERIOR

Walls/Ceilings:	Generally good condition. Minor cracks in living room wall near window (cosmetic/settling). Water stain on master bedroom ceiling approximately 2 feet in diameter. Stain appears dry and inactive. No moisture detected with meter at time of inspection. Source should be confirmed - may be related to roof flashing deterioration noted above.
Floors:	Hardwood in living areas (good condition). Tile in bathrooms and kitchen (good condition). Carpet in bedrooms (fair condition, normal wear).
Kitchen:	Appliances tested: Range, oven, dishwasher, garbage disposal, microwave - all functional. Countertops: granite, good condition. Cabinets: wood, good condition, soft-close hinges.
Bathrooms:	Master bath: Tile shower, no visible grout issues. Exhaust fan functional. Hall bath: Tub/shower combo. Functional. Caulk at tub/tile junction needs refreshing.

ATTIC

Access:	Pull-down stair in hallway. Attic accessed and inspected.
Insulation:	Blown fiberglass, approximately R-30 (adequate for CA Zone 4).
Ventilation:	Ridge vent and soffit vents. Appears adequate.
Observations:	No visible signs of active leaks, rodent activity, or mold. Roof decking appears dry and sound from interior.

GARAGE

Type:	Attached 2-car garage with automatic door openers (2 remotes)
Condition:	Good overall. Auto-reverse on door openers tested and functional.
Fire Separation:	Fire-rated drywall appears intact between garage and living space. Self-closing door to house present and functional.
Deficiency:	Junction box on ceiling missing cover plate (SAFETY - noted above). Two outlets open ground (noted in Electrical section).

LIMITATIONS AND DISCLAIMERS

This inspection is a visual examination of the readily accessible areas of the property at the time of the inspection. The inspection is not technically exhaustive. Areas that were inaccessible, concealed, or obstructed were not inspected. This report does not include inspection of: swimming pools/spas, outbuildings, underground systems, environmental hazards (asbestos, lead, mold, radon), pest/wood-destroying organisms, or geological conditions.

Estimated repair costs are provided as general guidance only and are based on typical contractor pricing in the San Jose, CA metropolitan area as of the inspection date. Actual costs may vary. Obtain professional estimates before making purchasing decisions.

This report is not a guarantee or warranty, expressed or implied, regarding the condition of the property. The inspector assumes no liability for conditions that develop after the inspection date.

Inspector: Robert Anderson, ASHI #247891

Date: 04/28/2026

Anderson Home Inspections, LLC