HOORVIA - OBD2 CODES CHART: PRINTABLE CHECK ENGINE CODE REFERENCE

Quick Reference Cheat Sheet · A4 Printable

Reference Charts · Sheet #1

Code	Meaning	System	Common Cause	First Check
P0300	Random / Multiple Cylinder Misfire	Ignition / Powertrain	Bad spark plugs, faulty ignition coils, vacuum leaks	Flashing light means active misfire; swap coils to isolate
P0301	Cylinder 1 Misfire Detected	Ignition / Powertrain	Failing coil or spark plug on cylinder 1	Move the cylinder-1 coil; if the misfire moves, replace the coil
P0171	System Too Lean (Bank 1)	Fuel & Air Metering	Vacuum leak, faulty MAF sensor, clogged injector	Listen for a vacuum hiss and inspect the MAF sensor
P0174	System Too Lean (Bank 2)	Fuel & Air Metering	Same as P0171, on the engine's second bank	Check intake boots and fuel trim on V6/V8 engines
P0420	Catalyst Efficiency Below Threshold (Bank 1)	Emissions	Failing catalytic converter, bad O2 sensor, exhaust leak	Rule out exhaust leaks, then check the O2 sensor waveform
P0430	Catalyst Efficiency Below Threshold (Bank 2)	Emissions	Failing catalytic converter on bank 2	Check both cats if P0420 and P0430 appear together
P0442	EVAP System Small Leak Detected	Emissions / EVAP	Loose gas cap or cracked EVAP hose	Tighten or replace the gas cap first
P0455	EVAP System Large Leak Detected	Emissions / EVAP	Missing or loose gas cap, damaged EVAP hose	Check the gas cap, then inspect hoses and purge valve
P0128	Coolant Temp Below Thermostat Temp	Cooling System	Thermostat stuck open, low coolant	Watch the gauge on cold start; a weak thermostat is the usual fix
P0401	EGR Flow Insufficient	Emissions	Clogged EGR valve or carbon-blocked passages	Clean or replace the EGR valve
P0101	MAF Circuit Range / Performance	Fuel & Air Metering	Dirty or failing mass airflow sensor	Clean the MAF sensor with proper cleaner
P0135	O2 Sensor Heater Circuit (Bank 1, Sensor 1)	Emissions	Failed heating element inside the O2 sensor	Replace the sensor; a cold sensor reads slowly

PRO TIP: Check the gas cap first: Tighten or replace the cap before anything else: it fixes most P0442 and P0455 EVAP codes.