

- **Adjusting Zoom** Press **[F2]** to display a rectangle (zoom window) indicating the area to be magnified. Use **[PAGE DOWN]** to decrease the size of the zoom window (zooming in), and use **[PAGE UP]** to increase the size of the zoom window (zooming out). Use the Cursor Arrow keys to move the zoom window to the desired location and press **[ENTER]** to complete the zoom and rescale the tool path window. The locator window (small view at the bottom right) shows the entire table with an outline of where the Tool Path window is zoomed. Tool Path window is cleared when zoomed, and the program must be re-run to view the tool path. Press **[F2]** and then **[HOME]** to expand the Tool Path window to cover the entire work area.
- **Control Status** The lower left portion of the screen displays control status. It is the same as the last four lines of all other displays.
- **Position Pane** The position pane displays axes locations just as it would during a live part run.

Graphics mode is run from Memory, MDI, or Edit modes. To run a program:

1. Press **[GRAPHICS]**. Or press **[CYCLE START]** from the active program pane in Edit mode to enter Graphics mode.
2. Press **[CYCLE START]**.



NOTE: *Not all machine functions or motions are simulated in graphics.*

4.12.2 Axis Overload Timer

When a spindle or an axes current load is 180% load, a timer starts and displays in the **POSITION** pane. The timer starts at 1.5 minutes and counts down to zero. An axis overload alarm *SERVO OVERLOAD* displays when the time has expired to zero.

4.13 Run-Stop-Jog-Continue

This feature lets you stop a running program, jog away from the part, and then start the program again.

1. Press **[FEED HOLD]**.
Axis motion stops. The spindle continues to turn.
2. Press **[X]**, **[Y]** or **[Z]**, then press **[HANDLE JOG]**. The control stores the current X, Y, and Z positions.



NOTE: *You can jog only the X, Y, and Z Axes in this mode.*