

1. Select **Jog** mode.
2. Press **[TS <—]** to jog the tailstock at feed speed toward the chuck, or press **[TS —>]** to jog the tailstock at feed speed away from the chuck.
3. Press **[TS RAPID]** and **[TS <—]** simultaneously to move the tailstock at rapid speed toward the chuck. Or, press **[TS RAPID]** and **[TS —>]** simultaneously to move the tailstock at rapid speed away from the chuck. The control reverts to the last jogged axis when the keys are released.

4.12 Features

Haas operation features:

- Graphics Mode
- Background Edit
- Axis Overload Timer

4.12.1 Graphics Mode

A safe way to troubleshoot a program is to run it in Graphics mode. No movement occurs on the machine, instead the movement is illustrated on the screen.

The Graphics display has a number of available features:

- **Key Help Area** The lower left of the graphics display pane is the function key help area. Function keys that are currently available are displayed here with a brief description of their usage.
- **Locator Window** The lower right part of the pane displays the whole table area and indicates where the tool is currently located during simulation.
- **Tool Path Window** In the center of the display is a large window that represents a view of the work area. It displays a cutting tool icon and tool paths during a graphics simulation of the program.



NOTE:

Feed motion is displayed as fine continuous lines. Rapid moves are displayed as dotted lines. Setting 4 disables the dotted-line display. The places where a drilling canned cycle is used are marked with an X. Setting 5 disables the X display.