FCC CLUTCH INDIA	H INDIA	OPERATIO	OPERATION STANDARD (B)		Doc. No. : FCC-APQP-QF Rev. No. : 01 Rev. Date : 21.02.2018	2P-QFO-04(b) 2018		
					SHEET10 OF1	13.		
OPERATION NO.	7	OPERATION NAME	FINAL TORQUE, SPRING DETECTION & MOVEMENT CHECK	Ж	मेटीरियल की पहचान	और	रखरखाव के निर्देश	
PREVIOUS OPN.	BOLT TIGHTENING WITH MULTI NUT RUNNER	NEXT OPERATION	TOTAL HEIGHT VARIATION CHECKING, SLIT JIG CONFIRMATION AND LOT STAMPING	,				
M/C NAME	LASER MARKING M/C	M/C NO.			मेटीरियल		रखरखाव	
PART NAME	CLUTCH ASSY		(M-23-E0028) HRHS HAHB	-		बिन,	साध	रखे
MODEL	K3CA	SETTING PRESSURE	ונים בורכים בור מאומים בו וופו	2. मशीन के द्वारा रिजेक्शन	नेक्शन		लाल बिन में रखें।	
TOOLS		JIG / FIX NAME	SLIT JIG & INDEXING	3. सप्लायर की गलती			पीले बिन में रखें।	
VISUAL AIDS		JIG / FIX NO.		4. शुद्धिकरण			पीले बिन में रखें।	
				नोट:– शुद्धिकरण केवल	. इंजीनियर / सुपरवाईज़र	के द्वारा शिफ्ट के अन्त	त में किया जाए।	
S. NO.	OPERATION	POINTS & CONTROL ITEMS	S CHECKING METHOD	МЕТНОБ	RESP.	ALTERNATE	INSP. FRQY.	DATA ENTRY
		Click' ध्वनि होने तक टाईट करें।	हाथ से महसूस करके चैक	रके चैक करे।		,	100%	OZ
क्लाच एसेम्बली : लिफटर के ईनर रैन्च की सहायत कसे।	क्लाच एसेम्बली ले और जिंग में सैट करें। फिर लिफटर के ईनर डाया में लोकेटर को रखकर टोरक रैन्च की सहायता सें बोल्टो को 'Click' ध्वाने होने तक कसे।	TORQUE TIGHTENING - 9.8 ~ 14N·m (100 ~140 kgf·cm) BLUE COLOR MARKING SHOULD BE DONE ON ALL BOLTs (03 Nos) (TORQUE WRENCH VALUE 100 kgf.cm)	NE ON ALL BOLTs टॉर्क रेन्च से चैक करे।		OPERATOR & INSP.	BACKUP TORQUE WRENCH	100%	N=5/SETUP & SHIFT
2 SPRING CONFIF	SPRING CONFIRMATION POKA YOKE	SPRING MISS CHECK AS PER LOAD TABLE BELOW PRESENCE OF ALL 03 SPRING LOAD SHOULD BE 1.2	E BELOW SULD BE 1.2 ~ SPRING CONFIRMATION MACHINE	TION MACHINE	OPER.		100%	
		U.95 KN.			INSP.		N=5/SETUP & SHIFT	N=5/SETUP & SHIFT
3 AIR PRESSURE	AIR PRESSURE OF LOAD MACHINE	0.4~0.55 MPa	PRESSURE GAUGE	GAUGE	OPER.	BACK UP PRESSURE GAUGE	1/START & FINISH	1/START & FINISH
फिर AUTOMAT केस्टर एसेम्बली (movementi	फिर AUTOMATIC PRESS की सहायता से, Jig में सेन्टर एसेम्बली का मूवमेन्ट चैक करे। (movement in axial direction))ig में सेन्टर एसेम्बली (СFD & CLUTCH PLATE) करनी चाहिए।	ATE) फी मूवमेन्ट		OPERATOR & INSP.		100%	N=5/SETUP & SHIFT
5 POKE YOKE FOR	POKE YOKE FOR PRESSURE PLATE MIXUP	MACHINE WILL NOT RUN FOR OTHER MODEL, OK PART MACHINE WILL RUN NG PART MACHINE WILL NOT RUN.	10DEL, Master Sample	ample	OPERATOR		N=1/SHIFT	N=1/SHIFT
FINAL	L TORQUE	SPRING DETI	SPRING DETECTION and MOVEMENT	T CHECK				
Final Torque 9.8 ~ 1.00	Final Torque Checking 9.8 ~ 14N·m (100 ~ 140 kgf cm) (TORQUE WRENCH VALUE 100kgf.cm) Vo. of Spreing I Load (kN) VK Spring Mix Condition Spring Mix 0.95 ~ 1.20 Spring Mix 0.60 ~ 0.65 Spring Mix 0.60 ~ 0.65 VTROL COPY ATROL COPY ATROL COPY ATROL COPY	REVISION RECORD NG NG NG NG NG NG NG NG NG N	SPRING DETECTION & MOVEMENT CHECK 1) THE THE SPRING DETECTION & MOVEMENT CHECK 3-Mar-23	APPRINT APPRINT	S Splay GO Block th 34	Son Marie Marie होना होना होना होना होना होना होना होना	ring load firmation harking of Spring onfirmation prepared by	Issued BY
DOCUMENT CONTROL NO. :- FCC-0S-ASSY-K3CA-10				C.	2	25	Gray Activate V	Windows to particulate Win