

Safety recall notice

Issued 18 November 2025 by Braxby Cycles Ltd. Reference REC-2025-11.

What is affected

Emberly XR front hubs from the 2024 production batch, sold as part number WHL-5104 and inside complete Emberly XR wheelsets supplied between March 2024 and October 2025.

Affected hubs carry a serial number etched on the non-drive side flange in the range EX-24 0001 to EX-24 4200 inclusive. Serials beginning EX-25 are not affected. The current part, WHL-5120, is not affected.

The defect

A batch of front hub shells was machined with an axle seat below the specified diameter. The bearing can develop play under load, and in a small number of cases the drive-side bearing has moved in the shell. The failure presents as a knock felt through the bars under braking, and as lateral play at the rim that does not respond to a bearing preload adjustment.

No injury has been reported. We are recalling on the basis of the failure mode rather than on the basis of harm, which is the right way round.

What to do

Stop riding the wheel. Do not attempt to repack or replace the bearings; a new bearing in an out-of-tolerance seat fails again, usually faster.

Email support@braxbycycles.example with the serial number and the order number if you have it. We will send a prepaid label. A replacement front wheel built on the current hub is sent as soon as the affected wheel is received, and there is no charge for anything, including the labour of moving your rotor and cassette across.

Where the wheel was supplied inside a complete bike built by our workshop, book the bike in instead and we will do the swap on the stand.

If you bought the wheel second hand

The recall follows the hub, not the purchaser. Send the serial number and we will replace it whether or not you were the original buyer and whether or not you have any proof of purchase.

Deadline

There is no deadline. This notice stays open until the last affected hub is returned or the last of them has worn out on a shelf somewhere.