

# Aurora Electronics

## Technical Support & Troubleshooting Guide — Internal Reference

This document contains symptom-cause-fix troubleshooting content for all 5 products in the Aurora line. It is written for PDF-RAG retrieval, but troubleshooting reasoning benefits from a graph structure layered on top (see `technical_support_graph_schema.cypher`) because customers rarely describe symptoms using the exact wording in this document — a graph of Symptom/Cause/Fix nodes with `SIMILAR_TO` relationships lets retrieval traverse from a paraphrased symptom to the correct fix even when text similarity alone would miss it.

Document version 1.6 | Last review: June 2026 | Internal use — Support & Training

### 1. AuroraBuds Pro 2 — Troubleshooting

| Symptom                            | Likely cause                                                           | Fix / resolution steps                                                                                                                     |
|------------------------------------|------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|
| One earbud not charging            | Misaligned charging contacts in case (most common) or debris on pins   | Wipe case charging pins and earbud contacts with a dry cloth; reseal earbud fully; if unresolved after 3 attempts, treat as defective unit |
| Earbuds not pairing with phone     | Stale Bluetooth cache on phone, or earbuds stuck in a previous pairing | Forget device on phone, reset earbuds (hold both touch sensors 10 sec until LED flashes white), re-pair                                    |
| Audio cutting out intermittently   | Bluetooth interference or out-of-range use, or firmware bug pre-v2.1   | Check firmware version in app; update if below v2.1 (fixed a known 5GHz Wi-Fi interference issue); otherwise move closer to source device  |
| ANC not reducing noise as expected | Improper ear-tip seal (most common) or ANC mode not enabled            | Try all 3 ear-tip sizes for best seal; confirm Adaptive ANC is toggled on in app, not Transparency mode                                    |
| Case not charging via wireless pad | Using Gen 1 AuroraCharge pad (incompatible) or case misaligned on coil | Confirm pad is Gen 2 or later; center case on charging coil; Gen 1 pads do not support this case, see Product Info catalog Section 1       |

## 2. AuroraWatch Fit 3 — Troubleshooting

| Symptom                                 | Likely cause                                                             | Fix / resolution steps                                                                                                               |
|-----------------------------------------|--------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| Watch not tracking steps accurately     | Wrist placement too loose, or accelerometer calibration drift            | Tighten band to snug (not tight) fit above wrist bone; recalibrate via app Settings > Sensors > Recalibrate                          |
| Can't reply to messages from watch      | Expected iOS behavior, not a defect (Apple notification API restriction) | Confirm customer's phone OS; if iOS, explain this is a platform limitation, not fixable via update; Android supports this feature    |
| Battery draining faster than 9-day spec | Always-on display enabled, or GPS left active after workout              | Check display mode in app; always-on reduces battery to ~5 days by design; confirm GPS auto-stops after workout end                  |
| Watch won't charge on dock              | Misaligned pogo pins or corrosion from sweat/moisture on contacts        | Clean both watch and dock contact pins with dry cloth; ensure watch is seated flush; if LED shows no response, escalate as defective |
| Band feels loose after ~2 months of use | Standard silicone band wear, not a manufacturing defect                  | Offer band replacement as a paid accessory; not covered under structural warranty per Product Info catalog                           |

### 3. AuroraSound Go — Troubleshooting

| Symptom                             | Likely cause                                                                                             | Fix / resolution steps                                                                                                                                      |
|-------------------------------------|----------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Speaker won't power on              | Battery fully depleted (most common after long storage)                                                  | Charge for minimum 30 minutes before attempting power-on; if still unresponsive, escalate as defective                                                      |
| PartyLink stereo pairing fails      | Attempting to pair with a non-AuroraSound Go unit, or units not in pairing mode simultaneously           | Confirm both units are AuroraSound Go (not cross-compatible with other AuroraSound models); hold both power buttons together for 5 sec to sync pairing mode |
| USB-C port cover feels loose        | Known cosmetic tolerance issue on early batches (serials ASG-2401 to ASG-2403)                           | Confirm serial number range; this is cosmetic only, does not affect IP67 rating; not a defect unless water ingress confirmed                                |
| Water damage claim after submersion | Requires distinguishing confirmed ingress vs. cosmetic wear                                              | Ask for evidence (photos, description of symptoms); if ingress cannot be confirmed via description, escalate to human agent per Returns policy Section 4    |
| Sound distorted at high volume      | Expected behavior above ~85% volume on bass-heavy content (driver limitation), or debris in speaker mesh | Explain this is a known characteristic near max volume; check for physical obstruction in mesh grille                                                       |

## 4. AuroraDesk Rise — Troubleshooting

| Symptom                                  | Likely cause                                                                         | Fix / resolution steps                                                                                                    |
|------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|
| Stand wobbles at maximum height          | Load exceeds recommended distribution at extended hinge angle for laptops over 2.5kg | Advise lowering by one height notch for stability; usage note, not a defect (see Product Info catalog)                    |
| Hinge feels stiff or difficult to adjust | New unit break-in period (first 1-2 weeks), or debris in hinge mechanism             | Normal for new units; if stiffness persists beyond 2 weeks or hinge is audibly grinding, escalate as potential defect     |
| Silicone grip pads peeling               | Adhesive degradation from prolonged heat/sun exposure                                | Not covered under structural warranty (cosmetic wear); offer replacement pad kit as goodwill for units under 6 months old |
| Laptop slides forward on stand           | Grip pads worn smooth, or laptop exceeds 17-inch compatible size                     | Confirm laptop size is within 10-17 inch spec; if pads are worn, replacement kit resolves this                            |

## 5. AuroraType K5 — Troubleshooting

| Symptom                                  | Likely cause                                                                           | Fix / resolution steps                                                                                                                                                           |
|------------------------------------------|----------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Bluetooth keeps disconnecting            | Known reconnection delay bug in firmware before v1.2                                   | Check firmware version via companion app; update to v1.2 or later, which fixed this issue; if already current, try re-pairing                                                    |
| Specific key not registering             | Debris under keycap, or switch failure after hot-swap modification                     | Ask if switches were hot-swapped; if yes, switch warranty is void (electrical/PCB warranty still valid); if factory-original, clean with compressed air or escalate as defective |
| RGB backlight not customizable           | Attempting configuration over Bluetooth (not supported) instead of USB-C/wired mode    | Explain RGB customization and macros require the wired USB-C connection or 2.4GHz dongle with software; Bluetooth mode is playback/typing only                                   |
| Keyboard not detected by 2.4GHz dongle   | Dongle not in the original USB port pairing, or interference from other 2.4GHz devices | Re-pair dongle via Fn+Insert combo; move dongle away from USB hubs/other wireless receivers                                                                                      |
| Typing feels inconsistent after hot-swap | Incompatible or improperly seated aftermarket switches                                 | Confirm only 3-pin or 5-pin compatible switches were used and fully seated; note that hot-swapping voids switch warranty per Section 4 policy                                    |

## 6. Escalation Guidance

Escalate to a human agent when: (a) a symptom persists after all listed fix steps have been attempted and confirmed by the customer, (b) the issue involves a safety concern (overheating, burning smell, swelling battery), (c) the customer disputes a 'known issue, not a defect' classification, or (d) the symptom does not match any documented pattern for the product. The agent should never speculate about a fix not present in this document.