

TXOne Release Note- Firmware



Product Type	Industrial EdgeIPS-Pro	Release Date	2023/2/22
1. Release version ● Firmware name: ipsp.fw.t01_IPSP_T01_1.3.27.acf ● Version: ISP_T01_1.3.27 ● SHA256 Checksum: 7d2d345c45e89ed02c21d55944b7547a36d08d5a655d0ff45ba1a0e198f93de5 ● Signature info: TM_IPSP_220214_06			
2. Applied models ● Platform: x86_64 - IPS-Pro-1048-BP-TM - IPS-Pro-2096-BP-TM - IPS-Pro-216-BP-TM - IPS-Pro-2008-10G-BP-TM			
3. Release info • TOS: ipsp_t01_1.3.27 • Platform (x86_64): ipsp_t01_1.3.26 • Import: ipsp_t01_1.3.26 • TDTs: ics/2.7.15 A. New Features (Since FW 1.3.7) • Added File Exclusions feature in File Filter Profiles. • Added File Exceptions feature is supported in Antivirus Profiles. • [TXN-5348] Added new model id and model name for EdgeIPS Pro 216. B. Improvements (Since FW 1.3.7) • Optimized the reporting behavior of Power-Failure/FAN- Failure SNMP Trap. • Optimized the behavior of Asset detection. • [TXN-5391] [Frontend] Added a new model ID (EdgeIPS Pro 216). • [TXN-5340] [IPSP][Object Profiles - File Filter Profiles, Antivirus Profiles] Updated the description and the flow of the warning message. • [TXN-5351] [IPSP, IPS, IEF, IPSLE][Typo] Fixed the error message display of illegal SNMP profile name. • Modified the LED blink rate of Ethernet Transceiver PHY (Marvell 88E1548) of EdgeIPS Pro 216. • Error Message Supported for Firmware Downgrade. • SNMP Attribute Update • Updated Attribute (Get Info): • <diskusage> supported in private mib • <memory info> supported in private mib • <cpu utilization> supported in private mib • <interface information> supported in standard mib • <serial> supported in standard mib • <sysname/hostname> supported in standard mib • Updated Attribute (TRAP): • <MGMT IP> supported in standard mib • <LINKUP/LINKDOWN> supported in private mib			

- [TXN-5619][CLI] Improved the session management functionality.
- [TXN-5428][Backup File] Apply the new file naming rule.
- [TXN-5787][FE][IPS Pro] Update front panel image for IPS Pro 216.
- [TXN-6094][FE][IPS Pro][Port Security] Fix a layout issue that table content will be hidden if the screen is too small.

C. Bug Fix (Since FW 1.3.7)

- [TXN-1660][IPSP]EdgeIPS Pro cannot detect malicious PE files transferred via SMB3 protocol.
- [TXN-2337][File Filter]Some Windows PE/Linux ELF files cannot be dropped via SMB3 protocol while SMBv3 is in a multi-channel setting.
- [TXN-3619][File Filter]The file name is not available in the file filter log while the file transfers between Windows Server and Windows Client via SMB protocol.
- [TXN-3680][LFPT][trap]EdgeIPS Pro doesn't have any trap event when the LFPT feature disables the other port in a port pair.
- [TXN-3804][SNMP restore config] SNMPv3 query fails after restoring configuration.
- [TXN-4993][AV_SMB]Download a folder containing files from Windows 10 server to Windows 10 client. The files can be bypassed.
- [TXN-4539][Port Security]The description of Security Operation Mode is inconsistent
- [TXN-4567][IPSP][CLI]"exit force" command shouldn't prompt the saved result.
- [TXN-4665][IPSP][CLI]The behavior and display of port-security and bandwidth-mgmt features in the command line interface are inconsistent with those in web-UI.
- [TXN-4782][HW Bypass]The HW bypass is still operational after the user enables and disables the port pair multiple times
- [TXN-5397][IPSP][HA] EdgeIPS Pro 2096 cannot disable HA while EdgeIPS Pro 2096 is in high utilization state.
- [TXN-5388][IPSP][CLI] user switching remote access with command line interface (CLI) from HTTP to HTTPS (or HTTPS to HTTP) will cause a logged-in account to be locked in an aborted connection.
- [TXN-5241][IPSP-216] Port13 to 16 cannot handle the RX/TX packet size with 9K byte
- [TXN-5179][Wording][IPSP] Updated the table description "Last Update Time" to "Last Updated Time" on the Suspicious Object Page.
- [TXN-6240][Hardware Bypass] Improved Hardware Bypass functionality during the reboot of EdgeIPS Pro.
- [TXN-6179][IPS Pro] Improved the online status of EdgeIPS Pro while connecting to ODC.
- [TXN-6078][IPS Pro][LFPT] Traffic may block when the port status is linked up via port settings.
- [TXN-5697][USB] Edge Device(IPS Pro, IPS LE) will save 0-byte config to the USB drive when the disk size of the USB drive is full.
- [TXN-6094][FE][IPS Pro][Port Security] Fixed a web console layout issue that table content will be hidden if the screen is too small.
- [TXN-5939][RDQA page] The file name is incorrect after the debug file is downloaded from the RDQA page.
- [TXN-5932][IPS Pro-216][front panel] Fixed the UI design of the IPSP-216-R front panel.
- [TXN-5908][Firmware] Firmware upgrade failed when config size is 11MB in IPS Pro 216.
- [TXN-5563][Security > Policy Enforcement]Fixed the issue that users can configure and exceed the maximum rule number of policy enforcement by RESTful API.
- [TXN-5549]Protocol filter profile with SMB/HSMS protocol does not work properly, and

no activity log is shown in the web console.

D. Known issues

- Win10 SMB client
 - When using the Win10 SMB client to connect to an SMB server, browsing the folder could generate file filter logs.
 - Windows SMB client will download partial contents of files as prefetch even if users haven't downloaded them.
 - [TXN-2368] - [File Filter] Show other file names via SMB protocol.
 - When Win 10 SMB client tries to copy a file from an SMB server, the client might issue the read request command twice for the same file but with a different file Id / UUID.
 - When Win 10 SMB client tries to delete a file from the SMB server, it will also create a file filter log.
- [IPS] Cannot apply new rules in default pattern for data plane to inspect traffic.
- After switching from the standby partition to the upgraded partition, if the "Management Method" option in the upgraded partition differs from the standby partition (e.g., HTTP, HTTPS), the user cannot be redirected to the login page.
- [TXN-1662] - [slot alarm log] No alarm or log for the slot fails.
- [TXN-1454] - [Firmware_management] After switch standby firmware, if used method is different (e.g. HTTP ->HTTPS) will keep last reboot page.
- [TXN-5974] - [Antivirus Profiles]The pop-up error message is incorrect when users create the same Antivirus Profiles multiple times.
- [TXN-6183] - [IPSP][Firmware]No error handling of firmware upgrade after users delete the firmware file with the newer version of chrome browser.
- [TXN-5949] - [Browser]The error response message is incorrect after user updates the non-existent IPS pattern File with the newer version of the chrome browser.
- SMB
 - [TXN-4868] - [SMB_advance] Use WinXP to read/write other windows OS servers. The event_log will display "anonymous read/write access."
- 24 port fiber LAN module can be detected by old FW w/ unexpected behavior.
 - [TXN-4569] - [IPSP][fiber module] SLOT1 - fiber module may cause data plane fail on FW 1.2 (downgrade or bootup).
- Logs of file filter
 - [TXN-5533][File Filter][Linux][FTP]Show the file name without space in the File Filter log that is in the File Exclude setting if the file name is with leading space or trailing space.
 - [TXN-5542][File Filter][Linux][HTTP]Show the file name without space in the File Filter log that is in the File Exclude setting if the file name is with leading space or trailing space
 - [TXN-5532][File Filter][Linux][SMB]Show the file name without space in the File Filter log that is in the File Exclude setting if the file name is with leading spaces (SMB-based client tool).
 - [TXN-5456][FileFilter] No log of File exclude file in prevention mode when the browser cache a downloaded file.

E. Software limitation (Since FW 1.3.7)

- Fiber LAN Module(s) for EdgeIPS 1048/2096 must be installed with FW version v1.3.15 or later. Fiber LAN Module(s) is not supported in FW version v1.3.14 or the older version.
- Asset visibility detection limitation (Same Issue in FW 1.0/1.1/1.2) - According to

proprietary protocol and specific setting in the specific OT environment. There is a possibility that EdgeIPS-Pro cannot detect since EdgeIPS Pro supports the well-known OT protocol and only make the best effort.

- Policy enforcement cannot block ICMP rules which are based on reversed direction (Same Issue in FW 1.0/1.1/1.2) - In the current design, when the service object is set to 'ICMP' and action is set to 'Deny,' it doesn't work if 'Type/Code' is set as response categories or they are related to the other connection.
- The max frame size of IP defragmentation is 9000 bytes (Same Issue in FW 1.0/1.1/1.2).
- PE-based malware detection (Same Issue in FW 1.1/1.2)
 - HTTP: Some HTTP clients (e.g., Chrome) can cache partial content for a long time. If resuming the download starts after 600 sec, IPSP might not block it.
 - SMB: Out-of-order and SMB3 multi-channel are not supported.
- File filter limitation (Same Issue in FW 1.2)
 - HTTP: If the depth of directories is over 255, the filename in the log will be shown as 'N/A.'
- When using the FTP protocol to transfer files and the TCP FIN flag is not set in the last packet, Antivirus cannot normally work (Same Issue in FW 1.2).
- Policy Enforcement
 - [TXN-4233]If OPCDA clients want to create new data connections w/ the destination port, which is replied by MSRPC/DCOM protocol, but this master connection is closed, policy enforcement cannot work normally.
- SMB
 - [TXN-4776]If the SMB client does not provide the file length when it tries to write the file to the SMB server, Antivirus cannot work normally.
 - [TXN-4783]File Filter & Antivirus Logs may display different uppercase/lowercase filenames for the same file in the Windows OS.

E. Hardware limitation

- When the hardware bypass status of the LAN module card is changed, a few packets will be lost due to PHYs re-negotiation.
- Fiber LAN module(s) ONLY support fiber SFP(s). Copper LAN module(s) doesn't support Fiber Media Converter.

F. Notes

- In the current design, when the service object is set to 'ICMP' and action is set to 'Deny,' it doesn't work if 'Type/Code' is set as response categories or related to the other connection.
- LFPT and LLDP features are set to disable for all EdgeIPS IPS Pro models in the default setting.

Comments :

TXOne Networks
