

PROFINET Device App

PROFINET Device for ctrlX OS

Version 4.6.1

Copyright

© Bosch Rexroth AG 2026-03

All rights reserved, also regarding any disposal, exploitation, reproduction, editing, distribution, as well as in the event of applications for industrial property rights.

Disclaimer

The specified data only serves to describe the product. As our products are constantly being further developed, no statements concerning a certain condition or suitability for a certain application can be derived from our information. The information given does not release the user from the obligation of own judgment and verification. Please note that our products are subject to a natural process of wear and aging.

DC-AE/PAG-SW (MiNi/PiaSt)

Table of contents

1	About this documentation	4
2	Important information	4
2.1	Product information	4
3	Version 4.6.1	4
3.1	Resolved defects and modifications	4
3.1.1	Bug 993292: Firmware update fails sporadically	4
3.1.2	Bug 1170073: PROFINET Device – Inconsistent configuration of the PROFINET device to the controller was sporadically not displayed as an error	4
3.1.3	Bug 1170735: PROFINET Device – Missing DL node 'admin' for a PROFINET device instance in service mode when operating with a COM.2	5
3.1.4	Bug 1185111: PROFINET Device – Removing a 15th parameter in the consumer slot for PROFINET IO resulted in undefined value changes for the remaining parameters	5
3.2	Notes on use and known restrictions	5
3.2.1	Bug 959787: An unused task remains configured after a project update from an older version	5
4	Version 4.4.0	5
4.1	New functions	5
4.1.1	Feature 872866: Web app dialog for configuring cyclic data . .	5
4.1.2	Feature 992046: Product maintenance	6
4.2	Notes on use and known restrictions	6
4.2.1	Bug 959787: An unused task remains configured after a project update from an older version	6
4.2.2	Bug 993292: Firmware update fails sporadically	6
5	Service and support	7
6	Index	9

1 About this documentation

Editions of this documentation

Edition	Release date	Note
01	2025 – 11	PROFINET Device App, Version 4.4.0
02	2026 – 03	PROFINET Device App, Version 4.6.1

2 Important information

2.1 Product information

For the latest information on our products, go to ➔ <https://www.boschrexroth.com>.

For current security advisories, please refer to ➔ <https://psirt.bosch.com/security-advisories/>

3 Version 4.6.1

3.1 Resolved defects and modifications

3.1.1 Bug 993292: Firmware update fails sporadically

Description

Error 0C1F0200 0C780130 may occur sporadically during a firmware update. The update process is then no longer carried out.

Bugfix

Restart update process after power cycle.

3.1.2 Bug 1170073: PROFINET Device – Inconsistent configuration of the PROFINET device to the controller was sporadically not displayed as an error

Description

The PROFINET Device app may not have generated an error message if the number of connections configured for a PROFINET Device in the controller exceeds the configuration stored in the device itself.

This behavior only occurred for PROFINET instances with COM.20.

Troubleshooting

Scenario:

- **Controller configuration:**
For example, 8 connections are configured for a specific PROFINET Device.
- **Device configuration:**
However, only 2 connections are configured in the device itself (e.g. via a profile such as "default_4in_4_out", which is internally reduced to 2 connections).

Error message:

In this case, the error message is displayed during the transition from preOP to OP: Error in PROFINET device / PN device: Config error at slot/subslot "slot 3 subslot 1"

3.1.3 Bug 1170735: PROFINET Device – Missing DL node 'admin' for a PROFINET device instance in service mode when operating with a COM.2

Description

With the ctrlX PROFINET Device App, the DL node "<address to instance-name>/admin/properties" was not accessible in service mode under certain circumstances. This affected access via the Data Layer as well as in the ctrlX web interface on the PROFINET device status and only occurred with instances with COM.2. <address to instance-name>/admin/properties is sporadically not accessible anymore in service mode. This affected access via the Data Layer as well as in the ctrlX web interface on the PROFINET device status and only occurred with instances with COM.2.

3.1.4 Bug 1185111: PROFINET Device – Removing a 15th parameter in the consumer slot for PROFINET IO resulted in undefined value changes for the remaining parameters

Description

If the consumer connection of a PROFINET IO device in the ctrlX Device app was completely occupied with 15 parameters and a parameter was then removed from the configuration, undefined value changes could occur for the remaining parameters when switching back to the PROFINET state "Operational (OP)". In the event of an error, the configuration of the device did not match the controller configuration.

Troubleshooting

If the configuration of the consumer connection is changed (removal of a parameter), undefined value changes no longer occur for the remaining parameters.

3.2 Notes on use and known restrictions

3.2.1 Bug 959787: An unused task remains configured after a project update from an older version

Description

The naming scheme of the task for the PROFINET device has changed in the current version. During automated conversion, an unused task with the old name may remain in the configuration.

Bugfix

Adjust the scheduler configuration or reset the configuration, see here:

➔ <https://docs.automation.boschrexroth.com/doc/1121918067/administration/latest/en/>

4 Version 4.4.0

4.1 New functions

4.1.1 Feature 872866: Web app dialog for configuring cyclic data

Description

An online editor for configuring cyclic data has been added to the web interface.

4.1.2 Feature 992046: Product maintenance

Description

Minor improvements and bugfixes.

4.2 Notes on use and known restrictions

4.2.1 Bug 959787: An unused task remains configured after a project update from an older version

Description

The naming scheme of the task for the PROFINET device has changed in the current version. During automated conversion, an unused task with the old name may remain in the configuration.

Bugfix

Adjust the scheduler configuration or reset the configuration, see here:

➡ <https://docs.automation.boschrexroth.com/doc/1121918067/administration/latest/en/>

4.2.2 Bug 993292: Firmware update fails sporadically

Description

Error 0C1F0200 0C780130 may occur sporadically during a firmware update. The update process is then no longer carried out.

Bugfix

Restart update process after power cycle.

5 Service and support

Our worldwide service network provides an optimized and efficient support. Our experts provide you with advice and assistance. You can contact us **24/7**.

Service Germany

Our technology-oriented Competence Center in Lohr, Germany, is responsible for all your service-related queries for electric drive and controls.

Contact the **Service Hotline** and **Service Helpdesk** under:

Phone: **+49 9352 40 5060**

Fax: **+49 9352 18 4941**

Email: [↗ service.svc@boschrexroth.de](mailto:service.svc@boschrexroth.de)

Internet: [↗ http://www.boschrexroth.com](http://www.boschrexroth.com)

Additional information on service, repair (e.g. delivery addresses) and training can be found on our internet sites.

Service worldwide

Outside Germany, please contact your local service office first. For hotline numbers, refer to the sales office addresses on the internet.

Preparing information

To be able to help you more quickly and efficiently, please have the following information ready:

- Detailed description of malfunction and circumstances
- Type plate specifications of the affected products, in particular type codes and serial numbers
- Your contact data (phone and fax number as well as your e-mail address)

6 Index

H

Helpdesk 7

Hotline 7

I

Important information 4

P

Product information 4

S

Service hotline 7

Support 7

Bosch Rexroth AG
Bgm.-Dr.-Nebel-Str. 2
97816 Lohr a.Main
Germany
Tel. +49 9352 18 0
Fax +49 9352 18 8400
www.boschrexroth.com/electrics

