Beretta 92 / M9 Series Pistols

Beretta • 92FS, M9, 96, Brigadier & Inox (9x19mm NATO & .40 S&W;)

Manufacturer:	Beretta	**Category:**	Pistols
Action Type:	Double-Action / Single-Action (DA/SA)	**Era / Service:**	Cold War to Modern Military (1975–Present)
Calibers:	9x19mm NATO, .40 S&W;	**Covered Models:**	Beretta 92FS, Beretta M9, Beretta 92F, Beretta 96 (.40 S&W;), Beretta 92D (DAO), Beretta Brigadier

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: Dead Trigger Spring Fix • Locking Block Inspection (15k rds) • Factory 92D Hammer Spring (8 lbs) • Slide Detail Strip • Extractor Carbon Cleaning

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
OPERATING SYSTEM	Short recoil falling locking block (Walther P38 heritage) with non-tilting straight-line barrel
LOCKING BLOCK SERVICE LIFE	Inspect every 5,000 rds; replace every 15,000–20,000 rds (Gen 3 radiused block)
RECOIL SPRING SERVICE LIFE	3,000 to 5,000 rounds (factory 13.0 lb standard weight)
TRIGGER PULL DA	11.5 to 12.5 lbs (standard factory mainspring) / 8.0 to 8.5 lbs (with factory 92D spring)
TRIGGER PULL SA	4.5 to 5.0 lbs with distinct clean wall and mechanical reset
LOCKING BLOCK PLUNGER	Spring-loaded plunger in barrel underlug must depress and rebound with zero hesitation
SLIDE RETENTION DEVICE	Enlarged hammer pin head (FS modification) preventing slide fly-back in catastrophic failure

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: Dead Trigger (Trigger Pulls Completely Slack, No Hammer Cock) **Slide cycles normally, round chambers, but trigger stays loose with zero mechanical resistance**	• Trigger bar spring forward leg slipped out of groove beneath trigger bar (very common after removing right grip panel). • Right grip screw over-tightened or missing washer, pinching trigger bar against frame. • Broken trigger bar return spring.	**Immediate Action: Cock hammer manually with thumb. Gunsmith Action: Remove right grip panel. Look at trigger bar spring (mouse-trap shaped wire). Reseat forward spring leg into underside slot of trigger bar. Verify grip screw bushing does not drag against trigger bar linkage.**
Stoppage 2: Fractured Locking Block Ear / Slide Locked Solid **Pistol fires and slide binds frozen partially open; weapon cannot be cleared or racked by hand**	• High round count (15,000+ rds) locking block ear metal fatigue fracture. • Old-style sharp-cornered 92F block without radius relief cuts. • Shooting heavy +P+ or submachine gun ammunition without increased-weight recoil spring.	**Gunsmith Action: Place frame in padded vise. Tap slide rearward with brass drift to relieve lug pressure. Remove slide. Knock out fractured locking block. Inspect frame locking recesses for peening. Install updated Beretta Gen 3 radiused locking block kit with new locking block plunger and pin.**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY
Beretta 92FS / M9 Armorer Detail Disassembly & Assembly	Midwest Gun Works / Armorer Bench	Full armorer teardown of slide decocker levers, firing pin block, extractor, falling locking block, and mainspring housing assembly.