ARMORER'S BENCH TECHNICAL MANUAL

Marlin Model 336 & 1895 Series

Marlin Firearms / Ruger-Marlin • Solid Top-Receiver Side-Eject Lever Action (.30-30 Win & .45-70 Government)

Manufacturer:	Marlin Firearms / Ruger-Marlin	**Category:**	Rifles & Carbines
Action Type:	Lever-Action Side-Ejecting Repeating Rifle	**Era / Service:**	Modern Lever Standard (1948–Present)
Calibers:	.30-30 Winchester, .45-70 Government, .35 Remington, .444 Marlin	**Covered Models:**	Model 336 (.30-30 Win), Model 1895 Guide Gun (.45-70 Govt), Model 1894 (.357 Mag / .44 Mag), Model 336 Dark Series

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: 'Marlin Jam' Carrier Snail Cam Stoning & Radius • Two-Piece Firing Pin Interlock Service • Crossbolt Safety O-Ring Replacement • Flat-Top Receiver Scope Torquing • Finger Lever Plunger Tension Tuning

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
SOLID TOP RECEIVER	One-piece steel receiver with solid top strap and side ejection port, inherently rigid for optic mounting
MARLIN JAM PREVENTION	Bottom edge of lever cam must be radiused and polished to prevent gouging a sharp notch into the carrier cam surface
TWO PIECE FIRING PIN	Rear firing pin segment drops out of alignment until lever is closed and locking bolt pushes it straight into battery
CROSSBOLT SAFETY	Transverse hammer-blocking crossbolt safety with captive rubber O-ring detent

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: The Infamous 'Marlin Jam' (Lever Frozen at Mid-Stroke) Cycling lever forward causes carrier to fail to lift; lever binds with heavy mechanical resistance	• Sharp lower cam on finger lever has battered and gouged a groove into the carrier cam snail. • Carrier drops into the groove and gets trapped, preventing lever from completing stroke.	**Gunsmith Action: MARLIN JAM CURE: Remove lever and carrier. Hand-stone the notch out of the carrier snail surface flat with India stone. Round and mirror-polish the sharp tip of the finger lever cam so it glides across the carrier smoothly rather than gouging.**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY
Fixing the Marlin Jam & Complete Model 336 / 1895 Disassembly	Brownells Gunsmithing Bench	Step-by-step disassembly of the Marlin 336/1895, diagnosing and fixing the carrier jam, two-piece firing pin service, and trigger stoning.