Mosin-Nagant Model 1891/30 & M44

Izhevsk / Tula / Sestroretsk / Chatellerault • Soviet Military Workhorse (7.62x54mmR Russian Rimmed)

Manufacturer:	Izhevsk / Tula / Sestroretsk / Chatellerault	**Category:**	Rifles & Carbines
Action Type:	Bolt-Action Two-Piece Bolthead Rifle	**Era / Service:**	Czarist to WWII Russian Legend (1891–1965+)
Calibers:	7.62x54mmR (Rimmed)	**Covered Models:**	Model 1891 'Three-Line', Model 1891/30 Standard Infantry, M38 Carbine, M44 Side-Folding Bayonet, PU Sniper

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: Interrupter/Ejector Tuning (Rim-Jam Elimination) • Firing Pin Protrusion Teardown Gauge (0.075"–0.095") • Sticky Bolt Fluting / Chamber Scrub • Connecting Bar & Bolt Head Alignment • Trigger Spring Shimming

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
INTERRUPTER DESIGN	Spring-steel leaf on left receiver wall separates top cartridge from cartridge below it, preventing rim-lock jams with rimmed brass
FIRING PIN PROTRUSION	Must be gauged using the Mosin armorer multi-tool notched cutout: 0.075" minimum (passes shallow notch) / 0.095" maximum (must not clear deep notch)
BOLT CONSTRUCTION	Unique 3-piece bolt: separate floating bolt head, connecting bar guide, and main bolt body with cocking knob
SAFETY MECHANISM	Pull cocking knob full rearward and rotate counter-clockwise to hook over receiver wall

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: Sticky Bolt Syndrome (Requires 2x4 Wooden Board to Open Bolt) **Rifle fires, but bolt handle is cemented shut; user cannot lift bolt handle by hand**	• Baked-on dried cosmoline and shellac lining the steel chamber walls. • Steel cartridge case lacquer melting and bonding to rough chamber surfaces.	**Gunsmith Action: Chuck 20-gauge brass shotgun brush on drill rod section. Dip in lacquer thinner and acetone. Run drill in chamber for 2 minutes at 600 RPM. Wipe out with clean patches. Mirror-polish chamber with metal polish paste.**
Stoppage 2: Rim-Lock / Rim-Jam (Bolt Jammed Mid-Push) **Top cartridge rim is trapped behind the rim of the second round in magazine; bolt cannot push round forward**	• Bent or fatigued interrupter leaf spring allowing second round to rise prematurely into the top feedway.	**Gunsmith Action: Disassemble action from stock. Remove interrupter screw. Inspect interrupter blade. Bend leaf spring outward slightly to increase spring tension holding the second cartridge down while top cartridge is chambered.**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY

Mosin-Nagant Complete Disassembly, Interrupter Fix & Chamber Polish	Iraqveteran8888 Bench	Full teardown of the Mosin-Nagant 91/30: using the teardrop armorer tool to set firing pin depth, curing sticky bolt syndrome, and tuning the interrupter.