SIG Sauer P320 / M17 / M18 Modular Pistols

SIG Sauer • US Military M17/M18 Service Pistols & P320 Series (9x19mm, .40 S&W;, .45 ACP)

Manufacturer:	SIG Sauer	**Category:**	Pistols
Action Type:	Modular Striker-Fired Service Pistol	**Era / Service:**	Modern Military & Police (2014–Present)
Calibers:	9x19mm Parabellum, .40 S&W;, .45 ACP, .357 SIG	**Covered Models:**	P320 Full Size, P320 Carry, P320 Compact, M17 Military (US Army), M18 Compact (US Navy/Marines), P320 X-Five

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: FCU Detail Disassembly • Voluntary Upgrade Safety Verification • Extractor Pin Retainer Service • Takedown Safety Lever Check • Manual Safety Rebuild

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
CHASSIS SYSTEM	Stainless steel internal Fire Control Unit (FCU) stamped with serial number; tool-less removal
TRIGGER PULL WEIGHT	5.5 to 6.5 lbs (standard) / 4.0 to 4.5 lbs (Legion/X-Series flat trigger)
SAFETY SYSTEM	Internal striker safety block, disconnector, trigger bar sear disconnect, and optional ambidextrous manual thumb safety (M17/M18)
BARREL LOCKUP	Full-chamber breech hood locks into slide ejection port cutout
SLIDE BACKPLATE	Slide cap with captive extractor spring guide rod and striker lock plate
UPGRADE STATUS	Factory voluntary trigger safety upgrade incorporates lightweight trigger shoe, mechanical disconnector, and skeletonized sear

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: Slide Will Not Lock Back on Takedown Pin Rotate **Takedown lever refuses to rotate 90° downward during disassembly**	• Magazine still seated in pistol (takedown safety interlock engaged). • Slide not pulled to absolute maximum rearward travel before engaging slide stop. • Takedown safety lever inside FCU binding on trigger bar.	**Immediate Action: Drop magazine, verify chamber clear, lock slide full rearward, then rotate lever 90° clockwise. Gunsmith Action: Inspect internal takedown safety lever (curved sheet metal arm) for bends or binding.**
Stoppage 2: Light Primer Strikes After Striker Cleaning **Striker releases with audible click but round does not fire; primer shows light faint strike**	• Liquid oil or solvent left in striker channel creating hydrodynamic resistance against striker cup. • Striker safety block spring inverted or jammed. • Debris in firing pin hole on breech face.	**Gunsmith Action: Detail strip slide. Pull out striker assembly. Swab striker channel with dry Q-tip until bone dry. Inspect striker spring cups and striker return spring.**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY

Sig P320 / M17 Complete Armorer Teardown & Rebuild	Sig Mechanics / Armorer Bench	Full bench teardown of the P320/M17 FCU: Sear spring replacement, safety lever alignment, trigger bar reassembly, and testing drop safety tolerances.