ARMORER'S BENCH TECHNICAL MANUAL

SIG Sauer P365 Series Pistols

SIG Sauer • P365, P365X, P365 XL, P365-XMACRO & SAS (9x19mm & .380 ACP)

Manufacturer:	SIG Sauer	**Category:**	Pistols
Action Type:	Striker-Fired Modular FCU Micro-Compact	**Era / Service:**	Modern Concealed Carry (2018–Present)
Calibers:	9x19mm Parabellum, .380 ACP	**Covered Models:**	P365 Standard, P365X, P365 XL, P365-XMACRO, P365 SAS, P365-.380

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: FCU Chassis Extraction • Extractor Spring & Pin Inspection • Striker Drag Assessment • Disconnector Cleaning • Grip Module Swap

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
OPERATING SYSTEM	Short recoil tilting barrel with standalone serialized Fire Control Unit (FCU) chassis
TRIGGER PULL WEIGHT	5.5 to 6.5 lbs (curved or factory flat trigger)
STRIKER DESIGN	Chiseled chisel-point striker tip (Gen 2 updated to eliminate primer wipe drag)
EXTRACTOR SPRING	Flat-wound high-cycle wire spring with internal indexing plunger
FCU RETENTION PIN	Single rear frame takedown cross-pin; pushes out left-to-right
MAGAZINE CATCH	Reversible steel catch with spring-loaded wedge plunger
SLIDE RAIL CLEARANCE	0.006" to 0.010" on stainless steel chassis rail tabs

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: Failure to Extract (Spent Casing Left in Chamber) **Slide cycles rearward, extractor slips off rim, leaving expanded casing in chamber while feeding new round**	• Carbon fouling or brass shavings packed beneath the extractor claw. • Fatigued or damaged flat extractor spring. • Chipped extractor hook edge. • Lacquered steel casing expansion in tight micro-compact chamber.	**Gunsmith Action: Drive out top extractor retaining pin with 1/16" punch. Remove extractor claw, plunger, and spring. Clean recess with brass brush; inspect hook angle under 10x magnification. Reinstall with fresh factory spring if extractor tension is under 2.5 lbs pull.**
Stoppage 2: Dead Trigger / Disconnector Hang-up After Cycling **Slide goes fully into battery, but trigger stays trapped rearward with no sear click**	• Disconnector tab on right side of FCU fouled with pocket lint or dry abrasive dust. • Trigger bar return spring disconnected from rear trigger bar hole. • Grip module internal wall rubbing on trigger bar linkage.	**Immediate Action: Press forward on trigger shoe to reset. Gunsmith Action: Push out rear FCU pin and lift chassis up and out of grip module. Inspect trigger bar spring (tiny leg hooked into chassis). Spray clean with non-chlorinated solvent, wipe dry, apply single micro-drop of synthetic oil to disconnector pivot.**

Stoppage 3: Slide Catch Fails to Lock Open on Empty Magazine **Last round fires, magazine follower reaches top, but slide slams shut on empty chamber**	• Weak magazine spring in high-capacity 12rd/15rd/17rd magazine. • Slide catch lever spring leg unseated from chassis retaining notch. • Shooter high thumb-forward grip riding downward on external slide catch tab.	**Gunsmith Action: Insert empty factory magazine and cycle slide briskly by hand. If it locks open manually but fails in live fire, check shooter thumb clearance or stretch/replace magazine spring.**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY
Sig Sauer P365 Complete Takedown & FCU Chassis Removal	Sig Mechanics Bench	Detailed armorer guide to driving out the rear frame pin, lifting the serialized FCU out of the polymer grip frame, and inspecting the disconnector and slide catch lever spring.
Sig P365 Striker Assembly Disassembly, Cleaning & Upgrades	Brownells Gunsmithing	How to depress the slide rear cap sleeve, slide off the backplate, remove the striker assembly, clean the striker channel, and check for primer drag wear.